

BEE402 Electrical Machines - I

Date _____

Unit-1:- Principle of Electro Mechanical Energy Conversion:-

Introduction, Review of magnetic system, Energy in magnetic system, Force and torque in magnetic field system, Energy balance equation, Energy conversion via electrical field. Energy in a singly excited system, Determination of the force and Torque from energy and co-energy, Generation of EMF in Machines, Torque in machine with cylindrical air gap.

Unit-2:-

DC Machines:- Armature winding (Concentrated and Distributed).

Winding factor, Armature reaction, commutation, Interpoles and compensating windings, Performance characteristics of DC generators, Applications.

Unit-3:-

DC Machines:- (Contd): Performance characteristics of DC motors,

Starting of DC motors; 3 point and 4 point starters, speed control of D.C motors; Field control, Armature control and voltage control (Ward Leonard method); Efficiency and Testing of DC machines (Hopkinson's and Swinburne's Test). Application, Stepper motor and DC servo motor and their Applications.

Unit-4:-

Single Phase Transformer:- Efficiency and voltage regulation, all

day efficiency, Excitation phenomenon and harmonics in Transformer.

Date _____

Auto Transformer :- Single phase and three phase Transformers.

Volt-ampere relation, copper saving in autotransformer efficiency, Merits & demerits and applications.


Testing of Transformers :- OC and SC tests, Polarity test, Simpson's test.

Unit-5 :-

Three phase Transformer :- Construction, Three phase transformer,

phases groups and their connections, open delta connection, three phase to 2 phase and their applications, Three winding transformers, Parallel operation of single phase transformers and load sharing.

Transformer :-



$$e \propto \frac{d\phi}{dt}$$

$\phi = \text{flux linkage}$

$$\phi = N\phi$$


$$e \propto \frac{d(N\phi)}{dt} \Rightarrow e = \frac{d(N\phi)}{dt}$$

$$e = N \cdot \frac{d\phi}{dt}$$


- (1) if magnet $\rightarrow$ stationary
conductor $\rightarrow$ motion } Dynamically induced emf
- (2) if magnet $\rightarrow$ motion
conductor $\rightarrow$ stationary } statically induced emf

Lenz law :-

"Result opposes its cause"



(Without opposition no energy conversion)





$\mathcal{E} = -N \frac{d\Phi}{dt}$

$$\mathcal{E} = -N \cdot \frac{d\phi}{dt}$$

represents opposition

Electrical circuit :- A closed path followed by current is known as electrical circuit.



emf (electromotive force) → Driving force

$$R \propto \frac{l}{A}$$


$$R = \frac{\rho l}{A}$$

ρ = resistivity

Ohm's law :-

$$V = IR$$

Magnetic circuit :- A closed path followed by flux is known as magnetic circuit.



$$\begin{aligned} \text{MMF } (\mathcal{F}) &= NI \\ \downarrow \\ \text{magnetomotive force} \\ \downarrow \\ \text{(Driving force)} \end{aligned}$$

$$\begin{aligned} V &= IR \\ \downarrow \\ \boxed{NI = \phi_0 \cdot S_{(234)}} \end{aligned}$$

$$R = \frac{\rho l}{A}$$

$$S \propto \frac{l}{A}$$

mean length of core
(औसत लंबाई)

$$S = \frac{\mu_r \cdot l}{A}$$

Reluctivity

Similarities between a electrical and magnetic circuit

Parameter	Electrical circuit	Magnetic ckt
① Driving force	emf (e/v) volt	m.m.f (f) $f = NI$ (Ampere Turns / ATs / Amperes)
② Response	Current (Ampere)	Flux (weber/wb)
③ Oppose	Resistance (R) (-Ω)	Reluctance (S) (ATs/wb)
④ Proportionality		

⑤ Admittance

Conductance (G)

$$G = 1/R \cdot (\Omega)^{-1}$$

Permeance (Δ)

$$\Delta = \frac{1}{S} \frac{\text{Wb}}{\text{ATs}}$$

⑥

Conductivity (σ)

$$\sigma = \frac{1}{\rho} (\Omega \cdot \text{m})^{-1}$$

Permeability (μ)

$$\mu = \frac{1}{\rho L}$$

$$\mu = \mu_0 \mu_r$$

 μ_r = Relative permeability μ_0 = Permeability of free space

$$\mu_0 = 4\pi \times 10^{-7} \text{ H/m}$$

⑦

Density

Density

current density (j)

$$J = \frac{I}{A} (\text{A/m}^2)$$

Flux density (B)

$$B = \frac{\Phi_0}{A} \left(\frac{\text{Wb}}{\text{m}^2} \text{ or Tesla} \right)$$

⑧ Intensity

Electric field intensity (E)

$$E = \frac{V}{l} (\text{V/m})$$

magnetic field intensity (H)

$$H = \frac{NI_0}{l} (\text{ATs/m})$$

Law



Ohm's law

Hopkinson law

$$J = \sigma E$$



$$B = \mu \cdot H$$

Series combination



$$S = S_1 + S_2$$

Parallel combination



$$\frac{1}{R} = \frac{1}{R_1} + \frac{1}{R_2}$$

$$\frac{1}{S} = \frac{1}{S_1} + \frac{1}{S_2}$$

Drop

emf Drop

mmf drop

$$V = IR$$



$$\mathcal{F} = \phi \cdot S$$

KVL

KMMF law



$$\sum V_{drop} + \sum V_{rise} = 0$$

$$\sum \mathcal{F}_{drop} + \sum \mathcal{F}_{rise} = 0$$





Dissimilarities


- (1) In case of electrical circuit air act as insulator but in case of magnetic circuit it does not act as insulator. even in air flux can be created.



- (2) Electrical equivalent of magnetic circuit






$$\Rightarrow NI_0 = \phi \cdot S_{12341}$$




$$NI_0 = \phi_0 (S_{34} + S_{456123})$$

3






23) Find the value of operating flux for the given magnetic circuit if relative permeability of core is 2500 and cross sectional area of core is $25 \times 10^{-4} \text{ m}^2$.




$$\mu_r = 2500$$

$$A = 25 \times 10^{-4} \text{ m}^2$$

$$I_0 = 1 \text{ A}$$





$$NI_0 = \phi_0 \cdot S_{12341}$$

$$\phi = \frac{NI_0}{S_{12341}}$$

$$\phi_0 = \frac{100 \times 1}{2.55 \times 10^6}$$


$$\boxed{\phi_0 = 39.25 \mu\text{wb}}$$

$$S_{12341} = \frac{1}{\mu_0 \mu_r} \frac{l}{A}$$


$$= \frac{1}{4\pi \times 10^{-7} \times 2500} \times \frac{20}{25 \times 10^{-4}}$$

$$\boxed{S_{12341} = 2.55 \times 10^6 \text{ ATs}}$$

Q. If in above question some air gap is present as shown then find the value of coil current to create 39.25 μwb of flux.



$$\boxed{\phi_0 = 39.25 \mu\text{wb}}$$



$$NI_0 = \phi_0 [S_{456123} + S_{34}]$$

$$= \phi_0 \left[\frac{S_{456123} + S_{34}}{N} \right]$$

$$I_0 = 39.25 \times 10^{-6} \left[\frac{S_{456123} + S_{34}}{100} \right]$$

$$I_0 = 1.25 \text{ A}$$

$$S_{456123} = \frac{1}{\mu_0 \mu_r} \cdot \frac{\phi_{456123}}{A}$$

$$= \frac{1}{4\pi \times 10^{-7} \times 2500} \times \frac{19.998}{25 \times 10^{-4}}$$

$$= 2.55 \times 10^6 \frac{\text{ATs}}{\text{wb}}$$

$$S_{34} = \frac{1}{\mu_0 \mu_r} \times \frac{0.002}{A}$$

=

Result - In case of transformer

In a magnetic circuit as the airgap increases then to maintain the same amount of flux the current drawn by the coil increases excessively. In case of transformer there is no airgap present, so its no load current is minimum which is only 2-5% of full load current.

⇒ In case of induction machine this no load current becomes (30-40)% of full load current due to presence of air gap.

⇒ In case of motor and generator air gap is present for mechanical clearance.

Transformer :-

"Transformer is a static device which transfer electrical energy from one electrical circuit to another electrical circuit through the medium of magnetic field without change in frequency"

⇒ Transformer is an electro magnetic energy conversion device.

① electro magnetic energy conversion

Electrical energy $\rightleftharpoons$ magnetic energy.

Eg (x)mer, inductor.

② Electromechanical energy conversion

electrical $\rightleftharpoons$ mechanical.

Eg :- motor, generator.


③ Electrochemical energy conversion

Electrical $\rightleftharpoons$ chemical.

Eg battery.

What happens with power loss when one of the wire of branch of 3- ϕ load get broken.

Star connected load



Power loss in each resistor = $\frac{V_{ph}^2}{R}$


$$\text{In 3 resistor} = \frac{3V_{ph}^2}{R}$$

$$\therefore V_{ph} = \frac{V_L}{\sqrt{3}}$$

$$\therefore \frac{3V_L^2}{3R}$$

$$P_{eq} = \frac{V_L^2}{R}$$


If 1 of the R branch get break



$$\text{Power loss} = 2 \times \left(\frac{V_L}{2} \right)^2 R$$

$$P_{eq}' = \frac{V_L^2}{2R}$$


Δ connected load



$$\text{Power loss in each} = \frac{V_{ph}^2}{R} = \frac{V_L^2}{R}$$

$$P_{eq} = \frac{3V_L^2}{R}$$

If one branch get break



$$P_{eq}' = \frac{2 \times V_L^2}{R}$$

$$\frac{P_{eq}'}{P_{eq}} = \frac{2V_L^2/R}{3V_L^2/R}$$

$$\frac{P_{eq}' \times 100}{P_{eq}} = \frac{2 \times 100}{3}$$

$$\text{reduction in loss} = 33\% \quad P_{eq}' = 66.6\% \text{ of } P_{eq}$$

$$P_{eq}' = 50\% \text{ of } P_{eq} \quad \text{Reduction in loss} = 50\%$$

Ideal Transformer analysis :-

For ideal transformer analysis's following assumptions are taken :-

- ① The resistance of both primary and secondary assumed to be zero.

(i.e. w losses = 0, resistive voltage drop = 0)

- ② Leakage flux between primary and secondary assumed to be zero.

- ③ Reluctance of core assumed to be zero.

$$\therefore \boxed{i_w = 0}$$

$$\phi_0 = \frac{N_1 I_{w1}}{S}$$

$$I_{w1} = \frac{\phi_0 S}{N_1} = 0 \quad \therefore \phi_0 S = 0$$


- ④ The hysteresis and eddy current losses are assumed to be zero.

i.e. $\boxed{i_w = 0}$ i.e. transformer assumed to be linear

$$\boxed{\phi \propto i} \quad \text{Linear}$$


Case - I :-

Ideal transformer under no load condition :-



Where

- e_2 = Secondary induced emf
- e_1 = Primary induced emf
- V_2 = Secondary terminal voltage
- V_1 = Primary terminal voltage



By KVL

According to Lenz law (always used for phasor)

$$V_1 = -e_1$$

it represents opposition

$$V_2 = e_2$$

Let $\Phi_0 = \Phi_m \sin \omega t$

supply frequency

$$e_1 = -N_1 \frac{d\Phi_0}{dt}$$

$$= -N_1 \frac{d\phi_{\max} \sin \omega t}{dt}$$

$$= -N_1 \phi_m \frac{d \sin \omega t}{dt}$$

$$= -N_1 \phi_m \omega \cos \omega t$$

$$= -2\pi f N_1 \phi_m \cos \omega t$$

$$e_1 = 2\pi f N_1 \phi_m \sin(\omega t - \pi/2)$$

$$\because \sin(\pi/2 - \phi) = \cos \phi$$

$$E_{1\max} = 2\pi f N_1 \phi_{\max}$$

max | Peak value of
primary induced emf.

$$[E_{\text{rms}} = \frac{E_{1\max}}{\sqrt{2}}]$$

$$= \frac{2\pi f N_1 \phi_{\max}}{\sqrt{2}}$$

$$E_1 = 4.44 \phi_{\max} \cdot f \cdot N_1$$

EMF equation of Transformer

$$e_2 = \frac{2\pi f N_2 \phi_{\max} \sin(\omega t - \pi/2)}{\sqrt{2}} \Rightarrow \frac{E_{1\max}}{N_1} \cdot N_2$$

$E_{2\max}$

By KVL (used in numerical)

$$\overline{V_1} - \overline{e_1} = 0$$

$$\boxed{\overline{V_1} = \overline{e_1}}$$

Result :-

①

$$\boxed{\frac{E_1}{N_1} = \frac{E_2}{N_2} = E_t = 4.44 \phi_{max} f}$$

Primary induced emf per turn

Secondary induced emf per turn

induced emf / turn


②

If a rated DC is applied to the primary of the transformer then its primary will definitely burn because there is no back emf.

③

Always induced emf e_1 and e_2 lags 90° with respect to corresponding operating flux ϕ_o .


Phasor diagram :-



Let transformer is
Step down
 $[E_2 < E_1]$

$\therefore E_1$ & E_2 lag Φ_0 by 90°

Case → 2 :- Ideal transformer under loading
condition :-



$$\Phi_0 \rightarrow e_2 \rightarrow i_2 \rightarrow N_2 \Phi_2 \rightarrow \Phi_2$$

(Φ_2 oppose Φ_0 so Φ_0 reduces so i_2 will flow to

maintain ϕ_0 flux so ϕ_2' is produced which is equal to ϕ_0 to ϕ_2 . So flux remains constant

$$\phi_0 - \phi_2 + \phi_2' = \phi_0 = \text{constant}$$

As load $i_a \uparrow$, $\phi_2 \uparrow$, $\phi_2' \uparrow$, $(\frac{c_1}{\omega} \uparrow)$

total component of primary current.

$$e_2 = V_2$$

$$\phi_2 = -\phi_2'$$

$$\phi_2 = -\phi_2'$$

$$\frac{N_2 \overline{I_2}}{S} = -\frac{N_1 \overline{I_2'}}{S}$$

$$\overline{I_2'} = -\frac{N_2}{N_1} \overline{I_2}$$

$$\overline{I_1} = \overline{I_2'} = -\frac{N_2}{N_1} \overline{I_2}$$



Result :-

(1)
$$\frac{E_1}{E_2} = \frac{N_1}{N_2} = \frac{I_2}{I_1} = \frac{V_1}{V_2}$$

(2)
$$V_1 I_1 = V_2 I_2$$

↓ ↓
I/P VA O/P VA

∴ In transformer

$VI = \text{constant}$

$$I \propto \frac{1}{V}$$

(3) $N_1 I_1 = N_2 I_2$

∴

Primary
MMF

Secondary
MMF

∴ P. MMF = S. MMF So, from primary to secondary power is transformed through induction.

(4) Conductor size $\propto$ current

(5) Insulation $\propto$ Voltage

(6) HV side $\rightleftharpoons$ LV side

$V \uparrow$, insulation $\uparrow$

$I \downarrow$, conductor thin

$V \downarrow$, insulation $\downarrow$

$I \uparrow$, Thick wire.


Phasor diagram:-

$$i_1 = i_2'$$

Parameters

$$V_1, I_1, \phi_0, E_2, V_2, I_2$$

$\parallel$
 I_2'



$\therefore \phi_0$ is linking to both so it is taken as reference

Let load is R-L is lags V_2 by angle (θ_2)

$\theta_1 =$ angle b/w V_1 and i_1

$\theta_2 =$ angle b/w V_2 and i_2

$$\theta_1 = \theta_2$$

$$\therefore \cos \theta_1 = \cos \theta_2$$



Note:-

If in a transformer current enter in dot on primary side then current must leave from the dot on secondary side or vice versa.

(यदि वही पिन वाले wire से enter से enter करेंगी then वही पिन वाले से निकलेगी)

Analysis of practical transformer:-

① B-H curve:-



Normal material

(wood, plastic)

random


has a number of dipoles

$$\sum \phi_d = 0$$

② Non-magnetic material:- (saturation not occurs)

When non-magnetic materials are placed in external

magnetic field the dipoles remains random and does not change their position ~~etc~~ because non magnetic materials provide high reluctance path. So, net flux due to dipoles becomes zero and we get flux only due to current.



$$\sum \phi_d = 0$$

$$\phi_{net} = \phi_i$$

ϕ_{net} is only due to i ~~so~~ because material has high ~~net~~ reluctance

reluctance $\uparrow$


eg wood, plastic

Aluminium, air
non magnetic


$$\phi_i \propto i \quad \text{--- linear}$$

Permeability of air = 1

iron ≈ 1000



$$E = \frac{1}{2} L I^2$$



From 0 to 1:-

$i_0 \uparrow$, system absorb energy
area of $\Delta O15$

From 1 to 2:-

$i_0 \downarrow$, system release energy
area of $\Delta O15$

So, there is no hysteresis loss.




(loss due to magnetisation & demagnetisation)

③ In case of non magnetic material there is no saturation. So, if current is sinusoidal then flux will also be sinusoidal.

④ There is no harmonics injection in case of non-magnetic material.

Magnetic materials:- (Harmonics comes due to saturation)

When magnetic materials are placed in external magnetic field the dipoles start arranging in the direction of magnetic field. So, we get the magnetic field due to current as well as due to dipoles. So, the B-H curve is non linear. Once all the dipoles are arranged in the direction of magnetic field then material goes into saturation region.



(case)

Diamagnetic material $\mu_r < 1$
 Paramagnetic material $\mu_r > 1$
 Ferromagnetic material $\mu_r > 1$

$\sum N = \{3, 9, 15, \dots\}$
 harmonics
 $N = \text{always odd}$

can ~

$$\mu_{m1} < \mu_p < \mu_{m2}$$

Results:-


- ① In case of magnetic material if current is sinusoidal then flux becomes flat topped or if flux is sinusoidal then current becomes peaky sinusoidal. So, there is harmonic injection due to saturation of the core (with dominant the 3rd order harmonics).

$$i_0(t) = i_{01}(t) + i_{03}(t) + \dots$$


$\downarrow$ fundamental component (f) $\searrow$ 3rd order harmonics (3f)

② Phasor diagram:-

$\therefore$ In phasor all have same frequency.



③ Magnetic material with cyclic magnetic field:-



$\alpha =$ hysteresis angle θ
 the fundamental component of i_o leads ϕ_o by angle α




Results :-

(1)



Practically $\alpha = 15^\circ$

(2)



(3)

$$\psi \propto i^\circ$$

$$\psi = Li^\circ$$

$$N\phi = Li^\circ$$

$$L = \frac{N\phi}{i}$$

$$E = \frac{1}{2} Li^{\circ 2}$$

$$= \frac{1}{2} \times \frac{N \phi}{l} \times i^2$$

$$E = \frac{1}{2} N \phi i \quad \text{--- (3)}$$

$\downarrow$ $\downarrow$ $\downarrow$
 Joule $(T_s \cdot w \cdot A)$

Area of BH Loop = $B \times H$

$$\frac{wb}{m^2} \times \frac{AT_s}{m}$$

$$= \frac{AT_s wb}{m^3} =$$

from equation (3)

$$= \frac{J}{m^3}$$

Area of BH loop represents energy density (J/m^3)

(4) hysteresis loss per cycle = area of BH loop (J/m^3)

(5) hysteresis loss per cycle = area of BH loop $\times$ Volume of core

(6) Total hysteresis Loss = area of BH loop $\times$ volume of core
 $\times$ operating frequency
 $W = J/sec$
 watt

Area of BH loop = ~~50 cm²~~ for a magnetic material = 50 cm²
when two axes of scaled as

$$1 \text{ cm} = 50 \text{ mWb} \text{ --- } y$$

$$1 \text{ cm} = 20 \text{ ATs} \text{ --- } x$$

If operating frequency is 50 Hz then find the total hysteresis loss.

$$\begin{aligned} \text{Area of BH curve} &= 50 \text{ cm}^2 \\ &= 50 (1 \text{ cm} \times 1 \text{ cm}) \\ &\quad \text{--- } x\text{-axis } y\text{-axis} \\ &= 50 \times (50 \times 20) \text{ mWb ATs} \\ &= 50 \times 10^3 \text{ mWb ATs} \end{aligned}$$

$$\text{area} = 50 \text{ J}$$

$$\begin{aligned} \text{Total hysteresis loss} &= 50 \text{ J} \times 50 \text{ Hz} \\ &= 2500 \text{ W} \end{aligned}$$

① Steinmetz formula for hysteresis loss :-

$$W_h \propto B_m^x \cdot f$$

B_m = maximum flux density (T)

f = operating frequency (Hz)

k = Steinmetz constant

By default
 $k = 1.6$ for ~~CR~~ C R G D steel

Cold Rolled Grain oriented

$$B_m = \frac{\phi_{max}}{A}$$

$$\phi_{max} \propto \frac{V}{f}$$

$\therefore E \propto V$ and $E = N \frac{d\phi}{dt}$

$$\left[\frac{1}{f} \propto \frac{1}{\phi} \right]$$

$$V_1 = E_1$$

$$V_1 = 4.44 \phi_{max} N_1 f$$

$$\phi_{max} \propto \frac{V_1}{f}$$

Case - I $\text{If } \frac{V}{f} = \text{constant}$

i.e. $\phi_{max} = \text{const}$ i.e. $B_m = \text{const}$


~~B_m~~ $W_h \propto f$

Case → 2 If $V/f \neq \text{constant}$, $\phi_{\text{max}} \neq \text{const}$, $B_m \neq \text{const}$

$$\therefore W_n \propto \left(\frac{V}{f}\right)^x \cdot f$$

$$\boxed{W_n \propto \frac{V^2}{f^{x-1}}}$$


⑤ Phasor diagram of practical transformer with only hysteresis loss :-



Eddy current loss:-

The main disadvantage of magnetic material is they are ^(good) well conductor of electricity. Since the alternating flux also link with core. So, an emf is induced in the core which is known as eddy induced emf.

⇒ Since the core is always closed. So, a current start flowing through it and due to resistance power losses occurs.



$$\phi_0 - \phi_e + \phi_e'$$

$$= \phi_0 = \text{constant}$$

e_e eddy induced emf

$i_e =$ eddy current

ϕ_e' produce

(So i_e start flowing in primary due to which a flux ϕ_e' produce so cancel flux ϕ_e)

$$\phi_e' = -\phi_e$$

$$\frac{N_1 I_{e'}}{S} = - \frac{(1) I_e}{S}$$

$$I_{e'} = - \frac{I_e}{N_1}$$

$$E_e = 4.44 \phi_{max} f$$

$$L = \frac{N \phi}{i} \quad , \quad \phi = \frac{N i}{S}$$

$$L = \frac{N \times N i}{i S} = \frac{N^2}{S}$$

$$\therefore L = \frac{N^2}{S}$$

$$\begin{aligned} \phi_e' &= -\phi_e \\ \frac{N I_{e'}}{S} &= - \frac{N I_e}{S} \\ I_{e'} &= - \frac{I_e}{N_1} \end{aligned}$$

Since core having only 'one' turn.

$$L = \frac{(1)^2}{55 \times 10^6} \Rightarrow L = 0.5 \times 10^{-6} \text{ H}$$

$$L = 0.1 \mu\text{H}$$


Core can be assumed pure resistive.

$$\therefore W_e = i_e^2 R$$

$$W_e = \frac{E_e^2}{R}$$

R = resistance of core.

$\therefore E_e$ cannot be reduced bcz E_e reduces ϕ and it is only reduced by reducing ϕ & ϕ_m



Area is reduced by using laminated core.

Thickness of strips = $t = 0.35 \text{ mm}$ to 0.50 mm


$W_e \propto t^2$

thickness of core

Result $\rightarrow$


- ① Eddy current loss can be minimised by making the core with thin lamination due to laminations effective cross sectional area of core gets reduced
- ② To increase the resistivity of the core a controlled quantity of silicon will be added. Too much addition of silicon is not preferred because it reduces the magnetic property of the core and also make the core ~~me~~ mechanically brittle.
- ③ The laminations are insulated by varnish or red oxide
- ④ Eddy current and hysteresis loss combined by known as iron loss or ~~the~~ core loss.

Phasor diagram of practical transformer which only core loss




$$\overline{I_0} = \overline{I_w} + \overline{I_u}$$

current divided in parallel connection



$$W_c = I_w^2 R_c = V_{Iw} I_o \cos \theta_1$$

$$L = \frac{N^2}{S}$$

for Linear inductor (Air core) Symbol 

Non linear inductor (Iron core) 

for transformer $\theta_1 = 75^\circ$
b/w V_1 and I_1 or I_o 

Steinmetz formula for eddy current loss :-

$$W_e \propto B_m^2 \cdot f^2$$

Case-I if $\frac{V}{f} = \text{constant}$

$$W_e \propto f^2$$

Case-II if $\frac{V}{f} \neq \text{constant}$

$$W_e \propto \frac{V^2}{f^2} \times f^2$$

$$W_e \propto V^2$$

A 220 V, 60 Hz single phase transformer having hysteresis loss of 340 watt and eddy current loss of 120 W find the total core loss of the transformer is operated at

(1) 110 V, 30 Hz

(2) 200 V, 50 Hz

$$\begin{array}{l} V = 220 \text{ V, } f = 60 \text{ Hz.} \\ W_h = 340 \text{ W, } W_e = 120 \text{ W,} \end{array} \quad \left| \quad \frac{V}{f} = \frac{220}{60} = \frac{11}{3} \right.$$

for case - 1

$$V_1 = 110 \text{ V, } f_1 = 30 \text{ Hz}$$

$$\frac{V_1}{f_1} = \frac{110}{30} = \frac{11}{3} = \frac{V}{f}$$

$\frac{V}{f}$ is constant.

AKTU NOTES HUB

$$W_H \propto f$$

$$\frac{W_H'}{W_H} = \frac{f'}{f}$$

$$W_H' = W_H \frac{f'}{f}$$
$$= 340 \times \frac{30}{60}$$

$$W_H' = 170 \text{ watt}$$

for constant V/f

$$W_e \propto f^2$$

$$\frac{W_e'}{W_e} = \frac{f_1^2}{f^2}$$

$$W_e' = W_e \frac{f_1^2}{f^2}$$

$$= 120 \left(\frac{30}{60} \right)^2$$

$$W_e' = 30 \text{ watt}$$

$$W_{\text{cor}}' = W_e' + W_H'$$

$$= 30 + 170$$

$$W_{\text{cor}}' = 200 \text{ W}$$

$$(2) \quad V'' = 200, \quad b'' = 50 \text{ Hz}$$

$$\frac{V''}{f''} = \frac{200}{50} = 4 \neq \frac{V}{f}$$

$\therefore \frac{V}{f}$ is not constant

$$\therefore W_H \propto B m^x f$$

$$W_H \propto \left(\frac{V}{f}\right)^c f$$

$$W_H \propto \frac{V^x}{f^{x-1}}$$

$$\frac{W_H''}{W_H} = \frac{V''^x}{V^x} \times \frac{f^{x-1}}{f''^{x-1}}$$

$$= \left(\frac{V''}{V}\right)^x \times \left(\frac{f}{f''}\right)^{x-1}$$

$$\frac{W_H''}{340} = \left(\frac{200}{220}\right)^{1.6} \times \left(\frac{50}{60}\right)^{0.6}$$

$$W_H'' = 325.55 \text{ W}$$

if $\frac{V}{y}$ is not const

$$W_e \propto y^2$$

$$\frac{W_e^4}{W_e} = \frac{b_u^2}{y^2}$$


$$W_e^4 = \left(\frac{80}{60}\right)^2 \times W_p$$

$$W_e^4 = 99W$$

$$\therefore W_e^4 = 42555W$$

fringing effect :-

As the flux crosses the air gap flux bulge out at the end of the core this is known as fringing due to fringing effective cross sectional area of the air gap increases so, flux density decreases.



ϕ_e = leakage flux

ϕ_m = useful / mutual flux.

$$\phi_o = \phi_m + \phi_e$$

total operating flux.

ideally $L \cdot F = 1$


practically $L \cdot F > 1, L \cdot F = 1.2$

$$\text{Leakage factor} = \frac{\text{Total operating flux}}{\text{useful flux}}$$

$$L \cdot F = \frac{\phi_o}{\phi_m}$$

Leakage flux :- The flux which link only with primary or only with secondary but not both. Is known as leakage flux

Case - I Leakage flux at No load



$$V_1 = -e_1, \quad e_1 = (e_m + e_{l1})$$


$$V_2 = e_2, \quad e_2 = e_{2m}$$

Primary leakage flux = Φ_l

Secondary leakage flux = 0

Case → II

leakage flux at load



$$(e_m + e_{1l})$$

$$\phi_m - \phi_{2m} + \phi_{2m}$$

$$\therefore \phi_m = \text{const}$$

$$\phi_2 = (\phi_{2m} + \phi_{2l})$$

$$\phi_2' = \phi_{2m}' + \phi_{2l}'$$

$$\boxed{\overline{\phi_{2m}'} = -\overline{\phi_{2m}}}$$

$$e_2 = e_{2m} + e_{2l}$$

$$e_1 = e_m + e_{1l}$$

$$v_1 = -e_1$$

$$v_2 = e_2$$

Primary leakage flux

sec leakage ϕ

$$\phi_2 + \phi_{2l}$$


$$\phi_{2l}$$

~~As the load increases leakage flux also increases and it is minimum at no load.~~

② Transformer as impedance matching device:-

$$\begin{array}{ccc}
 HV & \rightleftharpoons & LV \\
 V \uparrow, I \downarrow & & V \downarrow, I \uparrow \\
 \uparrow Z_{HV} = \frac{V \uparrow}{I \downarrow} & & Z_{LV} = \frac{V \downarrow}{I \uparrow}
 \end{array}$$

Let transformer is ideal.



Here Z_s = Source impedance

Z_L = Load impedance

α Transformation ratio. (K)

$$K = \frac{V_2}{V_1} = \frac{I_1}{I_2} = \frac{N_2}{N_1}$$

$$Z_S = \frac{V_1}{I_1} \quad , \quad Z_L = \frac{V_2}{I_2}$$

$$\boxed{\frac{V_1}{V_2} = \frac{I_2}{I_1} = \frac{N_1}{N_2} = \frac{1}{K}}$$

$$Z_S = \frac{V_2}{K \times K I_2}$$

$$\boxed{Z_S = \frac{Z_L}{K^2} = Z_L'}$$

Z_L' = Load impedance referred to primary.

condition for
maximum power
transfer.

$$\boxed{Z_L = K^2 Z_S = Z_S'}$$

Z_S' = Source impedance referred to secondary.

Example :- Q. $Q1 = Q$

Page = 72

$$N_2 = 40 \quad , \quad N_1 = 9$$

$$Z_L = 2 \Omega$$

$$Z_S = 8 \Omega$$

$$Z_S = Z_L'$$

$$Z_s = \frac{Z_L}{K^2}$$

$$K^2 = \frac{Z_L}{Z_s}$$

$$= \frac{2}{8}$$

$$K^2 = \frac{1}{4}$$


$$K = \frac{1}{2} = \frac{N_2}{N_1}$$

$$N_1 = 2N_2$$

$$N_1 = 2 \times 40$$

$$N_1 = 80 \text{ turns}$$

Exact equivalent circuit of transformer:-



By KVL

$$\boxed{\overline{V}_1 = \overline{E}_1 + \overline{I}_1 R_1 + j \overline{I}_1 X_1} \rightarrow \text{Numericals.}$$

Lenz law

$$\boxed{\overline{V}_1 = -\overline{E}_1 + \overline{I}_1 R_1 + j \overline{I}_1 X_1} \rightarrow \text{Phasor diagram}$$

oppose


KVL

$$\boxed{\overline{E}_2 = \overline{V}_2 + \overline{I}_2 R_2 + j \overline{I}_2 X_2}$$

R_1 = Primary winding resistance

X_1 = Primary leakage reactance.

Equivalent circuit of transformer referred to primary :-



$$R_2' = \frac{R_2}{K^2} = \text{Sec resistance referred to primary.}$$

$$X_2' = \frac{X_2}{K^2}$$

$$I_2' = \frac{N_2}{N_1} I_2 = K I_2$$

$$V_2' = \frac{V_2}{K}$$

$$E_2' = \frac{E_2}{K} = E_1$$


$$\therefore \frac{E_1}{E_2} = \frac{N_1}{N_2} = \frac{1}{K}$$

$$\therefore E_1 = \frac{E_2}{K}$$

$$\frac{V_1}{V_2} = \frac{1}{K}$$

$$V_1 = \frac{V_2}{K}$$

Equivalent circuit of transformer referred to secondary :-



$$R_1' = K^2 R_1$$

$$X_1' = K^2 X_1$$

$$I_2 = \frac{I_2 L}{K}$$

$$V_1' = KV_1$$

$$E_1' = KE_1 = E_2$$

$$I_1' = \frac{I_1}{K}$$

$$I_0' = \frac{I_0}{K}$$

$$I_m' = \frac{I_m}{K}$$

$$X_m' = K^2 X_m$$

$$R_c' = K^2 R_c$$


Phasor diagram of practical transformer at loading condition

Case 1:

At lagging load:

$$\overline{V}_1 = -\overline{E}_1 + \overline{I}_1 R_1 + j \overline{I}_1 X_1$$

$$\overline{E}_2 = \overline{V}_2 + \overline{I}_2 R_2 + j \overline{I}_2 X_2$$



(a) laggy load
 $|E_1| < |V_1|$

$$E_1 = 4.44 \phi_{max} f$$

$$\phi_{max} \propto \frac{E_1}{f}$$

In case of laggy load flux decreases slightly

$$\left. \begin{array}{l} \text{No load} = 1 \text{ W} \\ \text{Load } \phi_m = 0.99 \text{ Wb} \end{array} \right\}$$

At leading load:-

at leading load

$$|E_1| > |V_1|$$

$$E_1 = 4.44 \phi_m f$$

$$\uparrow \phi_{max} \propto \frac{E_1}{f}$$

Similar in T/m lines feranti's effect

In case of leading load flux increases slightly

$$\text{at No load} = 1 \text{ Wb}$$

$$\text{load} = 1.01 \text{ Wb}$$

Magnetostriction effect :-


Only occurs in ferromagnetic materials

$$\frac{E_L}{E} = K$$

$$E_L = \frac{E_L}{E} K$$


① When ferromagnetic materials under goes in an alternating magnetic field the dipoles start vibrating around its mean position. So, effective length of the core increases or decreases ($10^{-6} m$) this is known as magnetostriction effect or joule effect.

② Due to vibrations of the dipoles there is a noise humming




Polarity test :-

(use in 11th operation)



Short circuit

Additive polarity




Subtractive polarity

② Open circuit test (No load test) (OC test)

→ Open circuit test is performed to find out shunt branch parameters, core losses, turn ratio.

⇒ It is better to conduct OC test on L-V side with open circuited H-V with low power factor watt meter.



$$P_i = P_{out} + \text{Loss}$$

$$\because (I_a = 0 \therefore P_{out} = 0)$$

$$W_{NL} = 0 + \text{Loss}$$


$$\begin{aligned} & \text{Copper loss} \rightarrow I_1^2 R_1 = I_0^2 R_1 = I_0^2 (2-5)\% \text{ of full load current so it can be neglected} \\ & \text{Core loss} \rightarrow (W_h + W_c) \propto (B_m^2 f + B_m^2 f^2) \\ & \quad \text{at } k=2 \\ & \quad \propto (B_m^2 f + B_m^2 f^2) \text{ at } B_m = \frac{V}{f} \end{aligned}$$

$\propto \left(\frac{V^2}{f} + V^2 \right) \Rightarrow$ So rated core loss occurs,

Rated voltage $\left(\frac{V^2}{f} \right)$
 Rated frequency

$W_{NL} = \text{Core loss}$

$\Downarrow$



equal equivalent ckt of T/P under open circuit condition

H.V $\longrightarrow$ L.V (o.c)

$V \uparrow, I \downarrow$

X (So, test is not convenient)

High rating voltmeter required

Ammeter cannot read (2-5%) of very small current


L.V $\longrightarrow$ H.V (o.c)

$V \downarrow, I \uparrow$

(Test is done)

using low. volt meter available

Ammeter reads current



core loss = $V_{NL} I_{NL} \cos \theta_{NL}$

$$W_{NL} = V_N I_{NL} \cos \phi_{NL}$$

Known (K/N)

(K/N)

(K/N)

calculated by this formula

$$I_W = I_{NL} \cos \phi_{NL}$$

calculator

K/N

K/N (just about)

$$I_w = I_{NL} \sin \theta_{NL}$$

Calculated K/N K/W

$$R_e = \frac{V_{NL}}{I_w}$$

K/N K/W

$$X_m = \frac{V_{NL}}{I_w}$$

K/W K/W

$$\frac{N_1}{N_2} = \frac{V_{NL}}{V_2}$$


K/N K/N

Short circuit test :-

⇒ Short circuit test is conducted to find out total copper loss, series branch parameters, turn ratio.

⇒ It is better to conduct short circuit test on H-V side with short circuited LV with high power factor watt meter

$$\overline{I_{sc}} = \overline{I_0} + \overline{I_d} \text{ - rated}$$



V_{sc} = supply voltage required to produce rated current ~~require~~ on both primary and secondary. It is only 6% to 12% of rated voltage at rated frequency.

$$P_i = P_0 + \text{Loss}$$

$$W_{sc} = 0 + \text{Loss}$$

$$\therefore (V_2 = 0)$$

$$\text{Core Loss} \propto (V^2)$$

Since V is less so, core loss are very low

$$\text{Cu Loss} [I_{sc}^2 R_1 + I_2^2 R_2]$$

So, Compare to rated cu loss core loss can be neglected

$$\textcircled{3} \quad \begin{array}{ccc} \text{HV} & \longrightarrow & \text{LV (SC)} \\ V \uparrow, I \downarrow & & V \downarrow, I \uparrow \end{array}$$

✓ so test is on supply is given to H-V side

$$\begin{array}{ccc} \text{L.V} & \longrightarrow & \text{H.CSC)} \\ V \downarrow, I \uparrow & & \end{array}$$



X

$W_{sc} = Cu \text{ loss of transformer}$
Here $\overline{I_{sc}} = \overline{I_0} + \overline{I_a'}$

$I_0 = 2\% \text{ to } 5\% \text{ of } I_1$

$I_0 \ll I_a'$

$$\therefore \boxed{\overline{I_{sc}} \approx \overline{I_a'}}$$



$R_{e1} = R_1 + R_2' =$ equivalent resistance of transformer referred to primary.

$X_{e1} = X_1 + X_2' =$ equivalent reactance of transformer referred to primary

Cu loss of transformer = $I_{sc}^2 R_{e1}$

$$\boxed{W_{sc} = I_{sc}^2 R_e}$$

K/n K/n cal

$$R_{e1} = R_1 + R_2'$$

$$\text{let } \boxed{R_1 \approx R_2' = \frac{R_{e1}}{2}}$$

$$\overline{Z}_{sc} = R_{e1} + j X_{e1}$$

$$\overline{Z}_{sc} = \sqrt{R_{e1}^2 + X_{e1}^2} \angle \tan^{-1} \frac{X_{e1}}{R_{e1}}$$

$$\overline{Z}_{sc} = |Z_c| \angle \theta \text{ (impedance angle) of T/R}$$

$$\boxed{|Z_{sc}| = \sqrt{R_{e1}^2 + X_{e1}^2}}$$

K/n K/n cal

$$\boxed{|Z_{sc}| = \frac{V_{sc}}{I_{sc}}}$$

$$X_{el} = X_1 + X_2$$

let

$$|X_1| \approx |X_2| = \frac{X_{el}}{2}$$

let, R_e is V_{sc}

$$\overline{V_{sc}} = V_{sc} \angle 0^\circ$$

$$\overline{I_{sc}} = I_{sc} \angle -\theta_{sc}$$

I_{sc} lags V_{sc} by angle θ_{sc}

$$\overline{Z_{sc}} = \frac{\overline{V_{sc}}}{\overline{I_{sc}}}$$

$$\angle \beta = \frac{V_{sc} \angle 0^\circ}{I_{sc} \angle -\theta_{sc}}$$

$$\angle \beta = \angle \theta_{sc}$$

$$\theta_{sc} = \beta = \tan^{-1} \left(\frac{X_{el}}{R_{el}} \right) = \text{p.f. angle of T/F under s.c condition}$$

$$Y_{sc} = \frac{V_{sc}}{I_{sc}}$$

$$Z_{sc} (\text{Base}) = \frac{V_{\text{Rated}}}{I_{\text{Rated}}} = \frac{V_{\text{Rated}}}{I_{sc}}$$

Let $V_{sc} = x\% \text{ of } V_{rated}$

$$V_{sc} = \frac{x V_{rated}}{100}$$

$$(Z_{sc})_{pu} = \frac{Z_{sc}}{(Z_{sc})_{base}} = \frac{\frac{V_{sc}}{I_{sc}}}{\frac{V_{rated}}{I_{sc}}}$$

$$(Z_{sc})_{pu} = \frac{V_{sc}}{V_{rated}}$$

$$(Z_{sc})_{pu} = \frac{x}{100}$$

$$\% (Z_{sc}) = x\%$$

Q-14 Page $\rightarrow 72$

$$S = 10 \text{ KVA}$$

$$V_1 = 400 \text{ V}$$

$$V_2 = 200 \text{ V}$$

$$Z_{pu} = 0.10$$

$$V_{sc} = 10\% \text{ of } 400 \text{ V}$$

$$= 40$$

~~$$V_1 I_1 =$$~~

$$V_{sc} I_{sc} = 10 \text{ KVA}$$

$$I_{sc} = \frac{10000}{40} = 250$$

2

Result :-

① $\theta_r = \tan^{-1} \left(\frac{X_{e1}}{R_{e1}} \right)$

② $\cos \theta_r = \frac{R_{e1}}{\sqrt{R_{e1}^2 + X_{e1}^2}}$

$f \uparrow, X_{e1} \uparrow, \cos \theta_r \downarrow$

③ $\phi \propto V/f$

④ $\phi = \frac{N_1 I_m}{S}$

$\phi \propto I_m$

$I_m \propto V/f$

Page 78
 $\alpha = 45^\circ$

$V_{sc} = 30V, f = 50Hz, I_{sc} = 20A, \cos \theta_{sc} = 0.2$

$V_{sc}' = 30V, f' = 25Hz, I_{sc}' = ?, \cos \theta_{sc} = ?$

Objective :-

$\uparrow I_{sc} = \frac{V_{sc}}{\sqrt{R_{e1}^2 + X_{e1}^2} \downarrow}, I_{sc} \uparrow$

$\uparrow \cos \theta_{sc} = \frac{R_{e1}}{\sqrt{R_{e1}^2 + X_{e1}^2} \downarrow} > 0.2$

Solution :-

$$\overline{Z}_{sc} = \frac{V_{sc} \angle 0^\circ}{I_{sc} \angle -\theta_{sc}}$$

$$\overline{Z}_{sc} = \frac{30 \angle 0^\circ}{20 \angle -\cos^{-1}(0.2)} = 1.5 \angle 78.46^\circ = 1.5 [\cos 78.46 + j \sin 78.46]$$
$$= R_{e1} + jX_{e1}$$

$$\therefore R_{e1} = 0.3 \Omega$$

$$X_{e1} = 1.46 \Omega$$

$$\overline{Z}_{sc}' = \frac{V_{sc}' \angle 0^\circ}{I_{sc}' \angle -\theta_{sc}'}$$

$$\overline{Z}_{sc}' = \frac{30 \angle 0^\circ}{I_{sc}' \angle -\theta_{sc}'}$$

$$I_{sc}' \angle -\theta_{sc}' = \frac{30 \angle 0^\circ}{\overline{Z}_{sc}'}$$

$$\overline{Z}_{sc}' = R_{e1} + jX_{e1}'$$

$$\overline{Z}_{sc}' = 0.3 + jX_{e1}'$$

$$\therefore X \propto \frac{1}{b}$$

$$\left[\frac{X_{e1}'}{X_{e1}} = \frac{b}{b'} \right] \Rightarrow \frac{X_{e1}'}{1.46} = \frac{28}{50} \Rightarrow \boxed{X_{e1}' = 0.73}$$

$$\therefore Z_{sc}' = 0.3 + j0.73 \Omega$$

$$Z_{sc}' = 0.789 \angle 67.66^\circ$$

$$I_{sc}' \angle -\theta_{sc}' = \frac{V_{sc} \angle 0^\circ}{Z_{sc}'}$$

$$I_{sc}' \angle -\theta_{sc}' = \frac{30 \angle 0^\circ}{0.789 \angle 67.66^\circ}$$

$$\therefore I_{sc}' \angle -\theta_{sc}' = 38.02 \angle -67.66^\circ$$

$$\therefore I_x' = 38.02$$

$$\theta_{sc} = 67.66^\circ$$

④ Sumpner's back to back test or regenerative test
Heat run test

→ This test is performed for finding temperature rise for large rating transformer, core losses, copper losses and efficiency.


⇒ In this test two identical transformers primaries are connected in parallel and the secondaries are

connected in such a way their induced emf cancel out each other.

⇒ When primaries of both the transformer is connected with the supply the current drawn by the primary is only no-load current because secondary induced emf cancel out each other. This condition of transformer is equivalent to O.C test and the watt meter reading gives core losses of both the transformers.

⇒ Now, the autotransformer is connected to the supply which produces rated current in transformer windings and this is equivalent to short circuit test. and watt meter reading gives rated copper losses.

⇒ So, both condition of O.C and S.C test are produced simultaneously. And rise in temp can be calculated.



$W_1 =$ Rated core losses of both transformers

Rated core loss of 1 T/F = $\frac{W_1}{2}$

$W_2 =$ Rated copper losses of both transformers

Rated cu loss of 1 T/F = $\frac{W_2}{2}$

Rating of transformer :-

Q 10KVA, 220KV / 100V , 3- ϕ , Y- Δ , 50Hz, T/F ---?

Rated H-voltage (line voltage) Rated L-voltage (line voltage) (V_L) operating frequency.

Total (3- ϕ) Rated

Full load power

$$S = 3V_1 I_1 = 3V_2 I_2$$

Rated primary voltage (phase value) Rated primary current (phase value)

$$S = \sqrt{3} V_L I_{L1} = \sqrt{3} V_{L2} I_{L2}$$

Rated Primary voltage (line value) Rated Primary current (line value)

$$S = 3 V_1 I_1$$

$$10\text{KVA} = \frac{3 \times 220000 \times I_1}{\sqrt{3}}$$

$$I_1 = 0.026\text{A}$$

Voltage regulation:-

$$V.R = \text{p.u. voltage drop} \mid \text{Rise}$$

$$V.R = \frac{|V_{NL}| - |V_L|}{|V_{rated}|}$$

- Transformer, $|V_{rated}| = |V_{NL}|$
- Alternator, transmission $|V_{rated}| = |V_{FL}|$
- Motor $|V_{rated}| = |V_{FL}|$

∴ for transformer

$$V_R = \frac{|V_{NL}| - |V_L|}{|V_{NL}|}$$

$$V_R = \frac{|E_2| - |V_2|_{nh}}{|E_2|}$$


$|E_2|$ = Secondary terminal voltage at no load

$|V_2|_{nh}$ = Secondary terminal voltage at n^{th} loading of full loading.

$$\text{Loading} = \frac{\text{Present loading}}{\text{Full / Rated / Loading}} \Rightarrow \eta = \frac{I_2 n}{I_2}$$


$$\therefore I_2 n = \eta I_2$$

where, I_{2m} = Secondary current at m^{th} loading of T/F (full load)



$$V_1 = E_1 = E_2$$

|||



$$\boxed{E_2 = I_2 R_{e2} + j I_2 X_{e2} + V_2}$$

$$V.R = \frac{|E_2| - |V_2|}{|I_2|}$$

Case-1 If load is laggy load :-

I_2 lags V_2 by angle ϕ_2

$R_{e2} = R_1 + R_2$ = equivalent resistance of T/F secondary


$X_{e2} = X_1 + X_2$ = equivalent reactance of T/F secondary

Case III of load is leading I_2 leads V_2 by angle ' θ_2 '

$$\Theta_2 \longrightarrow -\Theta_2$$

$$V.R = \frac{I_2 R_{e2} \cos \theta_2}{E_2} - \frac{I_2 X_{e2} \sin \theta_2}{E_2}$$

Derivation of formula :-



$$OE = OD$$

$$|E_v| = OC + CD$$

OC >>>> CD

$$|E_{\text{ext}}| = 0 \text{ C}$$

$$|E_2| = OA + AB + BC$$

$$|E_1| = |V_1| + I_a R_{e2} \cos \theta_2 + I_a X_{e2} \sin \theta_2$$

$$|E_1| - |V_2| = I_a R_{e2} \cos \theta_2 + I_a X_{e2} \sin \theta_2$$

$$\frac{|E_1| - |V_2|}{|E_1|} = \frac{I_a R_{e2} \cos \theta_2}{E_1} + \frac{I_a X_{e2} \sin \theta_2}{E_1}$$

for far lagging

$$(V.R)_{\text{nth}} = n \left[\frac{I_a R_{e2} \cos \theta_2}{E_2} + \frac{I_a X_{e2} \sin \theta_2}{E_2} \right]$$

Lagging
Loading

$$(2) \frac{I_a R_{e2}}{E_2} = \frac{\text{Resistive Drop}}{\text{Rated Voltage}} = \text{P.u resistive Drop} = \frac{R_{e2}}{E_2/I_a} = \frac{\text{Resistance}}{Z_{\text{Base}}}$$

$$= \text{P.u resistance of 'x' mer } (R_e)_{\text{pu}}$$

$$(3) \frac{I_a X_{e2}}{E_2} = \text{P.u resist reactive drop} = \text{P.u reactance of 'x' mer } (X_e)_{\text{pu}}$$

$$(V.R)_{\text{nth}} = n \left[(R_e)_{\text{pu}} \cos \theta_2 \pm (X_e)_{\text{pu}} \sin \theta_2 \right]$$

$$\Rightarrow V.R \downarrow, \text{ Better V.R}$$

$$\Rightarrow V.R \uparrow, \text{ Poor V.R}$$

③ Condⁿ ~~max~~ maximum V.R :-

max V.R occurs at laggy p.f load.

$$\frac{d(V_R)_{nth}}{d\theta_2} = 0$$

$$\tan\theta_2 = \frac{(X_e)_{pu}}{(R_e)_{pu}}$$

④ Condⁿ for zero V.R :- It occurs at leading p.f load or near to θ_P w.r.t ϕ of load.


$$(V_R)_{nth} = n [(R_e)_{pu} \cos\theta_2 - (X_e)_{pu} \sin\theta_2]$$

$$(V_R)_{nth} = 0$$

$$\tan\theta_2 = \frac{(R_e)_{pu}}{(X_e)_{pu}}$$

⑤ ~~If load is of voltage regulation is positive then load is lagging load but if load is lagging then voltage regulation may be positive or negative. voltage regulation is positive then load may be lagging or leading.~~

- ⑥ If voltage regulation is negative then load is leading load. But, if load is leading then voltage regulation may be positive, negative or zero.



- ⑤ If load is lagging then voltage regulation is positive but if voltage regulation is positive then load may be lagging or leading.

16

10KVA, 400/200V

$$\% (R_e) = 3\% \Rightarrow (R_e)_{pu} = 0.03$$

$$\% (X_e) = 6\% \Rightarrow (X_e)_{pu} = 0.06$$

$$I_{2n} = 50A$$

$$(V_2)_{nH} = ?$$

$$V.R = n \left[R_{pu} \cos \theta_2 \pm X_{pu} \sin \theta_2 \right]$$

$$I_1 n = I_{2n}$$

$$n = \frac{I_{2n}}{I_2}$$

$$= \frac{50}{50}$$

$$\boxed{n = 1}$$

$$I_1 = \frac{10000}{2000}$$

$$I_1 = 50$$

$$\text{load} = \text{resistive} = \theta_2 = 0^\circ$$

$$\therefore V.R = \frac{|E_1| - |V_2|_{nH}}{|E_1|} = n \left[0.03 \times 1 \right]$$

$$\frac{200 - |V_2|_{nH}}{200} = 0.03$$

$$\boxed{|V_2|_{nH} = 194V}$$

$$\text{no load voltage } \boxed{E_2 = 200}$$

Efficiency and losses :-

Losses :-

Full load

Core losses : (W_c)

$$W_c = W_e + W_h$$

$$W_c \propto \left[\frac{V^2}{f^2} \cdot \cancel{b} + \frac{V^2}{f} \cdot \cancel{b} \right]$$

$$\boxed{W_c \propto \left[V^2 + \frac{V^2}{f} \right]}$$

From No load to full load $\cdot$ V and f remains constant.
So, core loss also remains constant. So, these are known as constant loss.

② Full load / Rated cu Loss (W_{cu})

$$W_{cu} = (I_1^2 R_1 + I_2^2 R_2)$$

$$= I_1^2 \left(R_1 + \frac{I_2^2}{I_1^2} R_2 \right)$$

$$= I_1^2 \left(R_1 + \frac{R_2}{K^2} \right)$$

$$= I_1^2 (R_1 + R_2')$$

$$\boxed{W_{cu} = I_1^2 (R_1 + R_2')}$$

$$= \boxed{W_{cu} = I_1^2 R_{e1}}$$

$$(W_{cu})_{nm} = (n I_2)^2$$

$$W_{cu} = I_1^2 \left[\frac{I_1^2}{I_2^2} R_1 + R_2 \right]$$

$$= I_1^2 [K^2 R_1 + R_2]$$

$$= I_1^2 [R_1' + R_2]$$

$$W_{cu} = I_1^2 R_2$$

Copper loss of transformer at full load remains constant

at n^{th} load of full load

$$(W_{cu})_{nm} = I_{2n}^2 R_2$$

$$I_{2n} = n I_2$$

$$= n^2 I_2^2 R_2$$

$$(W_{cu})_{nm} = n^2 W_{cu}$$

$$(W_{cu})_{nm} \propto n^2$$

variable loss

represent parabolic relation

Condition for maximum efficiency :-

Case → 1 if $n = \text{constant}$
 $\theta_2 = \text{variable}$

$$\frac{d\eta_{nm}}{d\theta_2} = 0$$

$$\therefore \boxed{\cos \theta_2 = 1}$$

unity power factor

Power o/p at maximum η
condition n

$$= n \cdot m \times \text{Rated Power}$$

$$= \sqrt{\frac{W_c}{W_{cu}}} \times \text{Rated power}$$

Efficiency (η)

$$\therefore \text{eff} = \frac{\text{o/p}}{\text{o/p} + \text{loss}}$$

$$\eta_{nm} = \frac{V_2 I_{2n} \cos \theta_2}{V_2 I_{2n} \cos \theta_2 + (W_{cu})_{nm} + W_c}$$

$$\eta_{nm} = \frac{n V_2 I_2 \cos \theta_2}{n V_2 I_2 \cos \theta_2 + n^2 W_{cu} + W_c}$$

Case - 2 if $n = \text{variable}$
 $\theta_2 = \text{const}$

outputting,

$$\frac{d\eta_{nm}}{dn} = 0$$

$$\boxed{n^2 W_{cu} = W_c}$$


variable loss = constant loss

$$\boxed{\eta_{ma} = \sqrt{\frac{W_c}{W_{cu}}}}$$

It is the load @ at which
maximum η occurs.

Result :-

- ① Loading below n_m efficiency is low because core losses are more in percentage with respect to output
- ② Efficiency is low loading above n_m because percentage copper losses are more with respect to output.



- ③ In case of distribution transformer avg loading in a day is approximately 40% of full loading. So distribution transformer are design maximum efficiency at 40% of full loading and power transformer are designed maximum efficiency at nearly

equal to full loading.

Distribution Transformer

$$\eta_m = 70\%$$

$$\sqrt{\frac{W_c}{W_{cu}}} = 0.7$$

$$W_{cu} = 2 W_c$$

$$W_{cu} > W_c$$

Power Transfer

$$\eta_m = 100\%$$

$$\sqrt{\frac{W_c}{W_{cu}}} = 1$$

$$W_{cu} = W_c$$

Note :-

- Voltage rating $\propto f$
- KVA rating $\propto f$
- Size of transformer $\propto \frac{\text{Power}^{0.75}}{f}$

① A single phase 50Hz transformer having max η of 90% @ full load unity P.f then find the efficiency at half load unity power factor.

$$\eta = \frac{n V_2 I_2 \cos \theta_2}{\dots}$$

$$\eta_{\max} = \frac{\eta_m \cdot V_a I_a \cos \theta_2}{\eta_m V_a I_a \cos \theta + \cancel{\eta_m} \eta_m^2 W_c + W_c}$$

given

$$\eta_{\max} = \frac{9}{10}$$

$$\eta_m = 1$$

$$\cos \theta_2 = \text{UPF} = 1$$

$$\sqrt{\frac{W_c}{W_{cu}}} = 1$$

$$\boxed{W_c = W_{cu}}$$

$$\frac{9}{10} = \frac{(1) V_a I_a (1)}{(1) V_a I_a (1) + (1)^2 W_c + W_c}$$

$$\frac{9}{10} = \frac{V_a I_a}{V_a I_a + 2W_c}$$

$$\boxed{18 W_c = 1 V_a I_a}$$

$$\eta_{1/2} = \frac{\frac{1}{2} V_a I_a \cos \theta_2}{\frac{1}{2} V_a I_a \cos \theta_2 + \left(\frac{1}{2}\right)^2 W_c + W_c}$$

$$\eta_{1/2} = \frac{\frac{1}{2} V_a I_a}{\frac{1}{2} V_a I_a + \frac{W_c}{4} + W_c}$$


$$\eta_{1/2} = 0.878$$

$$\eta_{1/2} \% = 87.8 \%$$

All day efficiency :-

On a distribution transformer loading is variable so for distribution transformer we define all day efficiency which is calculated for 24 hours

$$\text{All day efficiency} = \frac{\text{Energy o/p (Kwh)}}{\text{Energy o/p (Kwh)} + \text{Loss (Kwh)}}$$




Auto transformer :-

① Auto transformer is a transformer in which a part of primary will act as secondary and power is transfer threw both induction and conduction.

② In Autotransformer both primary and secondary

are electrically connected but in two winding transformer both are electrically isolated.



$$\therefore \boxed{\frac{N_1}{N_2} = \frac{V_1}{V_2} = \frac{I_2}{I_1} = \frac{1}{K}} \quad \text{Here } N_2 < N_1$$

$K < 1$

① MMF of AB $\div (N_1 - N_2) I_1$

$$\begin{aligned} &= N_1 I_1 - N_2 I_1 \\ &= N_2 I_2 - N_2 I_1 \\ &= N_2 (I_2 - I_1) \\ &= \text{MMF of BC} \end{aligned}$$

So, power transferred from A-B to BC is through induction only

② Power transferred inductively

$$= (V_1 - V_2) I_1$$

$$= V_1 I_1 - V_2 I_1$$

$$= V_1 I_1 - K V_1 I_1$$

$$= (1 - K) V_1 I_1$$

$$= (1 - K) \text{ input VA}$$

Power transferred conductively = $V_1 I_1 - (1 - K) V_1 I_1$,

$$= K V_1 I_1$$

Advantages :-

Volume of Cu Required

$$V_{Cu} \propto A \cdot l$$

$$V_{Cu} \propto I N$$

$$V_{Cu} \propto \text{mmf}$$

$$(V_{Cu})_{2 \text{ wdg}} \propto (N_1 I_1 + N_2 I_2)$$

$$(V_{Cu})_{2 \text{ wdg}} \propto 2 N_1 I_1 \quad \text{--- (1)}$$

$$(V_{Cu})_{\text{Auto}} \propto (\text{MMF of AB} + \text{mmf of BC})$$

$$(V_{Cu})_{\text{Auto}} \propto 2(N_1 - N_2) I_1 \quad \text{--- (2)}$$

By subtracting (1) from (2)

$$\frac{(V_{Cu})_{\text{Auto}}}{(V_{Cu})_{2 \text{ wdg}}} = \frac{2(N_1 - N_2) I_1}{2 N_1 I_1} = \frac{N_1 - N_2}{N_1}$$

$$(V_{cu})_{auto} = (1-K) (V_{cu})_{2 \text{ winding}}$$

$$\text{if } K = 0.2 \quad (V_{cu})_{auto} = 80\%$$

Cu losses :-

$$W_{cu} \propto I^2 R$$

$$W_{cu} \propto I^2 \frac{l}{A} \propto I^2 \cdot \frac{N}{\cancel{A}}$$

$$W_{cu} \propto NI$$

$$(W_{cu})_{auto} = (1-K) (W_{cu})_{2 \text{ winding}}$$



- ③ Leakage flux ↓, $X \downarrow$, $V_R \downarrow$ better.
- ④ Core less required, Core loss ↓, η increases,
 loss ↓ reduces

Disadvantage :-

- ① In case of step-down transformer if there is any break in the conductor of winding BC then L-V terminal will hit by H-V high voltage. so, all

The connected load get damage.

(2)




$$I_{sc} = \frac{E_a}{\sqrt{R_{e1}^2 + X_{e1}^2}}$$

So, its S.C current are greater than 2 w/hdy
T/F

Additive $\left\{ \begin{array}{l} \rightarrow \text{Valid } (K \rightarrow 1) \\ \text{near but small} \\ \rightarrow \text{Invalid } (K \rightarrow 0) \\ \text{near to zero} \end{array} \right.$

Subtractive $\left\{ \begin{array}{l} \rightarrow \text{Valid } (K \rightarrow 1) \\ \rightarrow \text{Invalid } (K \rightarrow 0) \end{array} \right.$



$$V_1 I_1 = V_2 I_2 = 25000$$

$$V_1 I_1 = 25000$$

$$= \frac{25000}{10}$$

$$= 2500$$

$$I_1 = 10A$$

$$V_2 I_2 = 25000$$


$$250 I_2 = 25000$$

$$I_2 = 100A$$

Additive polarity :-

cell

first find current of which is not common



$$P_{\text{rating}} = 2750 \times 100 = 275 \text{ KVA}$$

$$K = \frac{V_2}{V_1} = \frac{2750}{2500} = \frac{11}{10}$$

$$K' = \frac{1}{K} = \frac{10}{11} = .909$$

Valid case.

$$\text{Power transferred inductively} = (1 - K') V_1 I_1$$

$$= \left(1 - \frac{10}{11}\right) 2500 \times 110$$

$$= \frac{1}{11} \times 2500 \times 110$$


$$= 25000 \text{ VA} \quad 2$$

Power transferred Conductively.

$$= K' \cdot V_1 I_1$$

$$= \frac{10}{11} \times 2500 \times 110$$

$$= 250 \text{ KVA}$$



$$\text{Rating} = 2750 \times 10$$


$$K = \frac{2750}{250} = 11$$

$$K' = \frac{1}{11} = 0.09$$

$$\text{Inductive Power transfer} = (1 - K') \cdot V_1 I_1 = 28 \text{ KVA}$$

$$\text{Conductive} = K' \cdot V_1 I_1$$

Auto transformer :-




ABD $\rightarrow N_H \rightarrow$ high voltage winding

BC $\rightarrow$ Common short-circuited

CD $\rightarrow N_L \rightarrow$ Low voltage winding



AB $\rightarrow (N_H - N_L) \rightarrow$ Series winding


Leaking auto transformer :-




At no load :-

At no load a current flow from A to D as shown






So a flux is setup in core



So if a load is connected :-

In this condition a current I_L will flow which

opposes the flux ϕ and flux is ϕ' or ϕ_2



→ Now flux ϕ in core reduces. So, primary winding draws current I_H to make current I_L flux constant
So, apply KCL at point c



$$\therefore I_L + I_H = I_L$$

$$I_L' = I_V - I_H$$

For common flux induced emf per turn must be same.

$$E = \sqrt{2} \pi f \phi_m N \propto \frac{E}{N} \propto \phi$$

$$\therefore \frac{V_H}{N_H} = \frac{V_L}{N_L}$$

$$\frac{V_H}{V_L} = \frac{N_H}{N_L} = K_{\text{auto}}$$

turn ratio of auto transformer


How to convert a two winding transformer into auto transformer

Conversion of two winding transformer into auto transformer

It can be converted into two ways :-

- (1) Additive (voltage) $\begin{cases} \text{valid } K \rightarrow 1 \\ \text{invalid } K \rightarrow 0 \end{cases}$
- (2) Subtractive (voltage) $\begin{cases} \text{valid } K \rightarrow 1 \\ \text{invalid } K \rightarrow 0 \end{cases}$


Suppose there is two winding T/F



Additive polarity :-

Case 1

First find current of coil which is in not common



Due to additive polarity turns in both winding called in same direction.


$$K = \frac{V_2}{V_1} = \frac{2750}{2500} = \frac{11}{10}$$

$$K' = \frac{10}{11} = 0.99 \quad \text{Valid case } \therefore K \text{ is near } 1$$

$$\begin{aligned} \text{Power transferred inductively} &= (1 - K') V_1 I_1 \\ &= \left(1 - \frac{10}{11}\right) 2500 \times 110 \\ &= 25 \text{ KVA} \end{aligned}$$

$$\text{Conductively} = K' V_1 I_1 = \frac{10}{11} \times 2500 \times 110 = 250 \text{ KVA}$$

Case II make 250V as primary :-



$$K = \frac{2750}{280}$$

$$K_1 = \frac{280}{2750}$$


$$K_1 = 0.09$$

Since 0 comes
So, invalid

Inductive power transfer = $(1 - K^2) V_1 I_1 = 25 \text{ KVA}$


Conductively = $K^2 V_1 I_1 = \frac{1}{1} \times 250 \times \frac{10}{10} = 2.5 \text{ KVA}$

Subtractive polarity :- It means both coil with ~~coil~~ in opposite direction :-




Inductively = $(1 - K^2) V_1 I_1 =$
 Conductively = $K^2 V_1 I_1$

Case 4




$K = \frac{2250}{250} = 9$
 $K_1 = \frac{25}{45} = 0.55 \text{ (valid)}$



$$kVA = \text{Rating} = 225kVA = 2250 \times 100$$

$$x = \frac{2250}{2500}$$

$$= \frac{48}{50} = .9 \text{ valid car.}$$



$$KVA = 2250 \times 10$$

$$= 22.5 KVA$$

$$K = \frac{2250}{220} = 9$$

$$K' = \frac{1}{9} = 0.111$$

value of

Value :-


275kVA ✓

225KV


Types of transformer :-

① According to construction :-

② core type





shell type



H-V

220V 275V 220V 275V



150 to 1000 kVA
100 to 2000 BT

Winding around, around a part of the core

a part of the core. The core surrounds a part of the winding.

① C-V-V-C core in transformer to reduce stray flux. Half the primary and

→ It has 3-limb and 2 yoke. Middle limb is provided with winding


1/4 the secondary have been placed on one column only. Central on each limb. It having

② Circular cylindrical electrical windings are used.

40 Wmp and 2 pole: ~~It is a series magnetic circuit which~~

(a) Sandwich is one ~~set~~ alternate windings are used.

(b) In square core, large number of ~~the~~ spaces inserted to stepped core and which give more ~~more~~ stable factor, reduced mean length and ~~fields~~.



① It is a series magnetic

which having more leakage

→ Providing insulation &

cooling is easy.

→ Economical for high

voltages

→ In this stepped core is used to reduce copper losses.

→ low voltage winding is inside or near to core due to which :-

→ Reduce in insulation requirement.

→ Reduce the risk of shock in case of insulation break down.

→ It is a parallel magnetic ckt which having less leakage

Difficult in taking cooling and insulation

Economical for low voltage.


Hub

3- ϕ Transformer :-

3- ϕ transformer can be constructed by 2 ways

- (1) Three phase transformer bank :- When a three phase transformer is constructed by three identical single phase transformer then it is called as three phase transformer bank.

Page 74
Class = 38




3- ϕ transformer :-


When a single unit of 3- ϕ transformer is constructed then it is known as 3- ϕ transformer. These are of

two types :-

① Core :-




② Shell type :-



Result :-

- ① Cost of the 3- ϕ transformer is lesser, efficiency is higher than a three phase transformer bank.

Connection of 3- ϕ transformer :-



$$V_L = V_{ph}$$


$$I_L = \sqrt{3} I_{ph}$$

(Insulation) Δ 11 kV

(conductor size) $\Delta \propto \frac{1000}{\sqrt{3}}$

(conductor size) $\Delta = \frac{1}{\sqrt{3}}$ (conductor size)

for ~~H-V~~ size high current side Δ -connection is preferred



$$V_L = \sqrt{3} V_{ph} \text{ (Insulation)} \propto \frac{11}{\sqrt{3}}$$

$$I_L = I_{ph}$$

(Insulation) $Y = \frac{1}{\sqrt{3}}$ (insulation) Δ

for H-V side Y connection is preferred.

Down
H.V $\longrightarrow$ L.V

Y $\longrightarrow$ Δ

UP
L.V $\longrightarrow$ H.V
 Δ Y

Q1


$\sqrt{3} V_{ph1}$

$\sqrt{3} V_{ph2}$


Star - star connection :-

$$\text{given } \boxed{\frac{V_{ph1}}{V_{ph2}} = \frac{I_{ph2}}{I_{ph1}} = \frac{N_1}{N_2} = \frac{1}{K}}$$

h-v side




l-v side





$$\text{find } \boxed{\frac{V_{L1}}{V_{L2}} = \frac{\sqrt{3} V_{ph1}}{\sqrt{3} V_{ph2}} = \frac{1}{K}}$$

$$\boxed{\frac{I_{L2}}{I_{L1}} = \frac{I_{ph2}}{I_{ph1}} = \frac{1}{K}}$$




~~0° phase group~~



0° phase group




180° phase group



H-V - by minute hand

L-V - by hour hand




Star-star connection is not generally used.

⇒ Problem with Y-Y connection :-

In case of Y-Y connection if neutral is not grounded, then there is no third harmonic current in phase, so, current becomes sinusoidal and flux becomes flat topped.


Y connection with no neutral grounding :-




Interference with transmission line :-

② If in star connection neutral is grounded then third order harmonics can flow. So, current

becomes peaky sinusoidal & flux becomes sinusoidal.





Since, Δ connection provides the closed path for 3rd harmonics current, so, current becomes peaky sinusoidal and flux becomes sinusoidal. So, in case of Δ -Y connection if neutral is not grounded then third harmonic current can be obtained by providing a third winding known as tertiary. Tertiary is always connected in delta.



$$I_{ph3} = \frac{3E_3}{3Z_3}$$

③ Delta - Delta connection :-




$$C = \begin{bmatrix} b & c & a \\ a & b & c \\ c & a & b \end{bmatrix}$$



sequence =

~~CBA~~ ~~BCA~~ ~~ACB~~ ~~ABC~~

~~CB~~ ~~ACB~~ ~~A~~



D_{d2}, D_{d0}




Delta star connection

$\Delta - Y$ connection generally preferred for
Step-up transformer

+ 30

- 30



$$3 = 3\sqrt{3}$$



$$V_L =$$

$$V_{L1} = \frac{V_{ph1}}{\sqrt{3} V_{ph2}} = \frac{1}{\sqrt{3} \cdot K}$$


$$\frac{I_{L2}}{I_{L1}} = \frac{I_{ph2}}{\sqrt{3} I_{ph1}} = \frac{1}{\sqrt{3} \cdot K}$$

$$\sqrt{3} V_{L1} = \sqrt{3} V$$


Star to delta π




anticlock wise (+)



clockwise (-)



Y_{d11}



Y_{d1}


$$\frac{V_{L1}}{V_{L2}} = \frac{\sqrt{3} V_{ph1}}{V_{ph2}} = \frac{\sqrt{3}}{K}$$

$$\frac{I_{L2}}{I_{L1}} = \frac{\sqrt{3} I_{ph2}}{I_{ph1}} = \frac{\sqrt{3}}{K}$$

Note :-

- ① Distribution transformer always connected in $\Delta - Y$ due to availability of neutral on secondary side which is required for single phase supply. But, it is a step down transformer.

Scott connection / T-T connection | 2 ϕ - 3 ϕ conversion | 3- ϕ to 2- ϕ conversion



Let 3- ϕ supply

$$\overline{V_{BC}} = V_m \angle 0^\circ$$

$$\overline{V_{CA}} = V_m \angle -120^\circ$$

$$\overline{V_{AB}} = V_m \angle 240^\circ$$

Primary voltage of main T/F $\div$

$$\overline{V_{1m}} = \overline{V_{BC}} = V_m \angle 0^\circ$$

$$\frac{\overline{V_{1m}}}{\overline{V_{em}}} = \frac{N_1}{N_2} \Rightarrow \overline{V_{em}} = \frac{N_2}{N_1} \overline{V_{1m}}$$

$$\boxed{V_{em} = \left(\frac{N_2}{N_1} \right) V_m \angle 0^\circ}$$

Primary voltage of teaser T/F :-

$$\overline{V_{it}} = \overline{V_{AD}}$$

Here $\overline{V_{AD}} = \overline{V_{AB}} + \overline{V_{BD}}$

$$\overline{V_{AD}} = V_m \angle -240^\circ + \overline{V_{BD}}$$

Here

$$\overline{V_{BC}} = \overline{V_{BD}} + \overline{V_{DC}}$$

$$\overline{V_{BD}} = \overline{V_{DC}} = \frac{\overline{V_{BC}}}{2}$$

$$\overline{V_{BD}} = \overline{V_{PC}} = \frac{V_m \angle 0^\circ}{2}$$

$$\overline{V_{AD}} = V_m \angle -240^\circ + \frac{V_m \angle 0^\circ}{2}$$

$$\overline{V_{AD}} = \frac{\sqrt{3}}{2} V_m \angle 90^\circ$$

$$\frac{V_{it}}{V_{et}} = \left(\frac{\frac{\sqrt{3}}{2} N_1}{N_2} \right)$$

$$\therefore V_{et} = \frac{N_2}{\frac{\sqrt{3}}{2} N_1} \times V_{it}$$

$$V_{et} = \frac{N_2}{\frac{\sqrt{3}}{2} N_1} \times \frac{\sqrt{3}}{2} V_m \angle 90^\circ$$

$$V_{et} = \frac{N_2}{N_1} V_m \angle 90^\circ$$

WM 85191#

51.93


20.89

0.2


VS2 (9.1)
4

1.3 VL 9.1

Appt tapping
57.7% of full
winding for
neutral
 $V_{AN} = \frac{V_L}{\sqrt{3}} = .577 V_L$
 $V_{AD} = \frac{\sqrt{3} V_L}{2} = .866 V_L$



$$V_{AD} = V_{AB} + V_{BD}$$



Result :-

Scott connection is used for 3- ϕ to 2- ϕ conversion or 2- ϕ to 3- ϕ conversion

Application :-

To run furnaces

② To run 2- ϕ motor.

③

⑥ Open delta connection :- (V-V connection)



①

Case-1 :- Δ - Δ connected 3- ϕ transformer bank

at rated load ($S_{\Delta-\Delta}$)

When we apply a balanced 3- ϕ to the primaries of Δ - Δ bank then we obtained balanced 3- ϕ on secondary side. So, we can transfer 3- ϕ power by Δ - Δ bank

Suppose rating of each 1- ϕ T/F = 100 KVA



Let

$$\begin{aligned}\overline{V_{RY}} &= V_m \angle 0^\circ \\ \overline{V_{YB}} &= V_m \angle -120^\circ \\ \overline{V_{BR}} &= V_m \angle -240^\circ\end{aligned}$$

Balanced 3- ϕ

$$\overline{V_{ry}} = V_{m2} \angle 0^\circ$$

$$\overline{V_{yb}} = V_{m2} \angle -120^\circ$$



$$\overline{V_{br}} = V_{m2} \angle -240^\circ$$

By KVL

$$\overline{V_{ry}} + \overline{V_{yb}} + \overline{V_{br}} = 0$$

$$\boxed{\overline{I_{L2}} = \sqrt{3} \overline{I_{ph2}}} \text{ (Rated)}$$

Case 2 If one of the transformer of $\Delta-\Delta$ bank gets damage and loading, ^{remaining} $S_{\Delta-\Delta}$ (2)



Let

$$\overline{V_{ry}} = V_m \angle 0^\circ$$

$$\overline{V_{yb}} = V_m \angle -120^\circ$$

$$\overline{V_{br}} = V_m \angle -240^\circ$$

Balanced 3 φ

$$\overline{V_{ry}} = V_m \angle 0^\circ \text{ (remains same)}$$

$$\overline{V_{yb}} = V_m \angle -120^\circ \text{ (remains same)}$$

$$\overline{V_{br}} = ? \text{ (derived below)}$$

By KVL

$$\overline{V_{ry}} + \overline{V_{yb}} + \overline{V_{br}} = 0$$

$$\Rightarrow \overline{V_{br}} = -(\overline{V_{ry}} + \overline{V_{yb}})$$

$$\Rightarrow -(V_m \angle 0^\circ + V_m \angle -120^\circ)$$

$$\boxed{\overline{V_{br}} = V_m \angle -240^\circ}$$

$$\therefore \overline{V_{br}} \text{ also remains same} = \overline{V_{br}}$$

$$I_{ph2} = I_{L2}$$

$$I_{ph2}' = \sqrt{3} I_{ph2} \text{ rated}$$

$$\% \text{ Rise in loading on each T/F} = \frac{I_{ph2}' - I_{ph2}}{I_{ph2}} \times 100$$

$$= \frac{\sqrt{3} I_{ph2} - I_{ph2}}{I_{ph2}} \times 100$$

$$= \frac{I_{ph2} (1.732 - 1)}{I_{ph2}} \times 100$$

$$= 73.2 \times 100$$



$$\% \text{ Rise in loading on each T/F} = 73.2\%$$

So, in case of open delta connection balancing remains the same but both the transformers get overloaded.

Case 3: Rated loading of open delta connection, so, no one T/F is overloaded.

If one T/F of Δ - Δ bank gets damaged then loading (S.V-V). so, no one T/F is overloaded.

(11)



$$I_{L2}' = \frac{I_{L2}}{\sqrt{3}}$$

$$I_{max} = I_{L2}' = \frac{I_{L2}}{\sqrt{3}} \rightarrow \text{Rated}$$

$$S_{\Delta-\Delta} \propto I_{L2}$$

$$S_{V-V} \propto I_{L2}'$$

$$\therefore S_{V-V} = \frac{1}{\sqrt{3}} S_{\Delta-\Delta} \quad \#$$

$$S_{V-V} = \frac{1}{\sqrt{3}} \times 300 = 173.2 \text{ KVA}$$

$$S_{V-V} = 57.7\% \text{ of } S_{\Delta-\Delta}$$

or

rating of S_{V-V} 86.6% of rating of left 2T/r

- In open delta connection if no- one T/F is overloaded then loading is reduced to 57.7% or $\frac{1}{\sqrt{3}}$ of S Δ - Δ or 42.3% of S Δ - Δ or 86.6% of total kVA of both the transformer or reduced by 13.4% of total kVA of both the transformer.

Parallel operation of Transformer :-

It is an arrangement in which two or more T/F primaries are connected with same supply and secondaries are connected to carry the same load.


Necessary condition for parallel operation :-

- (necessary)
- ① Polarity must be properly checked it means polarity of all the transformer connected in parallel must be same otherwise a dead short circuit will occur and transformer gets damaged.

Application :-

- ① Reliability increases
- ② If addition is
- ③ It reduces cost.

$$\frac{W}{n}$$



$$I_{sc} = \frac{220 + 220}{Z_{eA} + Z_{eB}}$$

(Dead short circuit occurs)

② In case of 3- ϕ transformer all the transformers belongs to same phasor group (same relative phase displacement) and must have same phase sequence otherwise a circulating current will flow

① Dd6, Yy0X (If 0) are of same phasor group

② Yd1, Δ y1 same phasor group


③ Yd11, Dyt X (diff phasor group)

(necessary)

③ con

voltage ratio of all the transformer connected


in parallel must be same otherwise a circulating current will flow which causes unnecessary copper loss and net available KVA at output reduces,



$$I_c = \frac{220 - 200}{Z_{eA} + Z_{eB}}$$

$$I_c = \frac{20}{Z_{eA} + Z_{eB}}$$

Example :- by equivalent ckt



$$I_c = \frac{220 - 200}{4} = \frac{20}{4} = 5$$

$$\boxed{\text{Unnecessary copper loss} = I_c^2 (Z \text{ of both})}$$

$$= (5)^2 [2 + 2]$$

$$\boxed{\text{Loss} = 100 \text{ W}}$$

① In order to share load according to their individual KVA rating the magnitude of impedance ($\propto$ impedance) must be inversely proportional to their individual KVA rating.

OR

Their per unit (pu) impedance with respect to their individual KVA rating must be same.

$$\text{KVA Rating} = VI$$

$$\text{KVA Rating} = V \cdot \frac{V}{Z}$$

$$\text{KVA Rating} = \frac{V^2}{Z(\Omega)}$$

$$\boxed{\text{KVA Rating} \propto \frac{1}{Z(\Omega)}} \quad \text{###}$$

(Equivalent leakage impedance of both the transformer must be ~~not~~ inversely proportional to their VA rating)

$$T_A : 200 \text{ KVA}, 200/100 \text{ V}, Z_A = 10 \Omega$$

$$T_B : 100 \text{ KVA}, 200/100 \text{ V}, Z_B = 20 \Omega$$

or

$$Z_{pu} = \frac{Z_{actual}}{Z_{base}}$$

$$= \frac{V_b^2}{(V_A)^2}$$

$$Z_{pu} = \frac{Z(\cdot) (V_A)^2}{V_b^2}$$

$$= \frac{10 \times 200 \times K}{(200)^2}$$

$$= \frac{10 \times 1000}{200}$$

$$= 50 \text{ pu}$$

$$(Z_B)_{pu} = \frac{20 \times 100 \times K}{(200)^2}$$

$$= \frac{20 \times 100 \times 1000}{200 \times 200}$$

$$= 50 \text{ pu}$$

same Δ

- ⑤ All the transformer connected in parallel must have same $\frac{X}{r}$ ratio other wise they will not share kilowatt according to their KVA rating.

$$\cos \theta_A = \frac{R_{eA}}{\sqrt{R_{eA}^2 + X_{eA}^2}}$$

$$\cos \theta_A = 1$$

$$\sqrt{1 + \left(\frac{X_{eA}}{R_{eA}}\right)^2} (KW)_A = V I_A \cos \theta_A$$

$$\cos \theta_B = \frac{R_{eB}}{\sqrt{R_{eB}^2 + X_{eB}^2}}$$

$$(KW)_B = V I_B \cos \theta_B$$

$$(KW) \propto I$$

$$\boxed{\frac{X_{eA}}{R_{eA}} = \frac{X_{eB}}{R_{eB}}}$$

Result :-

- ① Condition 1 is known as most essential condition
- ② Condition 1 and 2 are known as absolute essential condition
- ③ Condition 1, 2, 3, 4, 5 all are known as essential condition.


In-rush current :- At starting of transformer no load current is very high similar to I-H motor. So, to reduce this current transformer is ON at peak voltage. If it is on at zero voltage current will be at its peak.

If two transformer $T_A = 15 \text{ KVA}$, 0.15 PU and $T_B = 5 \text{ KVA}$, 0.15 PU share a common load of 20 KVA then find the individual KVA shared by all the transformer.

$$T_A = 15 \text{ KVA}, 0.15 \text{ PU}$$

$$T_B = 5 \text{ KVA}, 0.15 \text{ PU}$$

$$S_L = 20 \text{ KVA}$$



$$S_A = E I_A$$

$$I_A = I_L \left(\frac{Z_B}{Z_A + Z_B} \right) \rightarrow S_A = E \cdot I_L \left(\frac{Z_B}{Z_A + Z_B} \right)$$

$$\boxed{S_A = S_L \left(\frac{Z_B}{Z_A + Z_B} \right)}$$

$$S_B = E I_B$$

$$I_B = I_L \left(\frac{Z_A}{Z_A + Z_B} \right)$$

$$S_B = E I_L \left(\frac{Z_A}{Z_A + Z_B} \right)$$

$$S_B = S_L \left(\frac{Z_A}{Z_A + Z_B} \right)$$

$$Z_{PU} = \frac{Z(\Omega) (V_A)_b}{V_b^2}$$

$$Z_A = \frac{Z_{PU} \times V_b^2}{(V_A)_b}$$

$$= \frac{.15 \times 10^2}{15 \times 1000}$$

$$Z_A = 10^{-5} \times 2$$

$$Z_B = \frac{Z_{PU} \times V_b^2}{(V_A)_b} = \frac{.15 \times 10^2}{5 \times 1000} = 3 \times 10^{-5} \times 2$$

$$S_A = 20k \left[\frac{3 \times 10^{-5} \times 2}{3 \times 10^{-5} \times 2 + 10^{-5} \times 2} \right] = 15 \text{ KVA}$$

$$S_B = 20K \left[\frac{10^{-5} \times 2}{10^{-5} \times 2 + 3 \times 10^{-5} \times 2} \right] = 5KVA$$

No over loading and no under loading occurs.

Rated load at

$$Z_{A'} =$$

$$Z_B = \frac{.18}{50}$$

SA

$$\frac{2}{3} \times 10^{-5} \times 2$$

$$\frac{(2+3) \times 10^{-5} \times 2}{3}$$

$$\frac{2 \times 20K}{11}$$

$$\frac{40}{11} KVA$$

$$S_A = \frac{11}{11}$$

$$S_A = 16.3636 KVA$$

$$S_B = 8.63 KVA$$



D.C machine :-


- ① D.C motors are used when load demand high starting torque, wide range of speed control, quick reversal, high accelerating and decelerating torque

Working principle of D.C machine :-

① D.C Motor :-

When a current carrying conductor placed in a magnetic field it experiences a force known as Lorentz force whose direction is given by ~~left~~ Fleming's left hand rule which is also known as motor rule.





$$\vec{F} = I (\vec{l} \times \vec{B})$$

B = magnetic field density (T/m)


I = Active length of conductor

l = current in conductor

$$F = BIl \sin \theta$$

angle b/w $\vec{B}$ and $\vec{l}$

D.C generator :- "It works on Faraday's law of electro magnetic induction".




$\vec{V}$ = always tangent to direction of rotation

$$e = \mathcal{L}(\vec{V} \times \vec{B})$$

v = velocity.

$$e = Blv \sin \theta$$

angle $\vec{V}$ and $\vec{B}$




$\phi \Rightarrow$ The axis which bisect the pole pitch is known as geometric neutral axis (GNA)

$\Rightarrow$ The axis which is perpendicular to field lines is known as magnetic neutral axis.

$\Rightarrow$ In the D.C machine armature the induced emf is alternating.


$\Rightarrow$ The direction of current is given by ~~the~~ Fleming's right hand rule which is also known as generator rule.



Construction of D.C machine :-

① Stator / Yoke :- The function of yoke in case of D.C machine is to carry the flux and also provide mechanical support to the whole machine.

⇒ Generally stator core is not laminated but in case of D.C motor is to be operated through a power electronic converter for speed control. It is laminated to reduce eddy current losses.



ϕ = flux per pole

⇒ Yoke handle flux $\phi/2$ or in each $1/4$ part.


⇒ Armature handle flux $\phi/2$

$$\text{speed (N)} \propto \frac{1}{\text{flux}}$$

Pole core :-

⇒ Pole shoes are used to support the field winding and these are chamfered so, that flux distribution becomes uniform.

⇒ In machine D.C machine both pole core and pole shoes are laminated to reduce eddy current losses.




Commutator :-

It is a mechanical converter, ~~used~~ it is used to convert $AC \rightarrow DC$ (Rectifier) in case of D.C generator, and used to convert $DC \rightarrow AC$ (Inverter) in case of motor.


Commutator segments are tapered in shape so, that their assembly gives a circular shape.


No of coils = No of commutator segments



→ Brushes are stationary sliding contacts on commutator in order to supply or collect the current physically brush are placed on direct axis (N-S) axis but magnetically it is on MNA.



⇒ Commutator makes armature flux stationary and unidirectional electro magnetic torque.





④ Bearings:-
friction.

Function of bearing is to reduce
made of "High carbon steel"




An Armature winding

Lap winding:-

Total no of parallel paths $(A) = P$

Preferred for high current



$$R_a = 1 \Omega$$


$$R_a = \frac{2 \times 8}{(4)^2} = 1 \Omega$$

Wave winding

Wave winding:-

$$A = 2$$

② Preferred for high voltage



$$R_a = 4 \Omega$$

$$R_a = \frac{2 \times 8}{(2)^2} = 4 \Omega$$

Resistance of armature = $\frac{\text{Resistance of one conductor} \times \text{total no of conductor}}{(\text{total no of parallel paths})}$

$$R_a = \frac{R_c \cdot Z}{A^2}$$

168 (33)

$$R_a = .05, A = 6$$

$$R_a = \frac{R \cdot Z}{A^2}$$

$$R \cdot Z = R_a \times A^2$$

$$R \cdot Z = 36 \times .05$$

$$A = 2$$


$$R_a = \frac{36 \times .05}{4}$$

$$= \frac{9 \times .05}{1}$$

$$R_a = .45$$

Avg value of induced emf per conductor (E_z)

$$E_z = \frac{\text{Flux cut by conductor in one rotation}}{\text{Time taken to complete one rotation}}$$



N = speed of armature (RPM)

Z = total no of conductor

P = total no of poles

A = total no of parallel paths

Rotation per minute = N

Rotation per sec = $\frac{N}{60}$

Time taken to complete one rotation = $\frac{60}{N}$ sec
Flux cut by conductor in 1 rotation = $P\phi$

$$\therefore E_z = \frac{P\phi}{60/N}$$

$$\boxed{E_z = \frac{NP\phi}{60}} \text{ by one conductor}$$

So, total emf induced due to Z conductors


$$E_{z'} = \frac{NP\phi Z}{60}$$

So, avg emf induced per parallel path

$$\boxed{E_g = \frac{NP\phi Z}{60A}} \text{ Volt}$$

Back emf or counter emf :-

Mechanical power developed in motor :-



$$V_t = I_a R_a + E_b$$

$$V_t I_a = I_a^2 R_a + I_a E_b$$

input electrical power
(P_i)

Armature
Cu losses

P_m

$$P_m = E_b I_a$$

Condition of maximum mechanical power developed :-

$$P_m = V_t I_a - I_a^2 R_a$$

$$\frac{dP_m}{dI_a} = V_t - 2I_a R_a$$

$$\frac{dP_m}{dI_a} = 0, \quad I_a R_a = \frac{V_t}{2}$$

$$E_b = V_t - I_a R_a$$

$$E_b = V_t - \frac{V_t}{2}$$

$$\# \boxed{E_b = \frac{V_t}{2}} \#$$

$$\boxed{P_{max} = \frac{V_t I_a}{2}}$$

η at Max power output $\therefore (\eta)$

$$\eta = \frac{P_{sh}}{P_{in}} = \frac{P_m}{P_{in}}$$

$$= \frac{\frac{V_t I_a}{2}}{V_t I_a} \times 100$$

$$\boxed{\eta = 50\%}$$

$$\boxed{\eta = \frac{E_b I_a}{V_t I_a} \times 100 = \frac{E_b}{V_t} \times 100}$$


Insulated gate Bipolar transistor

Ground time overshoot




Armature reaction :-


Generator at no-load :-




uniformly distributed flux.



Generator at load :-




Determine ϕ_r
by considering a turn



Rotation of $\vec{E}$ is
leading

- In case of D.C generator due to armature reaction MNA shift in the direction of generator rotation. So, to improve commutation brushes need to be forward shift (करते हैं $\frac{12^\circ}{2}$).
- Due to armature reaction in case of D.C generator net flux decreases on leading pole tip and ~~decreases~~ increases in trailing pole tip.

Motor at



$\Rightarrow$ In case of D.C motor due to armature reaction
 MNA shift $\Rightarrow$ in opposite direction of motor rotation
 so, to improve commutation brushes need to be
 backward shift and net flux decreases on trailing



pole tip and increases on leading pole tip.

Effect of armature reaction :-

- ① In D.C machine armature reaction effect is entirely cross magnetising. So, net flux gets distort.
- ② Due to shifting of MNA there is a short circuit current which may cause flash over.
- ③ Net iron losses increases.

Effect of brush shifting :- Due to brush shifting armature flux having two component demagnetising and cross magnetising. So, due to brush shifting extra demagnetising effect occurs:



Generator at load :-




$$\Phi_d = \Phi_a \sin \beta$$

$$\Phi_c = \Phi_a \cos \beta$$

Motor :-



Demagnetising and cross magnetising ampere turns :-



Demagnetising conductor spread on $4B$ out of 360° .

'X' magnetising conductor spread on $(360^\circ - 4B)$ out of 360°

I_c = conductor current.

$$I_c = \frac{I_a}{A}$$

$$\text{conductors per pole} = \frac{Z}{P}$$

$$\text{Turns per pole} = \frac{Z}{2P}$$

$$\text{ATs per pole} = \frac{Z}{2P} \times \frac{I_a}{A} \quad (\text{or for } 180^\circ \text{ electrical})$$

$$\text{For } 180^\circ = \frac{Z}{2P} \times \frac{I_a}{A}$$

$$I^{\circ} = \frac{Z}{2P} \times \frac{I_a}{A (180^{\circ})}$$

in 180° electrical

2B coils

$$2B = \frac{Z}{2P} \times \frac{I_a (2B)}{A (180^{\circ})}$$

$$\text{for } 4B \text{ in } 360^{\circ} \text{ electrical} = \frac{Z}{2P} \frac{4B}{360^{\circ}}$$

$$\text{Demagnetising ATs per pole} = \frac{Z}{2P} \times \frac{I_a}{A} \times \frac{4B}{360^{\circ}}$$

$$'X' \text{ mag magnetising ATs per pole} = \frac{Z}{2P} \frac{I_a}{A} \frac{(360^{\circ} - 4B)}{360^{\circ}}$$

β = Brushes shifted by β angle (electrical)

Methods to reduce armature reaction :-

$$\downarrow \phi_a = \frac{T_s I_a}{s \uparrow}$$


T_s = Turns.

Armature reaction can be decreased by increasing reluctance of ϕ_a


① By using chamfered pole shoes with high

Reluctance ϕ_a - HP.


①



②



③



These two techniques also reduces main flux. so, used for small rating machines.

Compensating coil:-

→ In large rating machine operating under varying load condition at high speed compensating windings are essential.


→ As load varies armature current also vary. So, flux also vary and it link with armature conductor and induces statically induced emf it results in unbalance circulating current and sparking at the brushes. But due to high speed this spark will spread on commutator surface and produces a flash over.

→ The compensating winding is connected in series with armature in such a way direction of current through compensating conductor in any pole phase will be opposite to direction of current through adjacent armature conductor.

→ Compensating winding is provided in pole shoes cutting it into teeth.

→ The compensating winding flux will neutralize

armature flux under pole. So, that armature reaction effect is removed & H₀ both MNA and GNA ~~for~~ becomes coin sides.



$$\phi_{\text{net}} = \phi_b + \phi_a + \phi_c$$

$$\therefore \phi_c = -\phi_a$$

must

Commutation :-

→ The reversal of current in a coil when its commutator segments passes by brush is known as commutation.

⇒ The time taken for a brush to span from 1

segment to another segment is known as
commutation time T_c .

⇒ If current in the coil under going commutation
reverses completely within commutating time then
commutation is successful and it is called as linear
or ideal commutation.


⇒ Successful commutation means no sparking at the brushes

Case-1 Ideal case:-


The inductance of armature is zero.

$$L_a = \frac{N^2}{S}$$

but $L_a \approx 0$



$$at T = T_c$$



Case + 2 : Practically if current in the coil under going commutation ~~is~~ does not ~~reverses~~ with is in commutating ~~time~~, then it is known as non-linear or delay commutation and a spark is produced at trailing ~~edge~~ edge of ~~brush~~ brush.

The change in current is opposed by reactance ~~voltage~~ voltage. Therefore any unchanged current will jump into air and produces a spark.

The inductance of ~~armature~~ armature is $\text{Non} \neq 0$

see

$$L_a = \frac{T_s^2}{S}$$


$$e = - L_a \frac{dI_c}{dt}$$

Reaction
voltage e


$$e = -L_a \left[\frac{-I_c - I_a}{T_c} \right]$$

$$\boxed{\downarrow e = \frac{2 L_a I_c}{T_c \uparrow}}$$


1-




2-



③



Brush width = (2 to 3) commutator seg.



Methods to improve commutation:-

① Resistance commutation:- High resistance carbon

brushes are used to improve commutation. It does not eliminate the spark but reduces its intensity and improve commutation.

⇒

Since it is a soft material. So, offer

self lubricating property but disadvantage due to high brush contact drop.

$$\downarrow \text{Intensity of spark} \propto \frac{1}{\text{Resistance of Brush} \uparrow}$$

(a) Emf commutation :-

(A) Brush shift :-

Generator $\rightarrow$ forward shift

Motor $\rightarrow$ Backward shift.

(B) By using interpole / commutating pole / compole :-

$\rightarrow$ Interpoles are small pole compare to main pole.

located in inter polar region. Interpole windings are also connected in series with armature winding.

$\rightarrow$ Interpoles are chamfered or tapered in shape with more air gap. So, that they does not saturate


easily

$$\phi = \frac{\mu \cdot NI}{S}$$

for const flux of $S \uparrow \therefore$ more I can be applied

⇒ Inter poles are used to neutralized reactance voltage in the coil undergoing commutation by providing commutating flux or counter flux.

⇒ Polarity of Interpole should be equal to polarity of pole ~~ed~~ ahead of generator rotation and behind of motor rotation.




Interpole polarity is decided by the direction of rotation of motor

Interpole polarity is decided by the direction of rotation of motor





Types of D.C Machines



① Separately excited D.C machines :-

Both armature and field windings are electrically isolated

Generator :-





V_b = Brush contact drop

V_b = 1V - 2V Per brush

$$E_g = I_a R_a + V_b + V_t$$

$$E_g > V_t$$

Motor :-



$$V_t > E_b$$

$$V_t = V_b + I_a R_a + E_b$$



Self excited :-

Both armature and field winding are electrically connected.

① D.C shunt Machine :-

Field winding is in parallel with armature :-

Motor :-



$$I_L = I_{sh} + I_a$$

$$V_t = V_b + I_a R_a + E_b$$



$$V_t = I_{SH} R_{SH}$$

$$I_{SH} = \frac{V_t}{R_{SH}}$$

$$\phi_{sh} \propto I_{SH} = \frac{V_t}{R_{SH}}$$

From no load to full load $\phi_{sh} = \text{const}$ without armature reaction

Generator :-




$$V_t = I_{sh} R_{sh}$$

$$E_g = I_a R_a + V_b + V_t$$


$$I_a = I_{sh} + I_L$$

D.C Machine :-

- ① Front pitch :- Distance b/w last conductor of I coil and 1st conductor of second coil.
- ② Back-pitch :- Distance b/w first and last conductor of same coil.
- ③ Average pitch :-
$$\frac{Y_F + Y_B}{2}$$
- ④ Resultant pitch :- Distance b/w conductors of two consecutive coils.
- ⑤ Progressive winding :- If coil goes forward called Progressive winding. i.e. last conductor connected to next commutator segment.




- ⑥ Retrogressive winding :- If coil goes backward is called retrogressive winding. i.e. last conductor connected to previous segment.



D.C compound :-

short shunt compound wound :-



$$V_t = I_{se} R_{se} + V_b + I_a R_a + E_b$$

$$I_{sh} R_{sh} = V_b + I_a R_a + E_b$$

$$I_L = I_{se} = I_{sh} + I_a$$

Cummulative :-

$$\phi_{net} = \phi_{sh} + \phi_{se}$$

differentially :-


$$\phi_{net} = \phi_{sh} - \phi_{se}$$

$$\phi_{sh} > \phi_{se}$$

Long shunt compound wound :-

priority list

10/10/21



$$E_g = I_a R_a + V_b + I_{se} R_{se} + V_t$$

$$V_t = I_{sh} \cdot R_{sh}$$

$$I_a = I_{se} = I_{sh} + I_L$$

fairly used D.C. motor

Result :-

- ① During short circuit of differentially compound D.C generator $V_t = 0$, $\phi_{se} \uparrow$, $\downarrow \phi_{net} = \phi_{sh} - \phi_{se} \uparrow$, $E_g \downarrow$, $I_{se} \downarrow$. So, does not damage during S.C. So, these are used in arc welding.
- ② When starting a differentially connected compound motor it is desirable to short circuit the

Series field winding to avoid the motor from starting in reverse direction.

Process :- at starting $N=0$, $I_{se} \uparrow$, $\phi_{se} \uparrow$,

$$\phi_{net} = \phi_{sh} - \phi_{se}$$

$\phi_{net} < 0$, So, start, in -ive direction (reverse)

Operating characteristics of D.C generator :-

N, E_g, I_f, V_t, I_L

① Open circuit characteristics / saturation curve / magnetization curve

E_g v/s I_f , $N = \text{const}$
 $a_t = \text{No load}$

② External characteristics

V_t v/s I_L , $N = \text{const}$
 $I_f = \text{constant}$

③ Armature / regulation curve :-

I_a v/s I_f , $N = \text{constant}$
 $V_t = \text{constant}$


④ Load curve :-

V_t v/s I_f

$N = \text{constant}$

$I_a = \text{constant}$

Separately excited D.C generator :-



at no load $I_a = I_L = 0$

$$E_g = V_t + I_a R_a + V_b$$

$$E_g = V_t = \text{V} \quad \text{voltmeter reading}$$

$$E_g = \frac{NP\phi Z}{60A}$$

$$E_g \propto \phi \quad \text{Linear}$$

$\phi \propto I_f$

- without saturation: air gap line for 1 pole of core (Linear)
- with saturation B-H curve (Non linear)

Concept

① A.C machine : BH curve area ↓


$$\phi_{\text{residual}} \downarrow \downarrow \downarrow \approx 0$$

Saturation neglected

② D.C machine B-H curve area ↑



$\phi_{\text{residual}} \uparrow \uparrow \uparrow$, Saturation included

$E_g \propto I_f$ $\rightarrow$ BH curve



OA = Induced emf due to residual flux
2V — 4V or minimum

⑧ Load characteristics:-




$$V_t \text{ v/s } I_f$$

$N = \text{constant}$
 $I_a = \text{constant}$
 $\downarrow$
 (Rated)



$$E_g = V_t + I_a R_a + V_b$$

$$V_t = (V) = E_g - (I_a R_a + V_b)$$



② External characteristics:-

$V_t \text{ v/s } I_L$, $N = \text{const}$
 $I_f = \text{const}$




$$V_t = E_g - (I_L R_a + V_{br} + \text{Armature reaction})$$

$$V_t = E_g - I_L (R_a + R_b)$$

$\downarrow$ $\downarrow$ $\downarrow$
 V C Z_m

$$\therefore m = -(R_a + R_b)$$


$$m \approx 0.1 \text{ (very less)}$$



(d) Armature reaction / regulation char?


In $V/s I_f$, $N = \text{constant}$

$$V_t = \text{const}$$



⑧ D.C. shunt generator :-

E_g v/s I_f $N = \text{constant}$
at No load




$$E_g = (I_a R_a + V_b + A R) + V_t$$

Here $I_a = I_{SH}$ (every lux)

$$V_t = E_g - (I_a (R_a + R_b) + A \cdot R)$$

$$I_a = I_{SH} + I_L$$

$$I_a = I_{sh}$$




⑧ Load characteristics :-

$N = \text{constant}$


$I_L = \text{const}$

V_t V/s I_f



$$I_a = I_L + I_{sh}$$

(c) External characteristics :-




separately


$$V_t = E_g - [I_L (R_a + R_b) + AR]$$

shunt :-

$$V_t = E_g - [(I_L + I_{sh})(R_a + R_b) + AR]$$



Armature regulation curve :-




In case of D.C shunt generator from no-load to full load terminal voltage decreases slightly (almost remains constant). So, these generators are used for battery charging.

⇒ It have drooping characteristics. So, it is suitable for parallel operation.

D.C series generator :-

OCC :-



E_g v/s I_f $\left(\begin{array}{l} N = \text{const} \\ \text{at no load} \end{array} \right)$

$$I_L = 0 = I_a = I_{sc} = \neq 0$$

Not possible.

P.Q. Load characteristics :-

$$V_t = E_g - I_a(R_b + R_a)$$

$$N_s = \text{const}$$

$$\therefore I_a = I_f = \text{const}$$

changing I_f and const I_a

$\therefore$ Not possible



E_g occ V_t
 I_f
 $V_t = E_g - (V_b + I_a R_a)$
 $N = \text{const}$
 $I_a = \text{const}$




Result :-

⇒ In case of D.C series generator it is not possible to draw all the characteristics.

⇒ External characteristics :-

compound generator :-



Operating characteristics of D.C motor:-

$$E_b = \frac{NP\phi Z}{60A}$$

$$P_m = E_b I_a$$

$$T_a = \frac{P_m}{\omega} = \frac{E_b I_a}{\omega}$$

$$T_a = \frac{K\phi\omega \cdot I_a}{\omega}$$

$$T_a = K\phi I_a$$

$$\therefore E_b = \left(\frac{2\pi N}{60} \right) \left(\frac{PZ}{2\pi A} \right)$$

$\downarrow \quad \quad \quad \downarrow$
 $\omega \quad \quad \quad K_a$

$$E_b = K_a \phi \omega$$

$$K_a = \frac{PZ}{2\pi A} = \text{armature constant}$$

here drawn b/ω

$$\boxed{\omega, T_a, I_a} \quad V_t$$

$\downarrow$
const

① Speed - Torque ($\omega - T_a$) char

$$\boxed{\omega \text{ V/s } I_a} \quad , \quad \boxed{V_t = \text{const}}$$

② Torque - Armature current ($T_a - I_a$) char


$$\boxed{T_a \text{ V/s } I_a} \quad , \quad V_t = \text{const}$$

③ Speed and armature current charact ($\omega - I_a$)

$$\boxed{\omega \text{ Vs } I_a}, \quad \boxed{V_t = \text{const}}$$

D.C shunt motor :-

preferred slightly more, then almost constant then constant



$$V_t = E_b + I_a R_a$$

$$E_b = V_t - I_a R_a$$

$$I_t = I_a + I_{sh}$$

$$E_b = K \phi \omega$$

$$T_a = K \phi I_a$$

④ Speed torque char :-

$$\boxed{E_b = V_t - I_a R_a}$$

$$K \phi \omega = V_t - I_a R_a$$

$$\omega = \frac{V_t}{K_a \phi} - \frac{R_a}{K_a \phi} I_a$$

$$I_a = \frac{T_a}{K_a \phi}$$

$$\boxed{\omega = \frac{V_t}{K_a \phi} - \frac{R_a T_a}{(K_a \phi)^2}}$$

Case I :- If AR armature reaction is neglected

$$\boxed{\phi \propto I_{SH} = \frac{V_t}{R_{SH}}}$$

$\therefore$ from no load to full load ϕ remains constant.

$$\boxed{\omega = \frac{V_t}{K_a \phi} - \frac{R_a T_a}{(K_a \phi)^2}}$$

$\downarrow$ $\downarrow$ $\downarrow$ $\downarrow$
 $y = c + m x \text{ (line)}$


$$\text{slope} = \frac{-R_a}{(K_a \phi)^2}$$

$$\boxed{\text{slope} = -0.01} \text{ means speed slightly decreases}$$

Case II If armature reaction considered.

As load $\uparrow$, $\phi \downarrow$.

$$\omega = \frac{\uparrow V_t}{K_a \phi \downarrow} - \frac{\uparrow R_a}{(K_a \phi \downarrow)^2} T_a$$




② Speed - armature current :-

$$E_b = V_t - I_a R_a$$

$$K_a \phi \omega = V_t - I_a R_a$$

$$\omega = \frac{V_t}{K_a \phi} - \frac{R_a I_a}{K_a \phi}$$



Case-I

of AR neg armature reaction neglected.

$$\boxed{\phi \propto I_{sh} = \frac{V_t}{R_{sh}}}$$

From no load to full load ϕ remains constant.

$$\boxed{\omega = \frac{V_t}{K_a \phi} - \frac{R_a}{(K_a \phi)} I_a} = \frac{1}{K_a \phi} (V_t - I_a R_a)$$

$y = c \quad m \quad x \rightarrow \text{line}$

$$\boxed{\text{slope} = -\text{ive} = -\frac{R_a}{K_a \phi}}$$

$$\boxed{\text{slope} = -0.1} \quad (\text{speed ~~increases~~ decreases very less or slightly})$$

Case-II of Armature reaction included.

As load $\uparrow$ $\phi \downarrow$


$$\omega = \frac{V_t}{K_a \phi} - \frac{R_a}{K_a \phi} I_a$$

$$\omega = \frac{1}{K_a \phi} \underbrace{(V_t - I_a R_a)}_{\text{Constant}}$$

due to armature reaction of $\phi \downarrow$ the $\omega \uparrow$.

$$\therefore \boxed{\omega \uparrow \propto \frac{1}{\phi}} \quad \text{with armature reaction}$$

ω increases



③ Torque - armature current characteristics :-

$$T_a = K\phi I_a$$

Case I without armature reaction

$$\phi = \text{const}$$

$$T_a = (K_a\phi) I_a$$

$$\downarrow \quad \downarrow \quad \downarrow$$


$$y = m \quad x$$

$$m = K_a\phi$$

Case II with armature reaction.

$$T_a = K_a(\phi)(I_a)$$

$\therefore$ for same I_a at full load if ϕ ↓
So T_a also ~~decreases~~





Result +

⇒ In case of D.C shunt motor from no load to full load speed decreases slightly (almost remains constant). so, these motors are used in lathe machine.

⇒ In case of D.C shunt motor without armature reaction all the characteristics are linear but due to armature reaction becomes non linear.

② D.C series motor :-





$$V_t = I_a R_a + I_{se} R_{se} + E_b$$

$$E_b = V_t - I_a \underbrace{(R_a + R_{se})}_{\downarrow}$$

$$E_b = V_t - I_a R_a'$$

$$T_a = K \phi I_a$$

Case → I Without Armature reaction

$$\phi \propto I_{se} = I_a \quad (\text{Linear})$$

$$\phi = \chi I_a$$

① Speed - Torque ($\omega - T_a$)

$$E_b = V_t - I_a R_a'$$

$$K \phi \omega = V_t - I_a R_a'$$

$$\omega = \frac{V_t}{K \phi} - \frac{R_a' I_a}{K \phi}$$

$$W = \frac{V_t}{K_a \phi} - \frac{R_a I}{(K_a \phi)^2} T_a$$

Case - I

$$\phi = \lambda I_a$$

$$T_a = K \phi I_a$$

$$T_a = K_a \phi I_a$$

$$T_a = K_a \phi \frac{\phi}{\lambda}$$

$$\phi = \sqrt{\frac{T_a \lambda}{K_a}}$$

$$W = \frac{V_t}{K_a \sqrt{\frac{T_a \lambda}{K_a}}} - \left(\frac{R_a I}{K_a^2 \cdot \frac{T_a \lambda}{K_a}} \right) T_a$$

$$W = \frac{V_t}{\sqrt{K_a \lambda} \cdot \sqrt{T_a}} - \frac{R_a I}{K_a \lambda}$$

~~Factorial~~

$$W = \frac{V_t}{\sqrt{K_a \lambda}} \cdot \frac{1}{\sqrt{T_a}} - \frac{R_a I}{K_a \lambda}$$

$$R_{el} = R_{at} + R_{se} = \text{low} \approx 0$$

$$\omega \approx \frac{V_t}{\sqrt{K_a \lambda}} \cdot \frac{1}{\sqrt{T_a}}$$

$$\omega \propto \frac{1}{\sqrt{T_a}}$$

$$T_a \propto \frac{1}{\omega^2}$$

at starting $\omega = 0$

$\therefore T \longrightarrow \infty$ from above eqⁿ

$\therefore$ D.C. series motor is not started at no load

$$T = K \phi I_a$$

Case-II with saturation :-

$$\phi = \text{constant}$$

$$w = \frac{V_t}{K_a \phi} - \frac{R_a}{(K_a \phi)^2} t_a$$



$\downarrow$
y

$\downarrow$
c

$\downarrow$
+ m \cdot x

$\downarrow$
t_a

Linear



Result :-

⇒ If a D.C series motor is started at no load then it will accelerate with dangerously a high starting torque and at no load motor may get damaged.

⇒ Due to high starting torque these motors are used in locomotives or train or traction.

Speed and armature current characteristics:-

$$E_b = V_t - I_a R_a$$

$$K_a \phi \omega = V_t - I_a R_a$$

$$\omega = \frac{V_t}{K_a \phi} - \frac{R_a}{K_a \phi} I_a$$

Case-I $\{\phi = \lambda I_a\}$

$$\therefore \omega = \frac{V_t}{K_a \lambda I_a} - \frac{R_a I_a}{K_a \lambda I_a}$$

$$\omega = \frac{V_t}{K_a \lambda I_a} - \frac{R_a I}{K_a \lambda}$$

$$I_b, R_{a1} = 0$$

$$\omega = \frac{V_t}{K_a \lambda I_a}$$

$$\omega \propto \frac{1}{I_a}$$

$$I_a \propto \frac{1}{\omega}$$

at starting

$$\omega = 0$$

$$I_{se} \rightarrow \infty$$


Case II :

$$\phi = \text{const}$$

$$\omega = \frac{V_t}{K_a \phi} - \frac{R_a I}{K_a \phi}$$

$$y = c + m \cdot x$$

linear



Torque armature current characteristics :-

$$T_a = k \phi I_a$$

Case I Without armature reaction.

$$\phi = \lambda I_a$$

$$\therefore T_a = (K_a \lambda) I_a^2$$

□


$\lambda \propto I_a^2 \rightarrow$ (Parabola)

Case II :- Saturation

$\phi = \text{constant}$

$$T_a = K_a \phi I_a$$


$I_a \propto T_a$ (linear)



Result :-


① In case of D.C series motor all the characteristics are non-linear but due to saturation becomes linear

② For all



$$T = K \phi I_a$$

$$E_b = K \phi \omega$$



Q A ~~240~~ 240V, 50A, 1500 RPM separately excited D.C motor
 having armature resistance of 2Ω find its starting current.

$$E_b = \frac{NP\phi Z}{60A} \quad \text{at starting } N = 0$$

$$E_b = 0$$

$$V_t = E_b + I_a R_a$$

$$\therefore V_t = I_a R_a$$

$$I_a = \frac{2400}{2}$$


$$I_a = 1200$$

$$I_{FL} \times = 1200 I_a$$

$$x = \frac{I_a}{I_{FL}}$$

$$= \frac{1200}{50}$$

$$\boxed{x = 24}$$



$$\boxed{I_{st} = 24 I_{FL} \quad (0.8 + 0.2)}$$

Pr

Starters are used to limit high starting current, starter is a resistor connected in series with armature.

Types of starter :-

① Shunt motor starter :-

① 3 point starter

② 4-point starter.

② Series motor starter :-

① 2-point starter

② 3-point starter :-

Construction :-

Starter is a variable resistance integrated into number of sections. The contact point of these sections is known as studs. These are OFF, 1, 2, 3, 4, 5 (RUN).

⇒ There are three main points line terminal L which is connected to positive or negative terminal of supply, field terminal F which is connected to field winding and armature terminal A which is connected to armature.

Spring - phosphor bronze (non magnetic material)

⇒ The line terminal L is connected to an electromagnet which is known as over load ~~rel~~ release (OLR). The other end of (OLR) is connected to lower conducting end of handle where a spiral spring also attached and handle also contain a soft iron piece.

⇒ This handle is free to rotate from studd off to RUN against the force of spring.

⇒ A parallel path is derived from studd I and given to another electromagnet known as no volt release. which is further connected to F terminal.

⇒

⇒ For starting the motor handle is moved to come in contact with stud - (1) as the stud (1) touches handle touches stud (1) all the starting resistance gets connect in series with armature. So, starting current reduces and motor start rotation.

⇒ After the armature pickup sufficient speed handle is moved to stud (2) this by cutting out resistance b/w stud one and (2) ~~now a moment~~ ^{movement} of handle is continued smoothly until the soft iron keeper touches the holding coil.

⇒ During waiting period of each stud the armature current falls and speed increases exponentially.

⇒ The waiting period of each stud reduces progressively from (1)-(2) and so on.

⇒ In case of power failure holding coil gets demagnetise and spiral spring bring the handle to its off position.

⇒ In case the armature current exceeds a preset value due to overload then overload release becomes more strong and attract the soft iron piece. So, that terminal A and B off of holding coil gets short circuit. and holding coil get demagnetise and handle move to OFF position.


For Both OLR and NVR act as protective devices

Disadvantage :-

- ① Since, both field winding and holding coil are connected in series. So, it cannot be used where speed controlled by flux weakening method. Otherwise holding coil releases handle and motor gets turn off.


4 point starter :-

This starter have points and both field winding and holding coil are connected in parallel. So, it ~~cannot~~ be use where speed controlled by flux weakening method.



D.C series motor starter

① α -point starter :-



Losses :-

① Rotation Loss :- Mechanical Loss + Armature core loss
(ω_0)

② I_a loss $\left\{ \begin{array}{l} \rightarrow \text{Armature Cu loss } (I_a^2 R_a) \\ \rightarrow \text{field winding Cu loss } (I_f^2 R_f) \end{array} \right.$

NOTE :-

for I-M constant

$$\textcircled{1} \text{ Constant Loss} = \text{Armature core loss} + \text{Mech loss} + I_b^2 R_b$$

$$\textcircled{2} \text{ Variable Loss} = I_a^2 R_a$$

for I/F const

D.C machine constant

$$\text{Constant loss} = \text{Variable loss}$$

$\textcircled{3}$ max η condⁿ constant


$$\begin{aligned} \frac{A}{V} &< \text{low resistance} \\ \text{actual value} &= A - \textcircled{1} \\ \text{high resist} &= V - A \end{aligned}$$

Testing of D.C machine:-

$\textcircled{1}$ No load test / Swinburnes test :-

Since, it is a no load test. So, it cannot be performed for D.C series motor. And from this test

we cannot calculate rotational loss.



$$P_i = P_o + \text{Loss}$$

at starting $P_i = 0 + \text{Loss}$

- Armature loss
- Field loss
- Armature core loss
- Mech loss

$$V_t I_{L0} = I_a^2 R_a + V_t I_{sh} + W_o$$

$$W_o = V_t I_{L0} - I_a^2 R_a - V_t I_{sh}$$

Diagram showing the components of the equation above, with arrows pointing from terms to their respective measurements:


- W_o is labeled "Cal" (Calculation)
- V_t is labeled with a voltmeter symbol (V)
- I_{L0} is labeled with an ammeter symbol (A)
- I_a^2 is labeled with an ammeter symbol (A)
- R_a is labeled "D.C test"
- V_t is labeled with a voltmeter symbol (V)
- I_{sh} is labeled with an ammeter symbol (A)

Hopkinson test / back to back test / Regenerative test

⇒ In this method 2 identical D.C machines are coupled mechanically as well as electrically and tested simultaneously. One of the machine runs as motor and another as generator.

⇒ This method can be used for large rating machine because the input power is only losses of both the machines.

⇒ This method can be applied for both shunt and series motor.



P_{i0} = Losses of both the machines

$$V_t I = W_0 + I_m^2 R_a + W_0 + I_a^2 R_g$$

$$W_0 = \frac{V_t I - (I_m^2 + I_a^2) R_g}{2}$$

Power input to motor = $V_t I_m$

Let efficiency of motor is -

$$\eta_m = \frac{\text{motor o/p}}{\text{motor i/p}}$$

$$\text{motor o/p} = \eta_m \times \text{motor i/p}$$

$$\text{motor o/p} = \eta \cdot V_t \cdot I_m \quad (1)$$

$$\text{Power o/p generator} = V_t I_{o1}$$

let efficiency of generator:-

$$\eta_{o1} = \frac{\text{Generator D/P}}{\text{Generator I/P}}$$

$$\text{Generator I/P} = \frac{\text{Generator O/P}}{\eta_{o1}} = \frac{V_t I_{o1}}{\eta_{o1}} \quad \text{--- (2)}$$

Gen

$$(1) = (2)$$

$$\eta_m \cdot V_t I_m = \frac{V_t I_{o1}}{\eta_{o1}}$$

$$\eta_{o1} \cdot \eta_m = \frac{I_{o1}}{I_m}$$

$$\eta_{o1} = \eta_B = \eta \quad \text{identical machines}$$

$$\eta = \sqrt{\frac{I_{o1}}{I_m}}$$

$$I_{o1} < I_m$$


$$\eta < 1$$

Retardation test :-

This test is conducted to calculate rotational losses and also to separate ~~the~~ armature core and mechanical losses by conducting this test in two ways :-

Way 1 :- Run the motor slightly more than rated speed and ~~it~~ disconnect only armature and field winding remains connected to the supply. In this case all the stored kinetic energy waste in rotational loss →

$$\text{Rotational loss} = \text{Armature core loss} + \text{mechanical loss}$$




$$d(\text{stored K.E.}) = \text{Mech loss} + \text{Armature core loss}$$

$$KE = \frac{1}{2} J \omega^2$$

J = moment of inertia ($\text{kg} \cdot \text{m}^2$)
 ω = speed of the motor


$$\omega_0 = \frac{d}{dt} \left(\frac{1}{2} J \omega^2 \right)$$

$$\omega_0 = J \omega \frac{d\omega}{dt}$$



Way 2 :- Repeat the same process but field winding is also disconnected from the supply. In this case stored kinetic energy waste into mechanical

class




$$\frac{d(KE)}{dt} = \text{Mechanical loss} + 0$$

$$KE = \frac{1}{2} J \omega'^2$$

analog

$$KE = \frac{1}{2} J (\omega')^2$$

$$\text{mech loss} = J \omega' \frac{d\omega'}{dt}$$




$$\frac{d\omega}{dt} > \frac{d\omega'}{dt}$$

Retardation in way-1 > Retardation in way-2

more loss occurs

Concept:- If supply terminals of a D.C shunt motor are interchanged then it will continue to run in the same direction.




$$T_a = K \phi I_a$$

$$T_a^2 = K \phi I_a^2$$

$$T_a = K \phi I_a$$

Concept - 2 :- If supply terminal of D.C series motor are interchange. Then it will



$$T_a' = K \phi I_a'$$

$$T = K \phi I_a$$

$$T_a^2 = K \phi I_a^2$$

$$T = K \phi I_a^2$$

Universal motor or single phase A.C series motor :-

When a single phase A.C supply is given to a D.C series motor it runs normally but with

large noise and sparking at the brushes. So, yoke and pole shoes are laminated to reduce eddy current losses, number of series field winding turns are also reduced to reduce field winding reactance, high resistance brushes are used with increased brush area.

⇒ The machine is generally operated at lower flux density. So, runs at very high speed. (7000 rpm to 10,000 rpm). It is popular in kitchen application such as mixer, juicer and hand tool application such as drilling machine, vacuum cleaner, hair dryer, grinder.

⇒ Low frequency operation of D.C series motor used in European railway to improve commutation, power factor and efficiency.



⇒ Work on both AC and D.C.

$$E_b = V_t \quad V_t = E_b + I_a R_a$$

$$E_b = K \phi \omega$$

$$V_t - I_a R_a = E_b$$

$$\boxed{\frac{V_t - I_a R_a}{K} = \phi}$$



① Breaking :-

Plugging / counter current breaking :-


For breaking purpose the torque is to be negative.

So, the torque can be reversed by reversing field winding terminals or by reversing the armature winding terminals but the inductance of armature is low compare to field. So, armature terminals


are to be reversed.

⇒ During plugging stored kinetic energy dissipate into heat.

Materning mode:



|||



$$I_a = \frac{V_t - E_b}{R_a}$$


of plugging in armature



parallel path

$$L_{eq} = L/4$$

in a field.



$$A = 1$$


$$[P.P]$$

$$L_{eq} = L$$


$$\therefore L_{field} > L_a$$

more oppose to reverse current. So, detuning time increases and it takes more time.

Braking mode :-



|||



$$I_b \uparrow = \frac{V_t + E_b}{R_a} = \frac{230 + 200}{R_a}$$

voltage added
so, $I_b \uparrow$


in motor $I_a \propto V_t - E_b$

$$\uparrow T_a = K_a \phi I_b \uparrow$$

so, retardation or plugging takes place faster.

Dynamic method:-

for dynamic braking armature is disconnected from the supply and external resistor R_b is connected. so, it act as a separated excited D.C generator and its stored kinetic energy waste in losses.



Regenerative braking :-

In case of motor speed become more than its no-load speed then it will work as D.C generator. So, a reverse torque experience by motor. And its speed control automatically.

Condition for D.C shunt generator voltage build up :-

- ① Pole should contain residual flux which is obtained by field flashing (charging).
- ② Speed should be more than critical speed i.e.

$$\boxed{N > N_c} \Rightarrow \boxed{E_g > V_{drop}}$$

③ Combined resistance of field and armature should be less than critical resistance.

④ Field and armature winding should be properly connected in such a way their initial mmf should add residual flux. Otherwise voltage build up is zero.

⑤ Best condition for D.C shunt generator voltage build up initially no load is connected.

D.C series generator voltage build up conditions:-

Following conditions are necessary:-

① Same

② Same

③ Combined resistance of armature, series field, load must be less than critical value. $R_a + R_{se} + R_L < R_c$

④ same as previous

⑤ Best condition for voltage build up in D.C series generator initially some load is connected.

① A D.C. shunt generator build up voltage normally if its field winding is reversed then.


② Voltage, ^{buildup} normally.

③ Voltage build up normally in opposite direction.

④ No voltage build up but v/g ~~at~~ across armature is 8V.

⑤ Zero

⑥ If only direction of rotation is reversed.




V. Build = Zero

⑦ If both direction of rotation and field winding

terminals are reversed. both Residual and new current ~~are~~ ^{are} in same direction.

⑧ Voltage build up normally

① A D.C shunt generator supply power to a bus bar and if its mechanical input fail then, it will work as a D.C shunt motor running in the same direction.



$$T = k \phi I_a$$

$$T = -k \phi I_a$$

$$T = k \phi I_a$$

$$T = -\phi \omega$$

Generator ($E_g > V_t$)
as E_b becomes Motor ($E_b > V_t$)
greater than V_t

Gen r

$$(T_g) = k \phi I_a$$


Motor

$$(T_a)_m = -k_a \phi I_a$$

$$\rightarrow (T_g)$$

Same direction

Q If a D.C series generator supply power to a bus bar then if its prime mover fail. It will work as



$$(T_a)_g = K \phi I_a$$

$$= K \phi I_g$$


$$(T_a)_m = -K \phi I_g$$

If its prime mover fails it will work as

D.C series motor running in opposite direction.


Page

299-07



If E_b becomes less than V_t then ~~motor~~ generator becomes motor and E_b becomes E_t

If field winding of D.C motor directly dis connect from supply
its speed $\propto$ increases



$$V_t = E_b + I_a R_a$$

$$E_b = V_t - I_a R_a$$

$$K \phi \omega = V_t - I_a R_a$$


By variation in armature terminal voltage

$$\omega = \frac{1}{K \phi} (V_t - I_a R_a)$$

By variation in armature resistance

flux weakening method

① By variation in armature resistance :- $I_r = \frac{s E_b}{R}$



$$I_a = K \phi I_a = \text{constant}$$

$$I_a = \text{const}$$

By KVL

$$V_t = I_a (R_{ext} + R_a) + E_b$$

$$E_b = V_t - I_a (R_{ext} + R_a)$$

$$\omega = \frac{1}{K_a \phi} [V_t - I_a (R_{ext} + R_a)]$$

↓
below rated

$$P_m = E_b I_a = K_a \phi \omega I_a$$

$$\sqrt{P_m} \propto \omega$$


↓
lower o/r speed

$$P_i = V_t I_L$$

$$P_o = V_t (I_a + I_{sh})$$

Constant

D.C series motor :-



$$V_t = I_a (R_a + R_{ext} + R_{se}) + E_b$$

$$E_b = V_t - I_a (R_a + R_{ext} + R_{se})$$


$$\omega = \frac{1}{K_a \phi} [V_t - I_a (R_a + R_{ext} + R_{se})]$$

Result same as previous.

Result :-

- ① Since armature current remains constant, so, power delivered from supply mains to the motor remains constant.
- ② The power output decreases in proportional to speed.
- ③ Since, torque developed by the motor remains constant. So, it is known as constant torque variable power drive.
- ④ It is less efficient method.

Flux weakening method :-



$$I_{sh} = \frac{V_t}{(R_{sh} + R_{ext})}$$

$$\downarrow \phi_{sh} \propto I_{sh} \propto \frac{1}{(R_{sh} + R_{ext})} \uparrow$$

Induction motor speed control is torque always control

$$V_t = I_a R_a + E_b$$

$$\omega = \frac{1}{K_a \phi} (V_t - I_a R_a)$$

$R_a \approx 0$ (negligible resistance)

$$\omega = \frac{V_t}{K_a \phi} \Rightarrow \boxed{\omega \propto \frac{1}{\phi}}$$

aberrated.

$$P_m = T_a \times \omega$$

$$\boxed{\omega = \frac{P_m}{T_a}}$$

if ω changes then for const P_m T_a changes

$$\boxed{T_a \propto \frac{1}{\omega}}$$

$$\boxed{P_m = E_a I_a = \text{constant}}$$


$$\boxed{I_a \propto \frac{1}{E_b}}$$

25119419000/287

2510018503

160553


D.C series motor :-



Results :- In this method mechanical power developed by motor remains constant but torque developed by armature decreases in inversely proportional to speed.

- Armature current increases as speed increases.
- Speed obtained are above rated.
- Top speeds are obtained at very high armature current.
So, armature gets overheated.

Artificial P_m or T_c constant
method




Speed control by variation in ^{armature} terminal voltage or Ward-Leonard method of speed control:-

⇒ Speed below rated speed are obtained by decreasing the field flux of a D.C generator and above base speed are obtained by decreasing the field flux of D.C motor.

→ This system of speed control is best suited for unlimited range of speed control in both the direction. It is used in industries such as rolling mill, metal

paper motor.

Disadvantage is due to higher initial cost.



$$V_t = E_b + (I_a R_a) \quad \text{or} \quad 0$$

$$V_t = E_b$$


$$V_t = K \phi \omega$$

$$\boxed{V_t \propto \omega}$$

Q

Speed control of traction motor:-

no. 10364



$$V_t = E_b + I_a R_a$$

$$V_t \propto E_b$$

$$V_t = K \phi \omega$$


$$\omega \propto \frac{V_t}{\phi}$$

$$N \propto \frac{V_t}{I_a} \quad \text{--- (1)}$$

Connected in series :- (identical)

$$T_a = K \phi I_a$$

$$T_a \propto I_a^2 \quad \text{--- (2)}$$



$$N_{se} \propto \frac{V_t}{I_a}$$

$$N_{se} \propto \frac{V_t}{I_a}$$

$$N_{se} = \frac{N}{2}$$


from (2)

$$T_{se} \propto I_a^2$$

$$T_{se} = T_a = \text{const}$$

$$\frac{V_t}{2} = \frac{K \phi I_a}{K \phi \omega} = V_t - I_a R_a$$

Connected in parallel



$$N_p \propto \frac{V_L}{\frac{I_a}{2}}$$

$$N_p \propto \frac{2V_L}{I_a}$$

from ①

$$N_p = 2N$$

$$(T_a) \propto (I_a/2)^2$$

$$(T_a)_p \propto \frac{I_a^2}{4}$$

$$(T_a)_p = \frac{T_a}{4}$$

$$\text{Result} = N_p = 4 N_{se}$$


$$\& T_p = \frac{T_{se}}{4}$$

Parallel operation of D.C generator:-

For parallel operation of D.C generator terminal voltage and polarity should be same

D.C series generator:-

For satisfactory parallel operation of D.C series generator it is necessary to connect the armature ~~the~~ through a heavy copper bar known as equalizing bar.



No load.


without equalizing bar

$(I_1 + I_2)$ increases and $(I_a - I_f)$ decreases.

$$\therefore E_{g1} = 235V \text{ and } E_{g2} = 225V$$

and this carry one and a

stage comes motor become generator (1)




with equalizer bar

then I_c gets the shortest path.

Shunt generators in parallel:

D.C shunt generators are having drooping characteristics. $\therefore$ these are popular for parallel operation.



Special machine :-

Repulsion type motor :- In A.C series motor rotor and stator windings are conductively coupled but in case of repulsion motor both stator and rotor windings are inductively coupled means it works on transformer action. According to construction and working principle repulsion type motors are of two types.

① Repulsion motor :-

• Principle :- start and run on repulsion principle

② Repulsion start Induction run motor :-

Principle :- It starts on repulsion principle but at a particular speed it runs as single phase induction motor.

Construction :- Stator having non salient poles and a single phase distributed winding similar to single phase induction motor.

⇒ Stator windings are connected to 1- ϕ A-C supply


⇒ The rotor or armature is similar to D.C motor having commutator and brushes

⇒ The brushes are short circuited by a low resistance

~~⇒~~ ~~##~~ Repulsion motor runs below synchronous speed
it ~~also~~ develop the torque in the direction which the brushes are shifted used to where high starting torque and adjustable speed required. So, used in oil winders.


⇒ The commutation is best when the ~~rotor~~ rotor runs near to N_s . By shifting the brushes speed, torque, direction of rotation ~~of~~ can be controlled

⇒ Since it runs below synchronous speed. So, commutation problem. So, demand more maintenance, runs with vibration and noise




$$T = 0 \quad \therefore \quad \alpha = 0$$

②



$$T \neq 0 \text{ (tive)} \\ 0^\circ < \alpha < 90^\circ$$


③



$$T = -\text{ive}$$

$$-90^\circ < \alpha < 0^\circ$$

④



$$\alpha = 90^\circ \quad T = 0$$

$$T \propto \sin \alpha \cos \alpha \\ \text{or} \\ T \propto \sin 2\alpha$$

$$T_{\text{max}} \text{ at } \alpha = 45^\circ$$


Servo motor :-

→ These motors are used in control system and these motors respond to the error signal abruptly known as servo motor. These motors are designed with high torque to inertia ratio. So, ratio of servo motor designed with long axial to length and smaller diameter to reduce rotor inertia.

→ Used in radar, process controller, tracking and guiding system robotics, computers, automatic manufacturing.

⇒ A.C servomotor :-

A.C servo motor is a two phase induction motor having thinner conductor bar in squirrel caged rotor. so, resistance is high which gives a linear torque slip characteristics.




② D.C Servomotor : Generally permanent magnet D.C motors are used as servomotor. For

$\Rightarrow$ For fast response armature control methods are used.

Stepper motor : Stepper motor does not rotate continuously but rotate in discrete (steps) manner.

$\Rightarrow$ The rotor of a stepper motor is a permanent magnet



$\alpha =$ The angle by which rotor rotates for 1 pulse
 ↓
 step angle.

$$\alpha = \left(\frac{T_s - T_r}{T_s \cdot T_r} \right) \times 360^\circ$$

$T_s =$ No of stator teeth / Pole

$T_r =$ No of rotor teeth.

$m = \frac{T_s}{T_s - T_r} =$ No of phases

$$\alpha = \frac{360^\circ}{m \cdot T_r}$$

→ The rotor has winding, no commutator and no brushes.

→ These are more popular in computer industry because they can be easily controlled by computers, microprocessors and programmable controllers. (compatibility with digital system)

⇒ α is from 0° to 90° but most common it is $1.8^\circ, 2.5^\circ, 7.5^\circ, 15^\circ$.

⇒ Higher the resolution higher the accuracy of positioning of an object by the motor.

Resolution = No of steps per revolution

$$R = \frac{360^\circ}{\alpha}$$

motor shaft speed (n) = Rotation per second.

$$n = \frac{\alpha f}{360^\circ}$$

f = stepping frequency (pulse per second)
(pulse rate)

$$\boxed{\text{Step angle } (\alpha) \propto \frac{1}{\text{No of steps}}}$$

$$\boxed{\text{Resolution} \propto \text{No of steps}}$$

$$\boxed{\text{Accuracy} \propto \text{Resolution}}$$

∴ {more no of steps = more resolution = more accuracy}

Q A stepper motor has a step angle of 2.5° .
Find its resolution.

$$R = \frac{360^\circ}{2.5} = 144$$

$$\boxed{R = 144^\circ \text{ steps per rev}} \quad \{$$

Q In above question find no of step require
for the shaft to make 25 revolution.

$$\begin{aligned} 1 \text{ revolution} &= 144 \text{ steps} \\ 25 \text{ steps} &= 144 \times 25 \end{aligned}$$

$$25 \text{ steps} = \frac{3600}{144 \times 25}$$

$$= 3600 \text{ Steps}$$

R

Q In above question find shaft speed if the stepping frequency is 3600 PPS.

$$n = \frac{\alpha}{360}$$

$$= \frac{2.5 \times 3600}{360}$$

$$n = 25 \text{ RPS}$$

Q A single stack 3- ϕ VR variable reluctance has a step angle of 15° find no of its stator and rotor poles $T_s, T_r = ?$

$$m = \frac{T_s}{T_s - T_r}$$

$$\alpha = \frac{(T_s - T_r) 360^\circ}{T_s \cdot T_r}$$

$$\alpha = \frac{1}{T_r \cdot m} \cdot 360^\circ$$

$$T_r 15' = \frac{360}{3}$$


$$T_r = \frac{120}{15} = 8$$

$$3 = \frac{T_s}{T_s - 8}$$

$$3T_s - 24 = T_s$$

$$\boxed{T_s = 12} \quad \text{2}$$

(a)



$$V_t = E_\phi + I_a R_a$$

$$V_t \approx E_\phi$$

$$V_t \approx K_a \phi \omega$$

$$V_t \propto \phi \cdot \omega$$

$$\boxed{\omega \propto \frac{V_t}{\phi}} \quad \text{1}$$

$$\phi \propto I_{sh} = \frac{V_t}{R_{sh}}$$

$$\phi \propto V_t$$

$\omega = \text{constant}$

$$T_a = K_a \phi I_a = T_L \quad (\text{for operation})$$

$$T_L \propto \omega^2$$

$$K_a \phi I_a \propto \omega^2$$

$$I_a \propto \frac{1}{\phi} \quad \propto \frac{1}{V_t}$$

↓ ↓
2 times 2 times

(3)

(7)