

(KEES03) Electrical Machines 2nd Syllabus.

Date _____

Unit-1 Synchronous Machines - I

Constructional features, Armature winding, EMF Equation, Winding coefficients, Equivalent circuit and phasor diagram, Armature reaction, O, C, & S, C, tests, Voltage regulation using Synchronous Impedance method, MMF-equation method, Potier's Triangle method, Voltage and frequency control (Governor system) of alternators, Parallel operation of synchronous generators, Operation of infinite bus, Synchronizing power and torque coefficient.

Unit-2 Synchronous Machines - II

Two reaction Theory, Transient and sub-transient reactance, Power flow equations of cylindrical and salient pole machines, Operating characteristics of Synchronous Motor - Starting methods, Effect of varying field current at different loads, V-curves, Hunting & damping, Synchronous condenser.

Unit-3 Three phase Induction Machine - I

Constructional features, Rotating magnetic field, Principle of operation, Phasor diagram, Equivalent circuit, Torque and power equations, Torque-slip characteristics, No load & blocked rotor tests, Efficiency.

Unit-4 Three phase Induction Machine - II

Starting, Deep bar and double cage rotors, Cogging & Crawling, Speed control (with and without emf on

Spiral

injection in rotor circuit).

Unit - V Single phase Induction Motor.

Double revolving field theory, Equivalent circuit, No load and blocked rotor tests, Starting Methods, Repulsion motor, Universal motor.

Synchronous machine :-

Alternator works on the principle of electromagnetic induction (cf. Faraday's law)

500 MW, 11 kV, 0.8 lagging

$$\sqrt{3} V_L I_L \cos \theta = 500 \times 10^6$$

$$\sqrt{3} \times 11000 \times I_L \times 0.8 = 500 \times 10^6$$

$$I_L = 32000 \text{ A}$$

Armature winding :- 11000 V, 32000 A, Insulated for (AC) high voltage.



Field winding :- DC 145V-200V, 1000A, Insulated for low voltage

Stationary field rotating armature

① Collecting large current through sliprings and brushes is very difficult practically

Rotating field stationary armature

① Since armature is stationary so, current can be collected by solid copper bars and it requires 2 sliprings for excitation purpose.



② Required large mechanical input to rotate bulk armature and does not offer high speed.

③ Providing insulation and coating to rotating armature is difficult.

④ Offer less space and demand high depth slot in armature. So, more leakage.

⑤ Result :-

① Modern

② Require lesser mechanical input to rotate small field winding so, offer high speed.

③ Providing insulation and coating is easy for stationary armature.

Offer more space & demand low depth slot in armature so, less leakage.

Result:-

- ① Modern alternator are designed with stationary armature & rotating field.
- ② High speed power generation:- 1800 RPM, 3000 RPM

Thermal, steam, gas, Nuclear, Turbo alternator.

- ③ Low speed power generation:- $< 750 \text{ R.P.M}$

Eg. Hydro power plant, Diesel power plant.

Stator Construction:- referred to I-M.


Stator contain 3- ϕ star connected, distributed winding with

Conductor:- Active length of wire which participate in

energy conversion known as a conductor.

Eg:- AB and CD are two conductor.

Turn:- One turn consist of two conductor
end connections/overhanging




1 Turn coil = 2 conductor

Coil $\div$ one coil consist of any number of turns

Coil side $\div$ A coil consist of 2 coil sides which are placed in two different slots. Here, WXYZ are two coil sides.


coil pitch $\div$ Centre to centre distance between two coil sides of a coil known as coil pitch or coil span (Y_c)




$$Y_c = \text{coil pitch} / \text{coil span}$$

Pole pitch $\div$ (Y_p) Centre to centre distance b/w two adjacent poles.

① $P = 2$




If conductor is at place show in above figure then




2 $\gamma_p \longrightarrow 360^\circ$ electrical
 1 $\gamma_p \longrightarrow 180^\circ$ electrical

② If $P = 4$



4 $\gamma_p \longrightarrow 720^\circ$ electrical
 1 $\gamma_p \longrightarrow 180^\circ$ electrical



$$\text{Pole pitch} = \gamma_p(n) = \frac{\text{total number of slots}}{\text{total no of poles}} = \boxed{n = \frac{S}{P}}$$

slot/pole

'n' slots are responsible for 180° electrical phase shift

$\rightarrow$ 1 pole pitch is always responsible for 180° electrical phase shift.

Eg ~~2 pole, 12 slots, 3~~

Eg $\rightarrow$ 2 pole, 12 slots, 3- ϕ Alternator

$P = 2, S = 12, \phi = 3$

$$n = \frac{S}{P} = \frac{12}{2} = 6$$



6 slots are responsible for 180° electrical phase shift.

⑦ Slots angle (β) :-

Phase difference contributed by 1 slot is known as slot angle β

$$\beta = \frac{180^\circ}{n} \text{ electrical}$$

$$\left\{ E_g = \frac{180^\circ}{6} = 30^\circ \text{ electrical} \right\}$$



Types of 3- ϕ winding:-

① Single layer and double layer winding:-

If 1 slot contains 1 coil side then it is known as single layer winding


Eg :- for 2 pole, 12 slot alternator.

6 coils requires for single layer winding.

Double layer :-


If 1 slot contains more than 1 coil side then it is known as double layer winding.

Eg :- 1 slot contains 2 coils side



This is done for a uniform flux distribution and for less harmonics

Eg: 7 slots containing 4 coil sides.



Result:- Generally double layer windings are preferred because easier to house the winding in slot, less leakage better emf waveform.

Short pitch and full pitch winding:-

full pitch:-

$$Y_c = Y_p$$



$$E_{net} = \sqrt{E^2 + E^2 + 2EE \cos(180)}$$


$$= \sqrt{2E^2 + 2E^2}$$

$$N_{net} = 2E$$

Short pitch:-

$$Y_c < Y_p$$

$$\Rightarrow Y_c = Y_p - \alpha = \pi - \alpha$$




$$Y_c = 4 \quad , \quad Y_p = 6$$

$$\frac{Y_c}{Y_p} = \alpha$$

α = angle by which coils are shorted
pitch

α = chording angle.



~~Net~~

$$E_{net} = \sqrt{E^2 + E^2 + 2E(-E) \cos(180 - \alpha)}$$

$$= \sqrt{2E^2 + 2E^2 \cos \alpha}$$

$$E_{net} = \cancel{\sqrt{2E^2 + 2E^2 \cos \alpha}} \quad 2E \cos \alpha / 2$$


$$E_{net} = 2E \cos \alpha / 2$$

$\cos \alpha / 2$ = pitch factor [coil span factor (K_p / K_c)]

$$K_p = \frac{\text{induced emf in short pitch}}{\text{induced emf in full pitch}}$$

$$K_p = \frac{2E \cos \alpha / 2}{2E}$$

$$K_p = \cos \alpha / 2$$




∴ Short pitch

$$0 < K_p < 1$$

Generally windings are short pitch by 1 or 2 slot angle

Result :- Generally short pitch windings are preferred because the length of end connections reduces, higher order harmonics can be eliminated lesser volume of copper required.

Harmonics reduction by short pitch winding :-



If fundamental is short pitch by angle (α) then the (r^{th}) order harmonics short pitch by angle $(r\alpha)$

pitch factor corresponding to r th order harmonics.

$$K_{pr} = \cos \left(\frac{r\alpha}{2} \right) \quad \# \#$$

If r th order harmonics are completely reduced then

$$K_{pr} = 0$$

$$\cos \left(\frac{r\alpha}{2} \right) = 0$$

$$\frac{r\alpha}{2} = \frac{\pi}{2}$$

$$r\alpha = \pi$$

$$\alpha = \frac{\pi}{r}$$

$$\alpha = \frac{\pi}{r}$$

$$\therefore (\gamma_c = \pi - \alpha)$$

$$\therefore \gamma_c = \pi - \frac{\pi}{r}$$

$$\# \# \left[\gamma_c = \pi \left(\frac{r-1}{r} \right) \right] \# \#$$

Concentrated and distributed windings :- (m)

Slots per pole per phase or phase group or phase belt or 'm'.

$$m = \frac{\text{slots per pole}}{\text{total no of pole/phase}}$$

$$m = \frac{n}{\text{phase}}$$

n = slots responsible for 180° displacement.

$$m = \frac{6}{3} = 2 \text{ slots per pole per phase}$$


let Z = total number of conductor

Z_{ph} = total no of cond^r per pole per phase.


$$\text{let } Z = 60$$

$$Z_{ph} = \frac{60}{2 \times 3} = 10$$

Concentrated



Distributed



⇒ If all the Z_{ph} conductors are placed in 1 slot keeping remaining 1 slot per pole per phase empty then winding is concentrated.

⇒ If all the Z_{ph} conductors are distributed uniformly in all the two slots per pole per phase available

then it is called as distributed windings.

→ Generally distributed windings are preferred because the waveform of induced emf is more sinusoidal.

Distribution factor / Breadth factor :- (K_d)

$$K_d = \frac{\text{Net induced emf in distributed winding}}{\text{Net induced emf in concentrated winding}}$$

$$K_d = \frac{\sin(m\beta)}{m \sin \frac{\beta}{2}}$$

for $K_d = 1$ 100% पाया
0% शेष

$\Rightarrow 0 < K_d < 1$ distributed

$\Rightarrow K_d = 0.7$ 70% पाया
20% शेष

for $K_d = 0$ 0% पाया
100% शेष

In alternators β is very small

therefore $\left[\sin \frac{\beta}{2} \approx \frac{\beta}{2} \right]$

$$K_d = \frac{2 \sin(m\beta)}{m\beta}$$

Case I :-

if 60° phase spread preferred.
 $\{m\beta = 60^\circ\}$

$$\left[(K_d)_{60} = \frac{2 \sin(60^\circ)}{\pi/3} = \frac{3}{\pi} \cdot 0.95 \right]$$

Case II:- of 120° phase spread.

$$(K_d)_{120} = \frac{\alpha \sin \frac{120^\circ}{2}}{2 \frac{\pi}{3}} = \frac{3\sqrt{3}}{2\pi} = 0.82$$

$$\therefore \frac{(K_d)_{120}}{(K_d)_{60}} = \frac{3\sqrt{3}\pi}{2\pi \times 3} = \frac{\sqrt{3}}{2}$$

$$(K_d)_{60} = 1.15 (K_d)_{120}$$

$\therefore$ Modern alternator are designed with 60° phase spread.

Reduction of harmonics by distributed windings:-

$$K_{dr} = \frac{\sin \left(\frac{mr\beta}{2} \right)}{2 \sin \left(\frac{r\beta}{2} \right)}$$

If r^{th} harmonics are completely removed

$$[K_{dr} = 0]$$

$$\frac{\sin \left(\frac{mr\beta}{2} \right)}{2 \sin \left(\frac{r\beta}{2} \right)} = 0$$

$$\sin \left(\frac{mr\beta}{2} \right) = 0$$

$$\frac{mr\beta}{2} = \pi$$

$$m \beta = \frac{2\pi}{r}$$

Note:- Winding factor (K_w)

$$K_p = 0.8$$

$$K_d = 0.7$$

$$K_w = K_d \cdot K_p$$

$$K_w = 0.8 \times 0.7$$

$$= 0.56 \rightarrow 44\% \text{ स्वीया}$$

↓
(due to distributed + short pitch)

$$E = 4.44 \phi_{\max} f N_1 = 100 \text{ V}$$

In a Transformer (concentrated

$$K_d = 1, K_w = 1$$

Emf equation of alternator:-

$$E_f = 4.44 \phi_f \cdot f T_{ph} K_w = 56 \text{ V}$$

E_f = induced emf per phase / Excitation emf

ϕ_f = Net flux in Air | main flux

f = frequency

T_{ph} = Turn per phase

$T_{ph} = K_w$

Effective No of turn

$E_f \propto \phi_f$ ————— $\nearrow$ excitation
is varied to change induced emf.

④ Fractional slot and integral slot winding :-

m = fractional slot $\rightarrow$ winding = fractional
 n = integral slot winding = integer

Slots per phase
 ||
 always integer

Eg = ① $12/2/3$ ————— Integral

② $16/4/3$ ————— X (not possible) $\because$ { Slots per phase is not integer }

③ $18/4/3$ ————— fractional

Rotor construction :-

According to construction there are two types of rotor :-

① Salient pole / Projected pole rotor :- ⑧

These rotors have concentrated field windings. So, not suitable for high speed and preferred for preferred for low speed power generation. So, used in hydra power plant.

$\Rightarrow$ These rotors have small axial length and large radial length.

⇒ These rotors have large number of poles.


⇒ Pole shoes are chamfered in shape to shape sinusoidal variation in air gap. So, flux becomes sinusoidal.

⇒ The air gap is non-uniform. So, reluctance power present in it.

⇒ Damper bars are present to reduce hunting in the slots on pole shoes which are short circuited by 2 end rings.

⇒ More windage loss.

⇒ In modern alternators both pole core and pole shoes are laminated.



Smooth cylindrical rotor: non salient pole rotor:

/ non projected pole rotor:-

⇒ Cylindrical rotor does not have any lamination and also its smooth surface will act as damper. So, no need of damper bar.


⇒ These rotors generally have two or four poles and field winding is distributed type. So, offer high speed and used in thermal, gas, nuclear, and turbo alternator.

⇒ For turbo alternators forged ^(वालेदार) is steel is used to make
rotors.

⇒ Since the air gap is uniform. So, no reluctance power int.


⇒ Less windage friction loss.

⇒ A These rotors have smaller diameter and large axial length.



Eg :-

P 244 - ①



$$N_{S1} = N_{S2}$$

$$\frac{120/p_1}{p_1} = \frac{120/p_2}{p_2}$$


$$\therefore \boxed{p_2 = 1.2 p_1}$$

p_1	p_2
2	2.4
4	4.8
6	7.2
8	9.6
10	12
20	24

$$p_1 = 10, p_2 = 12$$

$$N_{S1} = \frac{120 \times 60}{10} = 100 \text{ RPM } \square$$

Armature reaction :- (Case-1) Under No load condⁿ



$$\boxed{\Phi_{net} = \Phi_f}$$

Under no load condition $I_a = 0$, so, $\Phi_a = 0$, so, there is no armature reaction.


(Case-2) Under loaded condⁿ :-

⇒ As alternator loaded a current start flowing in all the three phases having mutual displacement of 120° . So, this produces an R.M.F which runs at synchronous speed known as armature flux.

⇒ Relative speed of main flux and armature flux is zero. so, their phasor sum is possible.

⇒ Armature flux will take an action on main flux

known as armature reaction.



$$\phi_{net} = \phi_f + \phi_a$$

Note :- for armature reaction analysis we always take ideal alternator.

$$\overline{E_f} = \overline{V_t}$$

$$E_t \angle \delta = V_t \angle 0^\circ$$

$$|E_f| = |V_t| \quad / \quad \delta = 0$$


(same phase) d/w

Case-I:- If load is pure inductive :- Ideal cases:-

I_a Lags V_t by angle 90° .

(3)

$$\phi_{net} = \phi_b - \phi_a$$




It shows demagnetising effect

$\Rightarrow$ As load connected, $\phi_{net} \downarrow$, $E_f \downarrow$, $(V_t)_{load} \downarrow$


$\Rightarrow V \cdot R = +ive$, to maintain $V_R = 0$. So, alternator is to be overexcited.

$\Rightarrow$ An overexcited alternator operate at lagging power factor

At no load



At load




Case-II If load is pure capacitive :-

I_a leads V_t by angle 90° .

$$\phi_{net} = \phi_b + \phi_a$$


Magnetising effect.




⇒ As load connected $\phi_{net} \uparrow$, $E_b \uparrow$, $(V_t)_{load}$
 ⇒ $V_R = -ive$, So, to maintain $(V_R = 0)$ alternator must be under excited

⇒ Under excited alternator operate at leading p.f.

No load



With Load




Case → III :- If load is pure Resistive :-

I_a is in phase with V_t


$$\phi_{net} = \sqrt{\phi_a^2 + \phi_b^2}$$

{ Cross magnetising effect }



$\Rightarrow$ As load connected, $\Phi_{net} \approx \text{constant}$, $E_f \approx \text{constant}$
 $\Rightarrow$ So, alternator is normally excited

Normally alternator operates at Unity power factor




Result :-

① Armature reaction effect depends on both $\frac{\text{load}}{(\text{magnetizing})}$ and nature of load (p.f.)

Load	Armature reaction
R-L	'cross' mag + De-mag
R-C	'cross' mag + Magnetizing

Equivalent circuit of alternator :-



X_{ar} = Armature reaction reactance (Fictitious) ^{काल्पनिक}
 parameter
 (or voltage drop due to drop in MMF)

R_a = Armature ~~voltage~~ resistance.

X_l = Leakage reactance

I_a = Rated / full load armature current

V_t = full load / Rated terminal voltage

By KVL

$$\boxed{\overline{E_f} = \overline{V_t} + \overline{I_a} R_a + j \overline{I_a} X_l + j \overline{I_a} X_{ar}} \quad \#$$

$\overline{E_f}$ (emf) $\overline{V_t}$ (emf) $\overline{I_a} R_a$ (emf) $j \overline{I_a} X_l$ (emf) $j \overline{I_a} X_{ar}$ (mmf)

$$\overline{E_f} = \overline{V_t} + \overline{I_a} R_a + j \overline{I_a} (X_l + X_{ar})$$

X_s = Synchronous reactance

$$\boxed{\overline{E_f} = \overline{V_t} + \overline{I_a} R_a + j \overline{I_a} X_s} \quad \#$$

$$\overline{E_f} = \overline{V_t} + \overline{I_a} \underbrace{(R_a + j X_s)}_{Z_s = \text{synth Impedance}}$$

$$\boxed{E_f = V_t + I_a \cdot Z_s}$$

$$Z_s = R_a + jX_s$$

$$Z_s = |Z_s| \angle \beta \quad \text{impedance angle}$$

$$|Z_s| = \sqrt{R_a^2 + X_s^2}$$

$$\boxed{\beta = \tan^{-1} \left(\frac{X_s}{R_a} \right)}$$

Result :- ~~Res~~

① $Z_s = R_a + jX_s$

$$\boxed{R_a \lll X_L \lll X_{ar}} \quad \# \#$$

$$R_a \lll X_s$$

$$\boxed{Z_s \approx jX_s}$$


if R_a is question में नहीं दिया हो then neglect it.

~~##~~ ② Here X_{ar} is a fictitious parameter whose value depends on a load and nature of load and it represent drop due to armature reaction.

Phasor diagram :-

I_a lags V_t by angle ' θ_z ' (p.f. angle, $\angle_{load}$)

$$\boxed{E_f = V_t + I_a R_a + jI_a X_s}$$



$$\psi = \theta_2 + \delta$$

angle b/w E_b and I_a
(internal ϕ angle)

$$V_R = \frac{|E_b| - |V_t| \cos \psi}{|V_t|} \times 100$$

$$|E_b| = OE$$

$$|OE| = \sqrt{(OB)^2 + (BE)^2}$$

$$= \sqrt{(OA + AB)^2 + (BC + CE)^2}$$

$$|OE| = \sqrt{(V_t \cos \theta_2 + I_a R_a)^2 + (V_t \sin \theta_2 + I_a X_s)^2}$$

$$\tan \psi = \tan (\theta_2 + \delta) = \frac{V_t \sin \theta_2 + I_a X_s}{V_t \cos \theta_2 + I_a R_a}$$

Result :-

$$E_f = \sqrt{(V_t \cos \theta_r + I_a R_a)^2 + (V_t \sin \theta_r \pm I_a X_s)^2}$$

lagging

$$\tan \phi = \tan(\theta_r \pm \delta) = \frac{V_t \sin \theta_r \pm I_a X_s}{V_t \cos \theta_r + I_a R_a}$$

lagging leading
leading leading

KVA rating of Alternator :-

A 10 KVA, 400 V, 50 Hz, $3-\phi$, Alternator

Full load / rated power O/P Rated / Full load terminal voltage (line value) output frequency.

$$S = \sqrt{3} V_L I_L$$

$$S = 3 V_t I_a$$

If any connection is not given in question then always take Δ connection

$$S = \sqrt{3} V_{tL} I_{aL}$$

$$\cos^{-1} 0.8 = 36.86^\circ$$

$$10K = \sqrt{3} \times 400 I_{aL}$$

$$I_{aL} = I_a = 14.43 A$$

3

Q A 10KVA, 400V, 50Hz, 3- ϕ alternator supply rated load, 0.8 p.f lagging. If armature resistance is 5Ω and synchronous reactance is 10Ω then the value of internal induced emf, voltage regulation, load angle? Take phase value because of equivalent circuit parameter.

Rated Load

$$\cos \theta = 0.8 \text{ Lagg}$$

$$R_a = 5\Omega, X_s = 10\Omega$$

$E_f, V.R, S$

$$V.R = \frac{|E_f| - |V_t|}{|V_t|} \times 100$$

$$V_{tL} = 400V$$

$$V_t = \frac{400}{\sqrt{3}} = 231V$$

of at full load

$$I_a = 14.43 A$$

$$E_f = \sqrt{(V_t \cos \phi_r + I_a R_a)^2 + (V_t \sin \phi_r + I_a X_s)^2}$$

$$E_f = \sqrt{(231 \times 0.8 + 14.43 \times 5)^2 + (231 \times 0.6 + 14.43 \times 10)^2}$$

$$E_f = 382 \text{ V}$$

$$\%R = \frac{382 - 231}{231} \times 100 = 65 \%$$

$$\tan(\theta_r + \delta) = \frac{V_t \sin \theta_r + I_a X_s}{V_t \cos \theta_r + I_a R_a}$$

$$\tan(\theta_r + \delta) = \frac{231 \times 0.6 + 14.43 \times 10}{231 \times 0.8 + 14.43 \times 5}$$

$$\theta_r = 36.86^\circ$$

$\cos^{-1} 0.8 = 36.86$


$$\delta = 18^\circ$$

Testing of alternator or determination of voltage regulation

Direct method :-

Direct methods can be applied only for small rating alternator and also load is directly connected so, it gives accurate results.

⇒ For high capacity alternators that much full load cannot ~~be~~ directly connected to the alternator - so, direct method cannot be used for high rating alternator.



$$V.R = \frac{|E_f| - |V_t|}{|V_t|} \times 100$$

II Indirect method :-

① Synchronous Impedance method / emf method / Pessimistic :-


$$E_f = \sqrt{(V_t \cos \theta_a + I_a R_a)^2 + (V_t \sin \theta_a + I_a X_s)^2}$$

By D.C test

D.C test
S.C Test

$$\text{D.C Test} = \boxed{R_{ac} = (1.2 \text{ to } 1.3) R_{dc}}$$

② Open ckt test (oc test)



open ckt test conducted to Draw open ckt characteristics (O.C.C)

O.C.C E_b V/F I_f

$$E_b = 4.44 \phi_f \cdot f \cdot T_{pn} \cdot k_w$$

$$E_b \propto \phi_f \rightarrow \text{Linear}$$


$$\phi_f = \frac{N I_f}{R_e}$$

$$\phi_f \propto I_f$$


(w/o saturation)
Non magnetic (Air)
(Linear)

$$E_b \propto I_f$$

Magnetic material (core)
Non linear
(B-H curve)
(with saturation)



Short ckt test :- (S.C test)



Short ckt test conducted to draw S.C characteristics (S.C.C)

S.C.C Ia V/s If

$$I_a = \frac{E_f}{\sqrt{R_a^2 + X_s^2}}$$


$$\Rightarrow \begin{aligned} I_a &\propto E_f \\ E_f &\propto \phi_f \end{aligned}$$

$I_f \propto \phi$
 $\phi \propto I_f$

$\{I_a \propto I_f\}$

$\therefore$ only 5% of rated I_f is taken
 so core not get saturated

linear




Result :-

(1) Under S.C condition only 5% of rated I_f is sufficient to circulate rated current in the armature under short circuit condition. So, the core is not saturate and S.C.C is a linear character-
 -ristics

(2) Since S.C.C is ^{a line} ~~align~~, passing through origin

So, only one reading is sufficient to draw S.C.

③ Under short circuit condition the power factor of alternator is almost 0 lagging.



$$R_a \lll X_s$$

$$\beta = \tan^{-1} \left(\frac{X_s}{R_a} \right)$$

$$\theta_{sc} = \tan^{-1} \left(\frac{X_s}{R_a} \right)$$

$$\theta_{sc} \approx -\pi/2$$

$$\cos \theta_{sc} = 0 \text{ lagging}$$


$$I_a \angle \theta_{sc} = \frac{E_f \angle 0^\circ}{|Z_s| \angle \beta}$$

$$R_a = 0.1 \text{ pu}$$

$$X_s = 1 \text{ pu}$$

So lagging

Determination of Z_s from OFC and SCC :-




By KVL

$$Z_s = \frac{(V_t)_{oc}}{I_{asc}} \quad | \quad I_f = \text{const}$$

$$Z_s = \sqrt{R_a^2 + X_s^2}$$

$\swarrow$ Kn $\swarrow$ DC Test $\swarrow$ cal



$$Z_s(\text{sat}) < (Z_s)_{\text{unsat}}$$

$\therefore$ after sat $V \approx \text{const}$

$$\therefore \boxed{Z_s \propto \frac{1}{I_{\text{asc}}}} \quad \therefore Z_s \downarrow$$

Result :-

① In this method all the quantities are assumed to be emf quantity and the value of obtained of regulation are more than actual. So, it is known as pessimistic method.

② The value of Z_s is different for different / different field current

Ques:- A star connected 400 V 50 Hz 4-pole synchronous machine gives following test results

S.C Test $\rightarrow$ 10 A, $I_f = 1.5$ A.

O.C Test $\rightarrow$ 400 V, $I_f = 2.3$ A

Find the Z_s for rated voltage?

As

$$Z_s = \frac{V_{t oc}}{I_{asc}} \quad | \quad g_f = 2.3 A$$

$$Z_s = \frac{400}{\sqrt{3} \times 15.33 A}$$

$$Z_s = 15.06 \Omega \quad R$$


S.C ~~is~~ is Linear

$$\therefore \frac{10}{I_{asc}} = \frac{1.8}{2.3}$$

$$I_{asc} = 15.33 A$$

Short circuit ratio (S.C.R) :-

$$(P_{o max}) = \frac{E_b V_t}{Z_s} - \frac{V_t^2 R_a}{Z_s^2}$$



$$SCR = \frac{\text{field current required to produce rated voltage at o.c.}}{\text{field current required to produce rated current at s.c.}}$$

$$SCR = \frac{OA}{OD}$$

$$\therefore \triangle ODE \approx \triangle OAB \quad (Z_s)_{\text{sat}}(\Omega) = \frac{V_{t oc}}{I_{asc}} \quad \left| \quad I_f = OA \right.$$

$$\therefore \frac{OD}{OA} = \frac{DE}{AB}$$

$$\Rightarrow \frac{I_a}{AB} = \frac{1}{SCR}$$

$$(Z_s)_{\text{sat}}(\Omega) = \frac{V_t}{AB}$$

$$(Z_s)_{\text{Base}}(\Omega) = \frac{V_{\text{rated}}}{I_{\text{rated}}} = \frac{V_t}{I_a}$$

$$(Z_s)_{\text{sat}}(\text{PU}) = \frac{(Z_s)_{\text{sat}}(\Omega)}{(Z_s)_{\text{Base}}(\Omega)}$$

$$= \frac{(Z_s)_{\text{sat}}(\Omega)}{(Z_s)_{\text{Base}}(\Omega)}$$

$$(Z_s)_{\text{sat}}(\text{P.U.}) = \frac{V_t}{AB} \times \frac{I_a}{V_t} = \frac{I_a}{AB}$$

$$\triangle ODE \approx \triangle OAB$$

$$\frac{OD}{OA} = \frac{DE}{AB}$$

$$\frac{I_a}{AB} = \frac{1}{SCR}$$

$$(Z_s)_{sat} (P.U) = \frac{1}{SCR}$$

$$SCR = \frac{1}{(Z_s)_{sat} (P.U)} \quad \text{|| ||}$$

$$SCR = \frac{1}{(Z_s)_{adjusted} (P.U)}$$

∴ for modern alternator

$$Z_{s sat} (P.U) = X_s (sat) P.U$$

$$SCR = \frac{1}{(X_s)_{sat} (P.U)}$$

$$SCR \propto \frac{1}{X} \propto \frac{1}{L} \propto R_e \propto \text{Air gap}$$

$$SCR \propto \text{air gap}$$

Case → I High SCR :-

$X \downarrow$, Air gap $\uparrow$

② $X \downarrow$, Voltage drop $\downarrow$, $V.R \downarrow$, Better voltage regulation.

③ $I_{sc} \propto \frac{1}{\sqrt{R^2 + X^2}}$, High S.C current

④ Stability $\propto \frac{1}{X \downarrow}$, more stable

Case $\rightarrow$ II Low SCR $\rightarrow$ $X \uparrow$, Air gap $\downarrow$

- ① $X \uparrow$, Voltage drop $\uparrow$, V.R $\uparrow$, poor Voltage regulation.
- ② $\downarrow I_{sc} \propto \frac{1}{X \uparrow}$, Low short circuit current.
- ③ $\downarrow \text{stability} \propto \frac{1}{X \uparrow}$, less stability.

Result :-

- ① Modern alternators are designed with high S-C.R.
Typical value of SCR = 5

Cylindrical : 0.5 to 0.9 } So, Salient pole motor
Salient : 1 to 1.5 } is more stable.

② Re Heun's method / MMF method / ATs method /
optimistic (अपेक्षावादी)

$\rightarrow$ In this method all the quantities are assumed to be MMF quantity. So, it is known as MMF method and obtained value of regulation are less than actual. So, it is known as optimistic method.

$\rightarrow$ In this method MMF required to produce rated induced Emf E_f having two components (fnet)
The first component is MMF required to produce

rated terminal voltage V_t under open circuit condition (f_o).


Another component is MMF required to compensate all the drops under short circuit condition (f_{sc}).

$$\overline{E_f} = \overline{V_t} + \overline{I_a \overline{Z_s}}$$

$$E_f \propto \phi_f \propto NI_f \propto \text{MMF} \propto f_{\text{net}}$$

$$\boxed{f_{\text{net}} = f_o + f_{sc}}$$

$$\boxed{V.R = \frac{|E_f| - |V_t|}{|V_t|} \times 100 = \frac{|f_{\text{net}}| - |f_o|}{|f_o|} \times 100}$$





③

Potier triangle method / Zero power factor characteristics method (ZPFC) :-

Potier separated all the drops according to their nature. So, this method gives more accurate results. In this method two operating characteristics required.

② Zero power factor char (ZPFC) V_t V_s I_f , $I_a = \text{constant (Rated)}$





or
current at which $V_t = 0$
and $I_a = \text{rated}$

$$Q P = O A$$

parallel
parallel to $N I_f$

or
now draw $Q R$ parallel to air gap line
join $R P$

$l(PQ) = l(OA) = \text{mmf required to compensate } 'X_a' \text{ Drop}$

$\therefore (I_a V_{ta}) \text{ emf} = l(RS) = \text{emf required to compensate } (X_L)$

$l(QS) = \text{mmf required to compensate } X_L \text{ Drop}$

$l(RS) = \text{emf drop due to } (X_s)$

$e(ST) = \text{emf drop due to } (AR)$

$l(PS) = \text{mmf drop due to } (AR)$

$$\boxed{P_{\max} = \frac{E_f V_t}{Z_s} - \frac{V_t^2 R_a}{Z_s}}$$

$$V_{ph} = \frac{V_t}{\sqrt{3}} = \frac{17.32 \times 10^3}{\sqrt{3}} = 10 \times 10^3 = 10 \text{ kV}$$

$$= \frac{10 \times 10^3 \times 10 \times 10^3}{9}$$

$$P_{\max \text{ per phase}} = \frac{4 \times 10^7}{3}$$

$$\boxed{\text{for 3 phase} = 39 \text{ or } 40 \times 10^6} \quad \approx$$

where $E_f = 12 \text{ kV}$, $V_t = 17.32 \text{ kV}$, $Z_s = 9 \Omega$, $R_a = 0.1 \Omega$, $P_{MVA} = 30 \text{ MVA}$,

→ The positive, negative and zero sequence impedances of 3- ϕ synchronous generator are $j \cdot 5 \text{ p.u.}$, $j \cdot 3 \text{ p.u.}$, and $j \cdot 2 \text{ p.u.}$ respectively. When symmetrical fault occurs on the machine terminals. Find the fault current. The generator neutral is grounded through reactance of 0.1 p.u.

$$\therefore \boxed{I_F = \frac{1 \angle 0^\circ}{j(5 + 3 + 2 + 0.1)} = -j 1.67 \text{ p.u.}}$$

Final

Two reactance theory for salient pole rotor :-

d-axis direct axis - N-S pole

q axis 90° electrical to d-axis.


In case of cylindrical rotor alternator air gap is uniform
 So main field flux and armature flux are sinusoidal in
 nature. But in case of ~~cylindrical~~ salient pole rotor alternator
 the length of air gap is different for different ~~different~~
 both d-axis & q-axis. So, reluctance also different.

So, the theory which gives the disturbing behaviour of
 salient pole rotor known as two reactance theory.

⇒ Along direct axis armature reaction effect is demagnetising
 or magnetising. But along q-axis it is ~~tan~~ always
 cross magnetising.

(d-axis) direct / polar axis :-

d-axis $[X_d = X_{ad} + X_L = X_s]$




X_q
 ||
 $X_{aq} + X_L$
 ||
 X_s

quadrature /
 indirect / inter polar
 axis
 (q-axis)

$[X_d = X_q = X_s]$

$[X_d - X_q]$
 ||
 0
 (crossed)

Salient pole Rotor :-





$$X \propto L \propto \frac{N^2}{S} \propto \frac{1}{\text{Air gap}}$$

$\# \# \boxed{X_d > X_q} \# \#$

Synchronous reactance along d-axis
 Synchronous reactance along q-axis

$$\boxed{X_d - X_q \neq 0} \quad (\text{Salient})$$

Armature reactance direct axis > Armature reactance q-axis
 (less airgap) (more airgap)




3- ϕ synchronous motor :- ⑤


→ Synchronous machines are popular for megawatt loading (alternator) and for low speed (synchronous motor).

⇒ From no-load to full-load its speed remains constant. So, its speed regulation is zero.


⇒ Stator of 3- ϕ synchronous motor is similar to 3- ϕ alternator contains 3- ϕ star connected distributed windings. But the rotor must be salient pole.



⇒ Synchronous motor works on the principle of magnetic locking b/w two opposite poles.



Since, the average torque experience by the rotor in 1 cycle becomes zero. So, 3- ϕ Synchronous motor are not self starting in nature.



Procedure to start 3- ϕ synchronous motor:-

→ First connect the stator to the 3- ϕ supply without exciting its field winding. So, stator R.M.F. is produced. Now rotate the motor by external device in the direction of R.M.F. near to N_s during starting. & the field winding is short circuited with a low resistance to avoid damage of insulation.

→ Now the field winding is connected to D.C supply. So, rotor poles forms and rotor poles gets magnetically locked with stator poles and rotor start rotation at N_s . As the motor start external device decoupled.


Methods for starting of 3- ϕ synchronous motor:-

① By using auxillary motor:- If auxillary motor is induction motor the supply to this motor disconnected after starting the motor but if it is a D.C motor. The same motor can be used as excitor of synchronous motor.

$\frac{1}{N_s}$
 $\frac{1}{N_s}$

⇒ Pony motor is a small induction motor ~~which~~ which having poles

$$P_{\text{pony}} = P_{\text{syn}} - 2$$




at
 $P_{\text{syn}} = 10$

$$P_{\text{pony}} = 8$$


② By using damper bar :-

It is induction start synchronous run method. But having disadvantage of low starting torque. In this method motor start as SCIM.




Starting as slip ring induction motor :

It is also induction start synchronous run method and motor can start with high starting torque.



Equivalent ckt of synchronous motor:-



KVL $\boxed{\overline{V_t} = \overline{E_b} + \overline{I_a} R_a + j \overline{I_a} X_s}$ $\rightarrow$ Numericals

phasor
law

$\boxed{\overline{V_t} = -\overline{E_b} + \overline{I_a} R_a + j \overline{I_a} X_s}$

$\boxed{E_b = 4.44 \phi_b \cdot f T_{ph} \cdot K_w}$

$\boxed{\overline{I_a} = \frac{\overline{V_t} + \overline{E_b}}{Z_s} = \frac{\overline{E_R}}{\overline{Z_s}}$

$\overline{E_R} = \overline{V_t} + \overline{E_b}$
 $\downarrow$
 Net / Resultant emf

Let E_R reference $\angle 0^\circ$

$\overline{E_R} = E_R \angle 0^\circ$

$Z_s = X_s \angle 90^\circ = 0 + j X_s$


$\boxed{\overline{I_a} = \frac{E_R \angle 0^\circ}{X_s \angle 90^\circ}} = \frac{E_R \angle -90^\circ}{X_s}$

from above I_a lags E_b by approx 90° .

Am Armature reaction in sy analysis :-

for armature reaction analysis we take ideal machine.


$$\overline{V_t} = -\overline{E_b}$$



$\Rightarrow$ Armature reaction effect is cross magnetising and the motor is normally excited.

Case-II :- If synchronous motor is operate at zero lagging p.f. :-


I_a lags V_t by angle 90°



Armature reaction effect is magnetising and motor is under excited.

Case-III :- If synchronous motor is operates at zero leading p.f.

I_a leads V_t by angle 90° .



Armature reaction is demagnetising and motor is over excited

Result :-

- ① Normally excited synchronous motor operate at unity power factor and armature reaction effect is cross magnetising in nature.

Ideal synchronous motor :-


$$\boxed{V_t = E_b}$$

$$V_t < 0 = E_b \angle -\delta$$

$$\boxed{|V_t| = |E_b|} \quad \boxed{\delta = 0}$$


$$\boxed{I_{a0} = 0}$$

No load armature current.



- ⇒ If rotor pole axis is ahead then stator pole axis then generator
- ⇒ If stator pole axis is ahead then R.P.A then motor.
- ⇒ consider for ideal case of locking.

Practical Synchronous motor at no-load:-



By KVL :-

$$V_t = E_b + I_a R_a + j I_a X_s$$

$V_t \angle 0^\circ$ for phasor diagram :-


$$\overline{V_t} = -\overline{E_b} + \overline{I_a} R_a + j \overline{I_a} X_s$$

$$\overline{I_a} = \frac{\overline{V_t} + \overline{E_b}}{Z_s} = \frac{\overline{E_r}}{Z_s}$$

If $R_a \approx 0$

$$\overline{I_a} = \frac{\overline{E_r} \angle -90^\circ}{X_s}$$

I_a lags E_r by angle 90°




If $E_b = \text{constant}$ & Load $\uparrow$, then $T_e \uparrow$,
 $(E_b) = \text{const}$

(81)


$$P = 3 V_t I_a \cos \theta_r = \text{constant}$$

$$I_a \propto \frac{1}{\cos \theta_2}$$

~~$$T_e = \frac{3 E_b V_t \cos \delta}{x_s}$$~~




As Load $\uparrow$ I_a becomes lag according to excitation




V-curve :-

I_a v/s I_b



Inverted V-curve :-



Synchronous condenser:-

- ① It is an over-excited synchronous motor used for power factor correction at ~~some~~^{sub} station and industrial load, transmission line.
- ② It is an over-excited synchronous motor which generally operates at no-load and made without any shaft extension.
- ③ A 3- ϕ induction motor draw 1000 kVA at the p.f. of .8 lagging. A synchronous condenser is connected in parallel to draw an additional 750 kVA at .6 p.f. leading. The power factor of the total load supplied by the mains is

$$S_L = S_i + S_c$$

$$S_i = P_i + jQ_i$$

$$P_i = S_i \cos \phi_i = 1000 \times .8 = 800 \text{ kW}$$

$$Q_i = S_i \sin \phi_i = 1000 \times .6 = 600 \text{ KVar}$$

$$S_i = 800 \text{ KW} + j 600 \text{ KVAR}$$

$$S_s = P_s + j Q_s$$

$$P_s = S_s \cos \phi_s = 750 \times 0.6 = 450 \text{ KW}$$

$$Q_s = S_s \sin \phi_s = 750 \times 0.8 = 600 \text{ KVAR}$$


$$S_s = 450 \text{ KW} - j 600 \text{ KVAR}$$

$$S_L = S_i + S_s$$

$$S_L = 1250 \text{ KW} + 0$$

$$\tan \phi_L = 0^\circ$$

$$\therefore \cos \phi_L = 1 \quad \text{O.P.F}$$



Single phase synchronous motor :-


Stator of a single phase synchronous motor is similar to single phase induction motor split phase type and according to rotor construction these motors can be classified into two types.

① Reluctance motor :-

① Reluctance motor works according to reluctance principle and due to reluctance power rotor get locked with stator ~~rotor~~ pole and motor runs at N_s .


② Reluctance motor does not have any field winding on rotor. So, damper bar start it as an induction SCIM near to N_s and due to reluctance power it runs at N_s .

③ Before rotor gets locked there is an induction torque but after locking it becomes zero and only reluctance torque is present.



$$T_{rel} \propto \sin(2\delta)$$

R_l - reluctance



Result:-

- ① Due to non uniform air gap reluctance motor runs with vibration and noise.
- ② If in a salient pole synchronous motor excitation is made zero under normal running condition it will continue to run at synchronous speed as a reluctance motor.

① In a cylindrical rotor synchronous motor excitation is made zero and if

if field winding is O.C :- speed '0'



if field winding is S.C :- Runs at slip ring induction motor ($N_r < N_s$)

Hysteresis motor :-

① The rotor is smooth cylindrical made by hard magnetic material.

② Initially rotor starts rotation due to combined effect of hysteresis torque and torque due to eddy current. But under running condition once the rotor gets locked the torque due to eddy current becomes zero and only hysteresis torque is present.

③ Due to uniform air gap its operation is silent so it is ~~not~~ used in sound producing instrument such as gramophone recorder, recording theater, compact disk drive.



Residual flux = $\phi_r \uparrow \uparrow$


Co-ercive force = $H_c \uparrow \uparrow$

High retentivity

Hunting :-

- A synchronous machine operate effectively if mechanical speed of the rotor is equal to synchronous speed.
- If a synchronous machine is loaded suddenly or due to disturbance the rotor starts acceleration and deceleration and the speed of the rotor becomes more or less than synchronous speed this is known as hunting.

$$T_{er} = \frac{3 E_b V_t}{X_s} \sin \delta$$



$$T_{\text{accelerating}} = T_{\text{em}} - T_{\text{load}}$$

Let

$$T_e = 10 \text{ N-m} = T_L \text{ at } N_s$$

and

$$T_L = 5 \text{ N-m applied.}$$

$T_L \therefore T_{\text{acc}} = -\text{ive}$, Deaccelerating, $N_s \downarrow$, $\delta \uparrow$, $T_e \uparrow$

when $T_e > T_L$, $T_{\text{acc}} = +\text{ive}$, accelerating, $N_r \uparrow$, $\delta \downarrow$, $T_e \downarrow$

again $T_e < T_L$

Causes of hunting :-

- ① Sudden change in load, sudden change in supply, sudden change in field system

Methods to reduce hunting :-

- ① By using damper winding, by using fly wheels, by designing the machine with high synchronising power coefficient.


$$\left. \begin{array}{l} N_r = N_s, \text{ 0 torque in damper is Bar} \\ N_r > N_s, \text{ Induction generating torque} \\ N_r < N_s, \text{ Induction motor torque.} \end{array} \right\}$$

Power flow equation of alternator :-

Case -> 1


Salient pole motor alternator :-

Alternator at no load



No energy conversion no
opposition

Alternator at load



-ive torque comes which opposes

Active power :- (P_g)

$$P_g = \underbrace{\frac{3E_f V_t \sin \delta}{X_d}}_{P_{em}} + \underbrace{\frac{3V_t^2}{2} \left[\frac{X_d - X_q}{X_d \cdot X_q} \right] \sin(2\delta)}_{P_{rel}}$$

P_{em}
electromagnetic
power

P_{rel} reluctance power = P_{rel}

$$\therefore P = T \omega_s$$

$$\therefore T_e = \frac{3 E_f V_t \sin \delta}{\omega_s X_d}$$

Electromagnetic torque

$$I_{rel} = \frac{3 V_t^2}{2 \omega_s} \left[\frac{X_d - X_q}{X_d \cdot X_q} \right] \sin(2\delta)$$

Reluctance torque.

Result:-

$\Rightarrow$ Reluctance power is present because armature flux having a tendency to pass through field structure along its minimum reluctance and this is present due to difference in reluctance along direct and quadrature axis. So, it is called as a reluctance power or power due to ~~re~~ saliency.

(B) Res Reactive power:-

$$Q_g = \frac{3 E_f V_t \cos \delta}{X_d} - \frac{3 V_t^2}{2} \left[\left(\frac{1}{X_d} + \frac{1}{X_q} \right) + \left(\frac{1}{X_d} - \frac{1}{X_q} \right) \cos 2\delta \right]$$

② Cylindrical Rotor alternator:-
Active Power :-

$$P_g = \frac{3 E_f V_t}{X_d} \sin \delta + \frac{3 V_t^2}{2} \left(\frac{X_d - X_q}{X_d X_q} \right) \sin 2\delta$$

Salient

symmetrical

$$\therefore X_d = X_q = X_s$$

Reluctance power = 0

$$P_g = \frac{3 E_f V_t \sin \delta}{X_s}$$

electromagnetic power

$$\therefore T_e = \frac{3 E_f V_t \sin \delta}{\omega_s X_s}$$

$T_e = T_L$ as load $\uparrow$, $(T_L \uparrow) = T_e \uparrow$, $\sin \delta \uparrow$, $\delta \uparrow$

Excitation = const

load / torque angle

$$\begin{aligned} \therefore E_f &= \text{const} \\ V_t &= \text{const} \\ f &= \text{const} \\ X_s &= \text{const} \\ \omega_s &= \text{const} \end{aligned}$$

Reactive power :-

$$Q_g = \frac{3 E_f V_t \cos \delta}{X_d} - \frac{3 V_t^2}{2} \left[\left(\frac{1}{X_d} + \frac{1}{X_q} \right) + \left(\frac{1}{X_q} - \frac{1}{X_d} \right) \cos 2\delta \right]$$

put $X_d = X_q = X_s$


$$Q_g = \frac{3 E_f V_t}{X_s} \cos \delta - \frac{3 V_t^2}{3} \left[\frac{1}{X_s} + \frac{1}{X_s} \right]$$

$$Q_g = \frac{3 V_t}{X_s} (E_f \cos \delta - V_t)$$

Power flow equations of synchronous motor :-

P_g $\longrightarrow$

Motor	+
Generator	to Motor
P_g	$-P_g$
Q_g	$-Q_g$
V_t	V_t
I_a	$-I_a$
E_b	E_b
δ	$-\delta$



① Cylindrical rotor syn-motor :-

① Active power (P_m)

$$P_g = \frac{3 E_f V_t \sin \delta}{X_s}$$

$$P_m = +P_g = - \frac{3 E_b V_t \sin (-\delta)}{X_s}$$

$$P_m = \frac{3 E_b V_t \sin \delta}{X_s}$$

② Reactive power :-
 Q_m

$$Q_g = \frac{3 V_t}{X_s} (E_f \cos \delta - V_t)$$

$$Q_m = - \left\{ \frac{3 V_t}{X_s} [E_b \cos (-\delta) - V_t] \right\}$$

$$Q_m = - \frac{3 V_t}{X_s} (E_b \cos \delta - V_t)$$

$Q_m = +ve \rightarrow$ absorb

$Q_m = -ve \rightarrow$ deliver

Salient pole synchronous motor :-

Active power (P_m) :-

$$P_g = \frac{3 E_b V_t}{X_d} \sin \delta + \frac{3}{2} V_t^2 \left[\frac{X_d - X_q}{X_d \cdot X_q} \right] \sin(2\delta)$$

$$P_m = - \left\{ \frac{3 E_b V_t \sin(-\delta)}{X_d} + \frac{3 V_t^2}{2} \left(\frac{X_d - X_q}{X_d \cdot X_q} \right) \sin(-2\delta) \right\}$$


$$P_m = \frac{3 E_b V_t \sin \delta}{X_d} + \frac{3 V_t^2}{2} \left(\frac{X_d - X_q}{X_d \cdot X_q} \right) \sin 2\delta$$

Reactive power (Q_m) :-

$$Q_g = \frac{3 E_b V_t}{X_d} \cos \delta - \frac{3 V_t^2}{2} \left[\left(\frac{1}{X_d} + \frac{1}{X_q} \right) + \left(\frac{1}{X_d} - \frac{1}{X_q} \right) \cos 2\delta \right]$$

$$Q_m = - \left\{ \frac{3 E_b V_t}{X_d} \cos \delta - \frac{3 V_t^2}{2} \left[\left[\frac{1}{X_d} + \frac{1}{X_q} \right] + \left(\frac{1}{X_d} - \frac{1}{X_q} \right) \cos 2\delta \right] \right\}$$

Power angle characteristics :-




$$P_m = \frac{3 E_b V_t}{X_d} \sin \delta$$

$$I_{ter} = \frac{P_m}{W_s} = \frac{3 E_b V_t \sin \delta}{\omega_s \cdot X_s}$$

For Excitation = const


$$I_{ter} \propto \sin \delta$$



Steady state stability limit obtained at $\delta = \pi/2$
 after this alternator fails to rotate
 for nonsalient pole stability limit
 ($60^\circ - 90^\circ$)


Q Salient pole syn m/c :-

$$P_{mech} = \frac{3E_b V_t}{X_d} \sin \delta + \frac{3V_t^2}{2} \left(\frac{X_d - X_q}{X_d \cdot X_q} \right) \sin(2\delta)$$



⇒ Due to reluctance power in net power angle characteristics gets distort and steady state ~~st~~ stability limit obtained at ' δ ' less than 90° .

Synchronising power coefficient :- $\frac{\text{stability factor}}{\text{factor of rigidity}}$




$$P_g = \frac{3E_f V_t}{X_s} \sin \delta$$

$$\boxed{\frac{dP_g}{d\delta} = \frac{3E_f V_t \cos \delta}{X_s} = P_{sy}}$$

$$P_{sy} = \frac{dP_g}{d\delta} = \frac{3E_f V_t \cos \delta}{X_s}$$

- # The machine is stable if P_{sy} is +ve.
- # Stability $\propto P_{sy}$
- # Stability $\propto E_f \phi_f \propto$ Excitation

Q Which operating pt is more stable?



B is more stable.

More excited machine is more stable

By keeping mechanical input constant or load is constant then and excitation change

Alternator :- { Excitation = variable, Mechanical I/P = const }

$$3V_t I_a \cos \theta_2 = \text{const}$$

$$I_a \propto \frac{1}{\cos \theta_2}$$

$$P_g = \text{const}$$

$$\frac{3E_f V_t \sin \delta}{X_s} = \text{const}$$

$$\sin \delta \propto \frac{1}{E_f}$$

→ If alternator is normally excited operate at unity power factor, $I_a \rightarrow$ minimum and armature reaction effect is 'cross magnetising'.

→ Excitation ↓, alternator is under excited operate @ leading p.f., $P_f \downarrow$, $I_a \uparrow$ and armature reaction effect is magnetising, $E_f \downarrow$, $\sin \delta \uparrow$, $\delta \uparrow$.

→ Excitation ↑, alternator is overexcited operated at lagging p.f., $I_a \uparrow$, armature reaction effect is demagnetising, $E_f \uparrow$, $\sin \delta \downarrow$, $\delta \downarrow$.

Synchronous motor :- { Excitation = variable, Mechanical load = const }

$$3V_t I_a \cos \theta_2 = \text{const}$$

$$I_a \propto \frac{1}{\cos \theta_2}$$

$$P_m = \text{const}$$

$$\frac{3E_b V_t \sin \delta}{X_s} = \text{const}$$

$$\sin \delta \propto \frac{1}{E_b}$$

- If motor is normally excited operate at unity power factor, $I_a \rightarrow$ minimum, and armature reaction is cross magnetising.
- Excitation $\downarrow$, under excited, operate at lagging p.f., $P_f \downarrow$, $I_a \uparrow$, $E_b \downarrow$, $\delta \uparrow$. armature reaction is magnetising.
- Exc1, over excited, operate @ lead p.f., $P_f \downarrow$, $I_a \uparrow$, $E_b \uparrow$, $\delta \downarrow$, AR effect demagnetising.

Parallel operation of alternator :-

⇒ A stationary alternator should not be connected directly to a live busbar otherwise the alternator gets damaged.


⇒ When two alternators are operating in parallel and if power I/P to one of the alternator fail then it will continue to run in the same direction at synchronous speed.

Necessary condition for parallel operation :-

① The terminal voltage of incoming alternator must be same as bus voltage it can be verified by a voltmeter.

② Frequency should be same as bus frequency and also same phase sequence. It can be verified



③ by lamp method or ~~synchronoscope~~ synchroscope.



Synchronising power :-

Perfectly synchronised :-


- It is inherent property of alternator when they operate in synchronism. Synchronism due to a disturbance resultant voltage E_r produces a circulating current known as synchronising current which produces a synchronising torque and synchronising power.
- The synchronising power comes into picture when steady state operating conditions are disturbed (either angle b/w E_1 and E_2 changes or magnitude of E_1 & E_2 changes)
- Once steady state reach the synchronising becomes zero and it is transient in nature.



$$V_t < 0^\circ$$

$$\overline{E_1} = \overline{E_2}$$

No synchronized power



$$\boxed{E_R \text{ (difference of } E_1 \text{ and } E_2) = 0}$$

$$\boxed{\overline{I_{sy}} = \frac{\overline{E_R}}{R + jX_s}}$$

$$\boxed{\overline{I_{sy}} = 0}$$

$$\left\{ \overline{I_{sy}} \cdot \overline{E_R} = 0 \right\}$$


Q. If excitation of machine 1 increased then its voltage increase. Therefore a synchronising current will develop in b/w alternator and lags E_1 by 90° . So, machine 1 operate at 0 power factor lagging and the armature reaction effect is purely demagnetising.

⇒ Synchronising current leads E_2 by 90° therefore machine 2 operate at zero p.f leading and armature reaction effect is purely magnetising.

⇒ If the excitation of 1 machine is increased the synchronous power comes into picture and it demagnetise the one machine whose excitation is increased and magnetise the other machine. So, that terminal voltage equalized.

⇒ If the excitation of one machine is increased then ^{7.62} synchronising power is reactive in nature. So, for reactive

power can be controlled by controlling excitation




$$|E_1| > |E_2|$$

$$E_R = E_1 - E_2$$

$$\overline{I_c} = \overline{I_{sy}} = \frac{E_R \angle 0^\circ}{2X_s \angle 90^\circ}$$

$$= \frac{E_R \angle -90^\circ}{2X_s}$$

I_{sy} lags 90° w.r.t E_R



$$I_{sy} = \frac{(E_1 - E_2) \angle -90^\circ}{2X_s}$$


$$Q_{sx} = E_R I_{sy} \sin(90^\circ)$$

$$Q_{sy} = \frac{(E_1 - E_2)^2}{2X_s}$$

Case → 2 :- Two alternators running in parallel at no-load and effect of change in steam input



① If steam input of one machine is increased the synchronising power will come into picture which is active power with respect to synchronising power. Machine one behaves as generator and machine two behaves as motor therefore the synchronising torque decelerate the first machine (generating machine) and accelerate the second machine (motoring machine).

② Since synchronising power is active in nature, so, active power can be changed by changing mechanical input.



$$I_{sy} = \frac{E_R \angle 0^\circ}{2V_s \angle 90^\circ}$$

$$|E_1| = |E_2| = E$$



$$E_R = \sqrt{E^2 + E^2 + 2E \cdot E \cos [180^\circ - \Delta\delta]}$$

$$= \sqrt{2E^2 + 2E^2 \cos (180^\circ - \Delta\delta)}$$

$$= \sqrt{2E^2 (1 - \cos \Delta\delta)}$$

$$= \sqrt{2E^2 \left\{ 1 - \left(1 - 2\sin^2 \frac{\Delta\delta}{2} \right) \right\}}$$

$$= \sqrt{4E^2 \sin^2 \frac{\Delta\delta}{2}}$$

$$E_R = 2E \sin \frac{\Delta\delta}{2}$$

$$\sin \frac{\Delta\delta}{2} \approx \frac{\Delta\delta}{2}$$

$\therefore \Delta\delta$ is very less

$$E_R = 2E \cdot \frac{\Delta\delta}{2} = E \cdot \Delta\delta$$

$$\overline{I_{sy}} = \frac{E \Delta \delta}{2 X_s \angle 90^\circ}$$

$$\overline{I_{sy}} = \frac{E \Delta \delta \angle -90^\circ}{2 \cdot X_s}$$

$$\boxed{I_{sy} \propto \Delta \delta}$$

$$P_{sy} = E_1 I_{sy} \cos \theta_1$$

$$P_{sy} = \frac{E \cdot E \cdot \Delta \delta \cos \theta_1}{2 X_s}$$

$$\boxed{P_{sy} = \frac{E^2 \Delta \delta \cos \theta_1}{2 X_s}}$$

Active power

$$\theta_1 \approx 0^\circ$$

$$\boxed{P_{sy} = \frac{E^2 \cdot \Delta \delta}{2 X_s}}$$


$$\boxed{Q_{sy} \approx 0}$$

$$\boxed{\text{Steam I/P} \uparrow \Rightarrow K_w \uparrow \Rightarrow P_f \uparrow \Rightarrow \theta \downarrow \Rightarrow I_a \downarrow}$$


Induction Machines :-

3- ϕ Induction motor :-


- $\Rightarrow$ 90% motors are induction motor because these are rugged in construction, its design is simple, provides a maintenance free operation.
- $\Rightarrow$ The disadvantage of induction motor is these have poor starting torque.



Concept :-




②




time varying rotating.

③




time varying stationary.

④




Time varying, alternating/pulsating (stationary)




Concept of rotating magnetic field :- (R.M.F)

When a 3-phase current flows in a 3-phase distributed winding a rotating magnetic field is produced. When a balanced 2-φ supply is given to a 2-φ distributed winding an R.M.F is produced which rotates in a particular direction from leading phase to lagging.

phase at a particular speed known as synchronous speed which having a constant magnitude of $1.5 \phi_m$



let $\overline{I_R} = I_m \sin \omega t \longrightarrow \phi_R = \phi_m \sin \omega t$
 $\overline{I_Y} = I_m \sin (\omega t - 120^\circ) \longrightarrow \phi_Y = \phi_m \sin (\omega t - 120^\circ)$
 $\overline{I_B} = I_m \sin (\omega t - 240^\circ) \longrightarrow \phi_B = \phi_m \sin (\omega t - 240^\circ)$




Case $\rightarrow 1$

$$\omega t = 0^\circ$$

$$\phi_R = 0$$

$$\phi_X = \phi_m \sin(-120^\circ) = -\frac{\sqrt{3}}{2} \phi_m$$

$$\phi_B = \phi_m \sin(-60^\circ) = -\frac{\sqrt{3}}{2} \phi_m$$



$$\phi_{Net} = \sqrt{\left(\frac{\sqrt{3}}{2}\phi_m\right)^2 + \left(\frac{\sqrt{3}}{2}\phi_m\right)^2 + 2\left(\frac{\sqrt{3}}{2}\phi_m\right)\left(\frac{\sqrt{3}}{2}\phi_m\right)\cos 60^\circ}$$

$$\boxed{\phi_{Net} = 1.5 \phi_m}$$


Case $\rightarrow 2$ $\omega t = 60^\circ$

$$\phi_R = \frac{\sqrt{3}}{2} \phi_m$$

$$\phi_X = -\frac{\sqrt{3}}{2} \phi_m$$


$$\phi_B = 0$$


formula for



~~Similarly it is done~~


Note:-







So, the direction of RMF can be reversed by interchanging any two supply terminals.

Rotating magnetic field :-





Formula for synchronous speed :-

g $P = 2$



360° Mechanical $\longrightarrow$ 360° electrical
1 Rotation $\longrightarrow$ 1 cycle

(ii) $P = 4$



360° mechanical $\longrightarrow$ 720° electrical
1 Rotation $\longrightarrow$ 2 cycles

$\Theta_{\text{electrical}} = \left(\frac{P}{2} \right) \Theta_{\text{mechanical}}$

$$\text{cycles per rotation} = \frac{P}{2}$$

Let f = frequency = cycles per sec

$$\frac{\text{cycles per sec}}{\text{cycles per rotation}} = \frac{f}{P/2}$$

$$\boxed{\frac{\text{Rotation}}{\text{sec}} = \frac{2f}{P}}$$

$$\frac{N}{60} = \frac{2f}{P}$$

$$\boxed{N = \frac{120f}{P}}$$

Rotation per unit = N

$$\frac{\text{Rotation}}{\text{sec}} = \frac{N}{60} \quad \text{RPM}$$

$$\boxed{\omega_s = 2\pi n_s = \frac{2\pi N_s}{60} = \frac{4\pi f}{P}}$$

ω_s : Synchronous speed (rad/sec)
 n_s : (Rotation/sec)

$$\boxed{N_s = \frac{120f}{P}}$$

Note :- In case of transformer R.M.F is not produced because the windings are concentrated type.

Construction of induction machine :-

Stator construction :-

① Stator core :- In case of induction and synchronous machine its function is to carry the flux. Since, the flux is rotating, so, to reduce eddy current losses it is laminated. It is made by silicon steel lamination.


② Yoke/frame :- Its function ~~is~~ in synchronous & induction machine is to keep stator stamping in position.

③ Stator contains a 3- ϕ star or Δ connected distributed windings.

Field winding = stator

armature winding = rotor


④



Types of slot :-

$T_{max} \propto \text{Torque max}$


Open type slot



① Winding design is simple so, preferred for large rating machines eg:- alternator

② Non uniform air gap. So, flux contains harmonics (space harmonics)

Closed type slot




① Winding design is very difficult not preferred

② Uniform air gap. So, no flux space harmonics

③ Net air gap is minimum, $I_{a \downarrow}$ pf $\uparrow$ (X & T) maximum slot angle, small, I see

Semi open / semi closed.



① Moderate preferred for medium, small rating & generally preferred slots

② Moderate

③ Moderate, moderate, moderate

③ Net air is maximum $\uparrow$
P.f $\downarrow$

④ Minimum leakage flux
(X₂) $T_{max} \uparrow$, $S_m \uparrow$, $I_{sc} \uparrow$

$x_2 \uparrow$ $x_2 \downarrow$

⑤ Moderate.

$$\textcircled{A} \quad T_{max} \propto \frac{1}{X_2}, \quad S_m \propto \frac{1}{X_2}, \quad I_{sc} \propto \frac{1}{X_2}$$

If size of slots increases the $X \uparrow$,

Rotor construction:-

According to construction there are two types of rotor

① Squirrel cage / cage rotor:-

① This type of rotor consists of solid aluminium or copper bar.

② Intentionally no poles designed on squirrel caged rotor. So, it responds automatically for any number of stator poles and provides a pole changing speed control.

③ It has low starting torque


Area $\uparrow$, $R \downarrow$, $T_{starting} \propto R_2$, R_2 is $\downarrow$

$\therefore T_s$ is also less

④ Have high starting current



Squirrel cage

$$I_{starting} \propto \frac{1}{R_2}$$



For ~~motor~~ running any motor otherwise motor will not run

$$\text{no of stator poles (Ps)} = \text{no of rotor poles (Pr)}$$




Slip ring motor :-

This type of motor contains 3- ϕ , Δ connected windings. Terminals of the windings are connected to 3 slip rings. So, it is known as slip ring motor.

② Here we design a particular number of poles on motor. So, it does not provide pole changing speed control.

③ There is the facility of add an external star connected resistor in series with motor conductor. So, starting torque is not improve.



$$\text{Area} \downarrow, R_2 \uparrow, \uparrow T_s \propto R_2 \uparrow \uparrow$$

$$\boxed{\downarrow I_{sc} \propto \frac{1}{R_2} \uparrow}$$

Working principle of Induction motor :-

When a 3- ϕ supply is given to stator of an induction motor an R.M.F is produced which links with the rotor conductor, so, an emf is induced in the rotor conductor. Since the rotor conductors are essentially short circuited, - so, a current starts flowing in rotor conductors. So, a torque is produced and rotation in the direction of R.M.F. to oppose its cause (According to ~~Lenz~~ Lenz law)


⇒ Rotor wants to catch synchronous speed but falls back by a speed due to its losses present in it. This speed is known as the slip speed

⇒ Induction motor also works on the principle of

Electromagnetic induction and it is a rotating transformer whose secondary is short circuited.

→ A ~~well~~ well designed induction has slip from no load to full load 1% to 5%.

$$N_s = \frac{120f}{P} \approx 1000 \text{ RPM (suppose)}$$



Electrical →

$$\text{Slip speed} = N_s - N_r = s N_s$$

Mechanical ↓

energy

$$\text{Slip (s)} = \frac{N_s - N_r}{N_s} \quad \text{P.u.}$$

At starting $N_r = 0$, $s = \frac{N_s - 0}{N_s}$

$$s = 1$$

② Under running = $N_r \rightarrow N_s$ $s \rightarrow 0$
(motor)

③ generator $N_r > N_s$

$$s = \frac{N_s - N_r}{N_s} = -ive, \quad \boxed{s < 0}$$

braking.

is called

Braking u

$$s = \frac{N_s - (-N_r)}{N_s} = \frac{N_s + N_r}{N_s}$$
$$= 1 + \frac{N_r}{N_s}$$

$$= > 1$$

$s < 0$ induction generator

$s = 0$ NO θ_m (floating)

$0 < s < 1$ Induction motor

$s = 1$, at starting of I-M

$s > 1$ Braking mode.

Ques An induction motor runs at 1250 rpm then find the number of pole on stator

$$N_r = 1250 \text{ RPM}$$

$$N_s = \frac{120f}{P} = \frac{120 \times 50}{P} \Rightarrow P = 4$$

P	N _s (RPM)
2	3000
4	1500
6	1000
8	750
10	600

Effect of slip on rotor parameter:-

Let f_1 = Supply frequency

V_1 = Supply voltage

f_r = rotor induced emf frequency @ starting/standstill/Blocked rotor condⁿ

f_{ar} = Rotor " " " " running condⁿ

N_r = Rotor speed (RPM)

E_s = Rotor induced emf @ starting.

E_r = " " " " at running

X_s = Rotor leakage reactance at starting

X_r = " " " " at running

R_s = rotor resistance at starting condⁿ

R_{sr} = rotor resistance at running condⁿ

I_s = Rotor current at starting condⁿ

I_{sr} = _____ running condⁿ

θ_s = Rotor p.f. angle at starting condⁿ

θ_{sr} = _____ running condⁿ.

s = slip of the motor

Rotor induced emf:

$$N_s - N_r = \frac{120 f_{sr}}{P_s} = \text{slip}$$

$$N_s = \frac{120 f_2}{P_s} = \frac{120 f_1}{P_1}$$

$$\boxed{f_2 = f_1}$$

$$\frac{\text{slip}}{N_s} = \frac{\frac{120 f_{sr}}{P_s}}{\frac{120 f_2}{P_2}}$$

$$\boxed{f_{sr} = s f_1}$$

eg $f_1 = 50 \text{ Hz}$
 $s = 0.05$
 $f_2 = f_1 = 50 \text{ Hz}$

$$\begin{aligned} f_{sr} &= s f_1 \\ &= 0.05 \times 50 \\ &= 2.5 \text{ Hz} \end{aligned}$$

Rotor leakage reactance:

$$\begin{aligned} X &\propto f \\ X_{sr} &\propto f_{sr} \end{aligned}$$

$$X_2 \propto f_2$$

$$\frac{X_{2r}}{X_2} = \frac{f_{2r}}{f_2} = \frac{s b_1}{b_1}$$

$$\boxed{X_{2r} = s X_2} \quad \text{---} \quad \text{---}$$

③ Rotor induced emf

$$E_r \propto N_s$$

$$E_r \propto N_s - N_r$$

$$\therefore \frac{E_r}{E_2} = \frac{N_s}{N_s - N_r}$$


$$\frac{E_r}{E_2} = \frac{1}{s}$$

$$\therefore \boxed{E_r = s E_2}$$

④ Rotor resistance :

$$\boxed{R_r = R_2}$$

⑤ Rotor current



$$I_{2r} = \frac{E_{2r}}{\sqrt{R_2^2 + (X_{2r})^2}}$$

$$I_{2r} = \frac{S E_2}{\sqrt{R_2^2 + S^2 X_2^2}}$$

$$I_2 = \frac{E_2}{\sqrt{R_2^2 + X_2^2}}$$

⑥ Rotor p.f.:-

$$\cos \theta_{2r} = \frac{R_2}{\sqrt{R_2^2 + X_{2r}^2}}$$

$$\cos \theta_2 = \frac{R_2}{\sqrt{R_2^2 + X_2^2}}$$

Note:-

$$R_2 = 0.2 \Omega$$

$$X_2 = 1 \Omega$$

Starting

$X_2^2 \gg R_2^2$
we can neglect R_2^2

$$I_2 \approx \frac{E_2}{X_2}$$

$$\cos \theta_2 = \frac{R_2}{X_2}$$

But Running:- $R_{2r} = 0.2 \Omega$

$$X_{2r} = 0.05 \Omega$$


$$X_{2r} = 0.05 \Omega$$

$$\therefore R_{2r}^2 \gg X_{2r}^2$$


$$\therefore I_{2r} = \frac{E_2}{R_{2r}}$$

Torque developed in an induction motor:-

If the rotor is pure ~~resistive~~; inductive.



$\therefore$ Torque lags E_{ar} by angle 90° .




$\therefore$ Torque $P = T \omega$

$T \propto V_i$

First cycle $T_{avg} = 0$



$\delta = 180^\circ$



~~Case I~~

Case II:- If rotor is pure & resistive


I_a in phase with E_r



So, in case of pure resistive rotor the average torque is maximum and

$$\boxed{\delta = \pi/2}$$

Case $\rightarrow$ III $\div$ If rotor is R-L & ϕ_r lags
 E_r by angle ~~ϕ_{2r}~~ θ_{2r}



Result $\boxed{\delta = \pi/2 + \theta_{2r}}$

$\textcircled{0} \quad \boxed{T_{er} \propto \Phi_s \cdot \Phi_r \sin \delta}$

T_{er} = rotor running torque

$T_{er} \propto \Phi_s \Phi_r \sin \delta$

$\Phi_s \propto \frac{V_1}{\phi_1} \propto \frac{E_s}{\phi_1} \quad \bigg| \quad \Phi_{a1} \propto I_{ar}$
 ~~$\delta = \pi/2 + \phi_{2r}$~~
 $\delta = \pi/2 + \theta_{2r}$

$$\frac{V_1}{V_2} = \frac{E_1}{E_2} = \frac{1}{K}$$

$$\boxed{V_1 = \frac{V_2}{K} = \frac{E_2}{K}}$$

$$T_{er} \propto \frac{3E_2}{\phi_1} \cdot I_{ar} \cdot \sin(\pi/6 + \theta_{ar})$$

$$T_{er} \propto \frac{3E_2}{\phi_1} \cdot I_{ar} \cos \theta_{ar}$$

$$\boxed{T_{er} = \frac{3E_2 I_{ar} \cos \theta_{ar}}{W_s}} \quad \#$$

$$T_{er} = \frac{3}{S W_s} \left(S^2 E \right)$$

$$E_2 \propto V_1$$

$$T_{er} = \frac{3E_2}{W_s} \frac{SE_2}{\sqrt{R_2^2 + S^2 X_2^2}} \cdot \frac{R_2}{\sqrt{R_2^2 + S^2 X_2^2}}$$

$$\boxed{T_{er} = \frac{3SE_2^2 R_2}{W_s (R_2^2 + S^2 X_2^2)}} \quad \# \quad \#$$

$$T_{er} = \frac{3}{S W_s} \left(\frac{S^2 E_2^2 R_2}{R_2^2 + S^2 X_2^2} \right)$$

$$T_{er} = \frac{3}{S W_s} T_{er}^2 R_2$$

$$T_{cr} = \frac{1}{s\omega_s} (3 I_e^2 R_2)$$

$$\boxed{\text{Rotor cu loss} = \text{Rotor copper loss} = R.C.L = 3 I_e^2 R_2}$$

$$T_{cr} = \frac{1 \times R.C.L}{s\omega}$$

Starting torque :

$$T_{cr} = \frac{3 s E_v^2 R_2}{\omega_s (R_2^2 + s^2 X_2^2)}$$

• at starting $s = 1$

$$(T_{cr})_{st} = \frac{3 E_v^2 R_2}{\omega_s (R_2^2 + X_2^2)}$$

$$R_2 \ll X_2^2$$

$$\boxed{(T_{cr})_{st} \approx \frac{3 E_v^2 R_2}{\omega_s \cdot X_2^2}}$$

~~Result~~ $(T_{cr})_{st} \propto R_2$

Result :-

$$(1) \quad (T_e)_{st} \propto R_2$$

$$(2) \quad (T_e)_{st} \propto V_1^2$$

$$(3) \quad (T_e)_{st} \propto \frac{1}{f^3}$$

∴ ~~increasing~~ case of 3- ϕ Im $(T_e)_{st} \neq 0$. So, these are self starting in nature

Condition for maximum starting torque :-

$$\frac{d(T_e)_{st}}{dR_2} = 0$$

$$R_2 = X_2$$

$$\text{Eg: } R_2 = 0.2 \Omega$$

$$X_2 = 1 \Omega$$

Value of max starting torque $\rightarrow R_2$ has to increase so that X_2 will

$$[(T_e)_{st}]_{\max} = \frac{3T_e V_2}{\omega_s (X_2^2 + X_2^2)}$$

$$\boxed{[T_e]_{st} \max = \frac{3E_2^2}{2\omega_s \cdot X_2}}$$

Result :-

① $T_{max} \propto V_1^2$

② $T_{max} \propto \frac{1}{f_2}$

③ Max starting does not depends on rotor resistance.

④ Rotor power factor for maximum starting torque

$\therefore \cos \theta_a = \frac{R_2}{\sqrt{R_2^2 + X_2^2}} \quad \text{at } R_2 = X_2$

$$\cos \theta_a = \frac{R_2}{\sqrt{R_2^2 + X_2^2}}$$

$$\boxed{\cos \theta_a = \frac{1}{\sqrt{2}} = 0.707 \text{ lagging}}$$

Formula for developed torque in the rotating rotor under running condition,

$$T_{er} = \frac{3 s I_2^2 L.P_2}{\omega_s (R_2^2 + s^2 X_2^2)}$$

$$\boxed{[T_e]_{st} \max = \frac{3E_2^2}{2\omega_s \cdot X_2}}$$

Result :-

① $T_{max} \propto V_1^2$

② $T_{max} \propto \frac{1}{f_2}$

③ Max starting does not depends on rotor resistance.

④ Rotor power factor for maximum starting torque

∴ $\cos \theta_2 = \frac{R_2}{\sqrt{R_2^2 + X_2^2}} \quad \text{at } R_2 = X_2$

$$\cos \theta_2 = \frac{R_2}{\sqrt{X_2^2 + X_2^2}}$$

$$\boxed{\cos \theta_2 = \frac{1}{\sqrt{2}} = 0.707 \text{ lagging}}$$

Formula for developed torque in the rotating rotor under running condition,

$$T_{er} = \frac{3 s E_2^2}{\omega_s (R_2^2 + s^2 X_2^2)}$$

Under running condition

$$S^2 \propto R_L^2 \ll R_L^2$$

$$\text{Tor} = \frac{3 S E^2 \cdot R_L}{\omega_s \cdot R_L^2}$$

$$\text{Tor} = \frac{3 S E^2}{\omega_s \cdot R_L}$$

Result :- $\text{Tor} \propto \frac{1}{P_2}$

② $\text{Tor} \propto V_1^2$

③ $\text{Tor} \propto f$

Value of max Torque :-

$$(\text{tor})_{\text{max}} = \frac{3 S A E^2 L R_L}{\omega_s (R_L^2 + S^2)}$$

$$(\text{Tor})_{\text{max}} = \frac{3 S m E^2 \cdot R_L}{\omega_s (R_L^2 + S^2)}$$


$$(T_{er})_{\max} = \frac{3E_2^2}{\omega_s X_2}$$

- ① $T_{\max} \propto V_1^2$
- ② $T_{\max} \propto \frac{1}{X_2}$

Max starting torque does not depend on rotor resistance,

Torque speed or torque slip characteristics:-

$$T_{er} = \frac{3sE_2^2 \cdot R_2}{\omega_s (R_2^2 + s^2 X_2^2)}$$



$\left(\uparrow T_{er} \propto \frac{1}{S} \downarrow \right)$ — 9 rectangular
 Hyperbola.


$$\left. \begin{array}{l} R_2 = .2 \Omega \\ X_2 = 1 \Omega \end{array} \right\} S = 1$$




$$\left[\begin{array}{l} R_2 = .2 \Omega \\ X_{ar} = 0.2 \Omega \end{array} \right] S = .2$$



$$\left[\begin{array}{l} R_2 = .2 \Omega \\ X_{er} = .05 \Omega \end{array} \right] S = .05$$





generally asked = rectangular parabola
 in low slip region = line
 high slip region = rectangular hyperbola

The Torque-slip characteristics of induction motor
 is rectangular parabola.

Note :-

Note :- if $T_e >$



$$T_{\text{accelerating}} = T_e - T_L \quad \text{load.}$$

~~electrical~~
electromagnetic


① if $T_e > T_L$, $T_{\text{acc}} = +ve$, accelerate,
 $N \uparrow$

② if $T_e < T_L$, $T_{\text{acc}} = -ive$, decelerate.
 $N \downarrow$

③ if $T_e = T_L$, $T_{\text{acc}} = 0$, $N = \text{constant}$.



On heavily left or right to being motor remains stable



~~$V_g = V_c = V_b = V_s$~~

Losses :-

① Stator losses $\left\{ \begin{array}{l} \rightarrow \text{Stator cu Loss } (3I_1^2 R_1) \\ \rightarrow \text{Stator core losses} \end{array} \right.$

② Rotor losses $\left\{ \begin{array}{l} \rightarrow \text{Rotor cu losses } [3I_r^2 R_r] \\ \rightarrow \text{Rotor core Loss } [f_{ar} \rightarrow 25\text{Hz} \rightarrow 0] \end{array} \right.$
 $(f_{ar} + f_{br})^2$

So, rotor core loss can be neglected.

③ Mechanical losses $\left\{ \begin{array}{l} \rightarrow \text{Bearing friction loss + windage friction loss} \\ \rightarrow \text{Brush frictional loss (Slip ring induction motor)} \end{array} \right.$

Nett :-

① Constant Loss = (Stator core loss + Rotor core loss $\uparrow$ with $\downarrow$ mech loss $\downarrow$ with $\uparrow$ in $\uparrow$)
 so overall constant

② Variable loss = Stator cu loss + RCL.

Power flow diagram :-

Results $P_{in} = \sqrt{3} V_L I_L \cos \theta_1$

$\uparrow$
P.f. of I-M

$$P_{in} = 3 V_L I_L \cos \theta_1$$

① $P_g = P_i - (\text{stator losses})$
 $= 3 E_a I_a \cos \theta_{ar}$

② $P_m = P_g - (\text{Roto losses})$

③ $P_{sh} = P_m - (\text{Mechanical losses})$

④ $\eta = \frac{P_{sh} \times 100}{P_i}$

$P_m = 2\pi N_s T_{er}$

⑤ $P_g = T_{er} \cdot \omega_s$ $P_m = P_g - R_e L$

$P_g = \frac{1}{s} (R_e L) \omega_s$ $R_e L = 2\pi T_{er} (N_s - N_r)$



$P_g = \frac{1}{s} (R_e L) \omega_s$ $\frac{R_e L}{P_g} = \frac{2\pi T_{er} (N_s - N_r)}{2\pi T_{er} N_s}$

$$P_g = \frac{1}{s} (R_e L)$$

$\frac{R_e L}{P_g} = s$
 $P_g = \frac{R_e L}{s}$

⑥ $P_m = P_g - (\text{rotor cu losses} + \text{Rotor core loss})$

⑦ $P_m = \frac{1}{s} (R_e L) - [R_e L + 0]$



$$P_m = \left(\frac{1-s}{s} \right) RCL$$

$$(8) \quad T_{sh} = \frac{P_{sh}}{\omega}$$

$$(9) \quad T_{sh} = T_{er} - (\text{Load torque})$$

$$(10) \quad T_{er} = \frac{1}{s\omega_s} (RCL)$$

Approx formula & formula for efficiency:

$$P_{sh} = \eta = \frac{P_{sh}}{P_i}$$

$$P_{sh} = P_m - \underset{SS}{\text{(mech loss)}}$$

$$P_{sh} = P_m$$

$$P_{sh} = \left(\frac{1-s}{s} \right) RCL \quad \text{--- (1)}$$

$$P_i = P_g + \underset{SS}{\text{(Stator Cu Loss + Stator core loss)}}$$

$$P_i = P_g + (RCL + \text{Rotor core loss})$$

$$P_i = P_g + RCL + 0 \Rightarrow P_i = P_g + RCL$$

$$P_i^o = \frac{1}{s} (RCL) + (RCL)$$

$$P_i^o = \left(\frac{1+s}{s} \right) RCL \quad \text{--- (2)}$$

$$\eta = \frac{\left(\frac{1-s}{s} \right) RCL}{\left(\frac{1+s}{s} \right) RCL}$$

$$\boxed{\eta = \frac{1-s}{1+s}}$$


$$\therefore s \rightarrow 0$$

$$1+s \approx 1$$

$$\boxed{\eta = 1-s}$$

By 1, 2, 3, 4, 5, 6, 7, 8, 9, 10, 11, 12, 13, 14, 15, 16, 17, 18, 19, 20, 21, 22, 23, 24, 25, 26, 27, 28, 29, 30, 31, 32, 33, 34, 35, 36, 37, 38, 39, 40, 41, 42, 43, 44, 45, 46, 47, 48, 49, 50, 51, 52, 53, 54, 55, 56, 57, 58, 59, 60, 61, 62, 63, 64, 65, 66, 67, 68, 69, 70, 71, 72, 73, 74, 75, 76, 77, 78, 79, 80, 81, 82, 83, 84, 85, 86, 87, 88, 89, 90, 91, 92, 93, 94, 95, 96, 97, 98, 99, 100, 101, 102, 103, 104, 105, 106, 107, 108, 109, 110, 111, 112, 113, 114, 115, 116, 117, 118, 119, 120, 121, 122, 123, 124, 125, 126, 127, 128, 129, 130, 131, 132, 133, 134, 135, 136, 137, 138, 139, 140, 141, 142, 143, 144, 145, 146, 147, 148, 149, 150, 151, 152, 153, 154, 155, 156, 157, 158, 159, 160, 161, 162, 163, 164, 165, 166, 167, 168, 169, 170, 171, 172, 173, 174, 175, 176, 177, 178, 179, 180, 181, 182, 183, 184, 185, 186, 187, 188, 189, 190, 191, 192, 193, 194, 195, 196, 197, 198, 199, 200, 201, 202, 203, 204, 205, 206, 207, 208, 209, 210, 211, 212, 213, 214, 215, 216, 217, 218, 219, 220, 221, 222, 223, 224, 225, 226, 227, 228, 229, 230, 231, 232, 233, 234, 235, 236, 237, 238, 239, 240, 241, 242, 243, 244, 245, 246, 247, 248, 249, 250, 251, 252, 253, 254, 255, 256, 257, 258, 259, 260, 261, 262, 263, 264, 265, 266, 267, 268, 269, 270, 271, 272, 273, 274, 275, 276, 277, 278, 279, 280, 281, 282, 283, 284, 285, 286, 287, 288, 289, 290, 291, 292, 293, 294, 295, 296, 297, 298, 299, 300, 301, 302, 303, 304, 305, 306, 307, 308, 309, 310, 311, 312, 313, 314, 315, 316, 317, 318, 319, 320, 321, 322, 323, 324, 325, 326, 327, 328, 329, 330, 331, 332, 333, 334, 335, 336, 337, 338, 339, 340, 341, 342, 343, 344, 345, 346, 347, 348, 349, 350, 351, 352, 353, 354, 355, 356, 357, 358, 359, 360, 361, 362, 363, 364, 365, 366, 367, 368, 369, 370, 371, 372, 373, 374, 375, 376, 377, 378, 379, 380, 381, 382, 383, 384, 385, 386, 387, 388, 389, 390, 391, 392, 393, 394, 395, 396, 397, 398, 399, 400, 401, 402, 403, 404, 405, 406, 407, 408, 409, 410, 411, 412, 413, 414, 415, 416, 417, 418, 419, 420, 421, 422, 423, 424, 425, 426, 427, 428, 429, 430, 431, 432, 433, 434, 435, 436, 437, 438, 439, 440, 441, 442, 443, 444, 445, 446, 447, 448, 449, 450, 451, 452, 453, 454, 455, 456, 457, 458, 459, 460, 461, 462, 463, 464, 465, 466, 467, 468, 469, 470, 471, 472, 473, 474, 475, 476, 477, 478, 479, 480, 481, 482, 483, 484, 485, 486, 487, 488, 489, 490, 491, 492, 493, 494, 495, 496, 497, 498, 499, 500, 501, 502, 503, 504, 505, 506, 507, 508, 509, 510, 511, 512, 513, 514, 515, 516, 517, 518, 519, 520, 521, 522, 523, 524, 525, 526, 527, 528, 529, 530, 531, 532, 533, 534, 535, 536, 537, 538, 539, 540, 541, 542, 543, 544, 545, 546, 547, 548, 549, 550, 551, 552, 553, 554, 555, 556, 557, 558, 559, 560, 561, 562, 563, 564, 565, 566, 567, 568, 569, 570, 571, 572, 573, 574, 575, 576, 577, 578, 579, 580, 581, 582, 583, 584, 585, 586, 587, 588, 589, 590, 591, 592, 593, 594, 595, 596, 597, 598, 599, 600, 601, 602, 603, 604, 605, 606, 607, 608, 609, 610, 611, 612, 613, 614, 615, 616, 617, 618, 619, 620, 621, 622, 623, 624, 625, 626, 627, 628, 629, 630, 631, 632, 633, 634, 635, 636, 637, 638, 639, 640, 641, 642, 643, 644, 645, 646, 647, 648, 649, 650, 651, 652, 653, 654, 655, 656, 657, 658, 659, 660, 661, 662, 663, 664, 665, 666, 667, 668, 669, 670, 671, 672, 673, 674, 675, 676, 677, 678, 679, 680, 681, 682, 683, 684, 685, 686, 687, 688, 689, 690, 691, 692, 693, 694, 695, 696, 697, 698, 699, 700, 701, 702, 703, 704, 705, 706, 707, 708, 709, 710, 711, 712, 713, 714, 715, 716, 717, 718, 719, 720, 721, 722, 723, 724, 725, 726, 727, 728, 729, 730, 731, 732, 733, 734, 735, 736, 737, 738, 739, 740, 741, 742, 743, 744, 745, 746, 747, 748, 749, 750, 751, 752, 753, 754, 755, 756, 757, 758, 759, 760, 761, 762, 763, 764, 765, 766, 767, 768, 769, 770, 771, 772, 773, 774, 775, 776, 777, 778, 779, 780, 781, 782, 783, 784, 785, 786, 787, 788, 789, 790, 791, 792, 793, 794, 795, 796, 797, 798, 799, 800, 801, 802, 803, 804, 805, 806, 807, 808, 809, 810, 811, 812, 813, 814, 815, 816, 817, 818, 819, 820, 821, 822, 823, 824, 825, 826, 827, 828, 829, 830, 831, 832, 833, 834, 835, 836, 837, 838, 839, 840, 841, 842, 843, 844, 845, 846, 847, 848, 849, 850, 851, 852, 853, 854, 855, 856, 857, 858, 859, 860, 861, 862, 863, 864, 865, 866, 867, 868, 869, 870, 871, 872, 873, 874, 875, 876, 877, 878, 879, 880, 881, 882, 883, 884, 885, 886, 887, 888, 889, 890, 891, 892, 893, 894, 895, 896, 897, 898, 899, 900, 901, 902, 903, 904, 905, 906, 907, 908, 909, 910, 911, 912, 913, 914, 915, 916, 917, 918, 919, 920, 921, 922, 923, 924, 925, 926, 927, 928, 929, 930, 931, 932, 933, 934, 935, 936, 937, 938, 939, 940, 941, 942, 943, 944, 945, 946, 947, 948, 949, 950, 951, 952, 953, 954, 955, 956, 957, 958, 959, 960, 961, 962, 963, 964, 965, 966, 967, 968, 969, 970, 971, 972, 973, 974, 975, 976, 977, 978, 979, 980, 981, 982, 983, 984, 985, 986, 987, 988, 989, 990, 991, 992, 993, 994, 995, 996, 997, 998, 999, 1000, 1001, 1002, 1003, 1004, 1005, 1006, 1007, 1008, 1009, 1010, 1011, 1012, 1013, 1014, 1015, 1016, 1017, 1018, 1019, 1020, 1021, 1022, 1023, 1024, 1025, 1026, 1027, 1028, 1029, 1030, 1031, 1032, 1033, 1034, 1035, 1036, 1037, 1038, 1039, 1040, 1041, 1042, 1043, 1044, 1045, 1046, 1047, 1048, 1049, 1050, 1051, 1052, 1053, 1054, 1055, 1056, 1057, 1058, 1059, 1060, 1061, 1062, 1063, 1064, 1065, 1066, 1067, 1068, 1069, 1070, 1071, 1072, 1073, 1074, 1075, 1076, 1077, 1078, 1079, 1080, 1081, 1082, 1083, 1084, 1085, 1086, 1087, 1088, 1089, 1090, 1091, 1092, 1093, 1094, 1095, 1096, 1097, 1098, 1099, 1100, 1101, 1102, 1103, 1104, 1105, 1106, 1107, 1108, 1109, 1110, 1111, 1112, 1113, 1114, 1115, 1116, 1117, 1118, 1119, 1120, 1121, 1122, 1123, 1124, 1125, 1126, 1127, 1128, 1129, 1130, 1131, 1132, 1133, 1134, 1135, 1136, 1137, 1138, 1139, 1140, 1141, 1142, 1143, 1144, 1145, 1146, 1147, 1148, 1149, 1150, 1151, 1152, 1153, 1154, 1155, 1156, 1157, 1158, 1159, 1160, 1161, 1162, 1163, 1164, 1165, 1166, 1167, 1168, 1169, 1170, 1171, 1172, 1173, 1174, 1175, 1176, 1177, 1178, 1179, 1180, 1181, 1182, 1183, 1184, 1185, 1186, 1187, 1188, 1189, 1190, 1191, 1192, 1193, 1194, 1195, 1196, 1197, 1198, 1199, 1200, 1201, 1202, 1203, 1204, 1205, 1206, 1207, 1208, 1209, 1210, 1211, 1212, 1213, 1214, 1215, 1216, 1217, 1218, 1219, 1220, 1221, 1222, 1223, 1224, 1225, 1226, 1227, 1228, 1229, 1230, 1231, 1232, 1233, 1234, 1235, 1236, 1237, 1238, 1239, 1240, 1241, 1242, 1243, 1244, 1245, 1246, 1247, 1248, 1249, 1250, 1251, 1252, 1253, 1254, 1255, 1256, 1257, 1258, 1259, 1260, 1261, 1262, 1263, 1264, 1265, 1266, 1267, 1268, 1269, 1270, 1271, 1272, 1273, 1274, 1275, 1276, 1277, 1278, 1279, 1280, 1281, 1282, 1283, 1284, 1285, 1286, 1287, 1288, 1289, 1290, 1291, 1292, 1293, 1294, 1295, 1296, 1297, 1298, 1299, 1300, 1301, 1302, 1303, 1304, 1305, 1306, 1307, 1308, 1309, 1310, 1311, 1312, 1313, 1314, 1315, 1316, 1317, 1318, 1319, 1320, 1321, 1322, 1323, 1324, 1325, 1326, 1327, 1328, 1329, 1330, 1331, 1332, 1333, 1334, 1335, 1336, 1337, 1338, 1339, 1340, 1341, 1342, 1343, 1344, 1345, 1346, 1347, 1348, 1349, 1350, 1351, 1352, 1353, 1354, 1355, 1356, 1357, 1358, 1359, 1360, 1361, 1362, 1363, 1364, 1365, 1366, 1367, 1368, 1369, 1370, 1371, 1372, 1373, 1374, 1375, 1376, 1377, 1378, 1379, 1380, 1381, 1382, 1383, 1384, 1385, 1386, 1387, 1388, 1389, 1390, 1391, 1392, 1393, 1394, 1395, 1396, 1397, 1398, 1399, 1400, 1401, 1402, 1403, 1404, 1405, 1406, 1407, 1408, 1409, 1410, 1411, 1412, 1413, 1414, 1415, 1416, 1417, 1418, 1419, 1420, 1421, 1422, 1423, 1424, 1425, 1426, 1427, 1428, 1429, 1430, 1431, 1432, 1433, 1434, 1435, 1436, 1437, 1438, 1439, 1440, 1441, 1442, 1443, 1444, 1445, 1446, 1447, 1448, 1449, 1450, 1451, 1452, 1453, 1454, 1455, 1456, 1457, 1458, 1459, 1460, 1461, 1462, 1463, 1464, 1465, 1466, 1467, 1468, 1469, 1470, 1471, 1472, 1473, 1474, 1475, 1476, 1477, 1478, 1479, 1480, 1481, 1482, 1483, 1484, 1485, 1486, 1487, 1488, 1489, 1490, 1491, 1492, 1493, 1494, 1495, 1496, 1497, 1498, 1499, 1500, 1501, 1502, 1503, 1504, 1505, 1506, 1507, 1508, 1509, 1510, 1511, 1512, 1513, 1514, 1515, 1516, 1517, 1518, 1519, 1520, 1521, 1522, 1523, 1524, 1525, 1526, 1527, 1528, 1529, 1530, 1531, 1532, 1533, 1534, 1535, 1536, 1537, 1538, 1539, 1540, 1541, 1542, 1543, 1544, 1545, 1546, 1547, 1548, 1549, 1550, 1551, 1552, 1553, 1554, 1555, 1556, 1557, 1558, 1559, 1560, 1561, 1562, 1563, 1564, 1565, 1566, 1567, 1568, 1569, 1570, 1571, 1572, 1573, 1574, 1575, 1576, 1577, 1578, 1579, 1580, 1581, 1582, 1583, 1584, 1585, 1586, 1587, 1588, 1589, 1590, 1591, 1592, 1593, 1594, 1595, 1596, 1597, 1598, 1599, 1600, 1601, 1602, 1603, 1604, 1605, 1606, 1607, 1608, 1609, 1610, 1611, 1612, 1613, 1614, 1615, 1616, 1617, 1618, 1619, 1620, 1621, 1622, 1623, 1624, 1625, 1626, 1627, 1628, 1629, 1630, 1631, 1632, 1633, 1634, 1635, 1636, 1637, 1638, 1639, 1640, 1641, 1642, 1643, 1644, 1645, 1646, 1647, 1648, 1649, 1650, 1651, 1652, 1653, 1654, 1655, 1656, 1657, 1658, 1659, 1660, 1661, 1662, 1663, 1664, 1665, 1666, 1667, 1668, 1669, 1670, 1671, 1672, 1673, 1674, 1675, 1676, 1677, 1678, 1679, 1680, 1681, 1682, 1683, 1684, 1685, 1686, 1687, 1688, 1689, 1690, 1691, 1692, 1693, 1694, 1695, 1696, 1697, 1698, 1699, 1700, 1701, 1702, 1703, 1704, 1705, 1706, 1707, 1708, 1709, 1710, 1711, 1712, 1713, 1714, 1715, 1716, 1717, 1718, 1719, 1720, 1721, 1722, 1723, 1724, 1725, 1726, 1727, 1728, 1729, 1730, 1731, 1732, 1733, 1734, 1735, 1736, 1737, 1738, 1739, 1740, 1741, 1742, 1743, 1744, 1745, 1746, 1747, 1748, 1749, 1750, 1751, 1752, 1753, 1754, 1755, 1756, 1757, 1758, 1759, 1760, 1761, 1762, 1763, 1764, 1765, 1766, 1767, 1768, 1769, 1770, 1771, 1772, 1773, 1774, 1775, 1776, 1777, 1778, 1779, 1780, 1781, 1782, 1783, 1784, 1785, 1786, 1787, 1788, 1789, 1790, 1791, 1792, 1793, 1794, 1795, 1796, 1797, 1798, 1799, 1800, 1801, 1802, 1803, 1804, 1805, 1806, 1807, 1808, 1809, 1810, 1811, 1812, 1813, 1814, 1815, 1816, 1817, 1818, 1819, 1820, 1821, 1822, 1823, 1824, 1825, 1826, 1827, 1828, 1829, 1830, 1831, 1832, 1833, 1834, 1835, 1836, 1837, 1838, 1839, 1840, 1841, 1842, 1843, 1844, 1845, 1846, 1847, 1848, 1849, 1850, 1851, 1852, 1853, 1854, 1855, 1856, 1857, 1858, 1859, 1860, 1861, 1862, 1863, 1864, 1865, 1866, 1867, 1868, 1869, 1870, 1871, 1872, 1873, 1874, 1875, 1876, 1877, 1878, 1879, 1880, 1881, 1882, 1883, 1884, 1885, 1886, 1887, 1888, 1889, 1890, 1891, 1892, 1893, 1894, 1895, 1896, 1897, 1898, 1899, 1900, 1901, 1902, 1903, 1904, 1905, 1906, 1907, 1908, 1909, 1910, 1911, 1912, 1913, 1914, 1915, 1916, 1917, 1918, 1919, 1920, 1921, 1922, 1923, 1924, 1925, 1926, 1927, 1928, 1929, 1930, 1931, 1932, 1933, 1934, 1935, 1936, 1937, 1938, 1939, 1940, 1941, 1942, 1943, 1944, 1945, 1946, 1947, 1948, 1949, 1950, 1951, 1952, 1953, 1954, 1955, 1956, 1957, 1958, 1959, 1960, 1961, 1962, 1963, 1964, 1965, 1966, 1967, 1968, 1969, 1970, 1971, 1972, 1973, 1974, 1975, 1976, 1977, 1978, 1979, 1980, 1981, 1982, 1983, 1984, 1985, 1986, 1987, 1988, 1989, 1990, 1991, 1992, 1993, 1994, 1995, 1996, 1997, 1998, 1999, 2000, 2001, 2002, 2003, 2004, 2005, 2006, 2007, 2008, 2009, 2010, 2011, 2012, 2013, 2014, 2015, 2016, 2017, 2018, 2019, 2020, 2021, 2022, 2023, 2024, 2025, 2026, 2027, 2028, 2029, 2030, 2031, 2032, 2033, 2034, 2035, 2036, 2037, 2038, 2039, 2040, 2041, 2042, 2043, 2044, 2045, 2046, 2047, 2048, 2049, 2050, 2051, 2052, 2053, 2054, 2055, 2056, 2057, 2058, 2059, 2060, 2061, 2062, 2063, 2064, 2065, 2066, 2067, 2068, 2069, 2070, 2071, 2072, 2073, 2074, 2075, 2076, 2077, 2078, 2079, 2080, 2081, 2082, 2083, 2084, 2085, 2086, 2087, 2088, 2089, 2090, 2091, 2092, 2093, 2094, 2095, 2096, 2097, 2098, 2099, 2100, 2101, 2102, 2103, 2104, 2105, 2106, 2107, 2108, 2109, 2110, 2111, 2112, 2113, 2114, 2115, 2116, 2117, 2118, 2119, 2120, 2121, 2122, 2123, 2124, 2125, 2126, 2127, 2128, 2129, 2130, 2131, 2132, 2133, 2134, 2135, 2136, 2137, 2138, 2139, 2140, 2141, 2142, 2143, 2144, 2145, 2146, 2147, 2148, 2149, 2150, 2151, 2152, 2153, 2154, 2155, 2156, 2157, 2158, 2159, 2160, 2161, 2162, 2163, 2164, 2165, 2166, 2167, 2168, 2169, 2170, 2171, 2172, 2173,

Equivalent circuit of induction motor:-




$$I_{ar} = \frac{E_{ar}}{\sqrt{R_2^2 + X_{2r}^2}}$$


$$I_{ar} = \frac{E_{ar}}{\sqrt{R_e^2 + X_{2r}^2}}$$

$$I_{ar} = \frac{s E_2}{\sqrt{R_e^2 + s^2 V_2^2}}$$

$$I_{ar} = \frac{E_2}{\sqrt{\left(\frac{R_e}{s}\right)^2 + X_2^2}}$$



$$\frac{R_2}{s} = R + \left(\frac{1-s}{s} \right) R_2$$



At no load $s \rightarrow 0$

$$\left(\frac{1-s}{s} \right) R_2 \rightarrow \infty (O.C.)$$

$$I_{2r} \rightarrow 0$$

As load increases

$$s \rightarrow 1$$


$$\left(\frac{1-s}{s} \right) R_2 \rightarrow 0 (S.C.)$$

$$I_{2r} \rightarrow \uparrow \uparrow$$

So, $\left(\frac{1-s}{s} \right) R_2 = R_L$ it represents electrical equivalent load of Mechanical ~~loading~~ loading.

Equivalent circuit referred to primary:-

$$\boxed{R_e' = \frac{R}{s}}$$




$$P = 3 I_{ar}'^2 \cdot \left(\frac{1-s}{s} \right) R_2'$$

$$P = \left(\frac{1-s}{s} \right) (3 I_{ar}'^2 \cdot R_2')$$

$$P = \left(\frac{1-s}{s} \right) R_{CL}$$


$$P = P_m$$

Approx (obj) circuit for objective i



Testing of Induction motor :-

No load test :-




- $P_i^0 = P_o + \text{Loss}$
 $P_i^0 = 0 + \text{Loss}$
 $W_{NL} = \text{Loss}$
- Stator Cu Loss ($3 I_{NL}^2 R_1$) = $3 I_o^2 R_1 (L)$
 - Stator Core Loss $\propto (B_m^x \cdot f + B_m^2 f^2) \times \left(\frac{V^2}{f}\right) (L)$
 - R.C.L ($3 I_{ar}^2 R_r$) → $I_{ar} \rightarrow 0 \approx 0$
 - Rotor core loss ($I_{br} \rightarrow I_{fr} \rightarrow 0$) ≈ 0
 - mech loss (✓)

$(W_{NL}) = \text{Stator Cu Loss} + \text{Stator Core loss} + \text{Mech Loss}$

$$W_{NL} = 3 I_{NL}^2 R + W_o$$

(K/W) (A) DC Test (✓)



$$\bar{Z}_{NL} = R_1 + j(X_1 + X_m)$$

$$|Z_{NL}| = \sqrt{R_1^2 + (X_1 + X_m)^2}$$


$\downarrow$ $\downarrow$ $\downarrow$
 K/N D.C Blocked
 test test test

No Load :-

$$S \rightarrow 0$$

$$R_1' \rightarrow \infty$$


$$I_{1r'} \rightarrow 0$$



$$|Z_{NL}| = \frac{V_{NL}}{I_{NL}}$$

(V)
(A)

D.C Test :-




$$\frac{V_{DC}}{I_{DC}} = 2(R_1)_{DC}, (R_1)_{DC} = \frac{V_{DC}}{2 I_{DC}}$$

$$R_L = R_{IAC} = (1.2 \text{ to } 1.3) \sigma(R_i) \rho_c$$

Separation of stator core loss and mechanical loss :-

For separation of mechanical loss and stator core loss the no-load test should be performed at different - different supply voltages from 40% of V_{rated} to 125% of V_{rated} at rated frequency and rotational losses calculated for different - different value of $N-L$. Now a graph is plotted b/w

ω_0 and V_{NL} and length of OC gives rotational loss corresponding to zero volt which is mechanical loss.



$$(V_{NL})_{L1} = 200V, \omega_{01}$$

$$(V_{NL})_{L2} = 250V, \omega_{02}$$

$$(V_{NL})_{Ln} = 625V, \omega_{0n} =$$

$\omega_0 \propto (\text{stator core loss} + \text{mech loss})$

$\omega_0 \propto \text{stator core loss}$

$$\omega_0 \propto \left[\frac{V_{NL}^2}{f^2} \cdot f + \frac{V_{NL}^2}{f^2} \cdot f^2 \right]$$


$$W_0 \propto V_{NL}^2 \rightarrow \text{parabolic}$$

$$W_{NL} = 3I_{NL}^2 R_1 + W_0$$

$\swarrow$ $\swarrow$ $\swarrow$ $\swarrow$
 K/n K/n K/n calculated


$$W_0 = \text{stator core loss} + \text{mech loss}$$

$\swarrow$
 Rotating loss
 K/n



$$I_{loss}(oc) = \text{mech Loss}$$

Blocked rotor test :-



10% to 40% of

Applied voltage is sufficient to circulate rated current on both stator and rotor at rated freq

$$P_i = P_o + \text{Loss}$$

$$P_i = \text{loss}$$


$$W_{BR} = \text{LOS}$$

- Stator cu loss (✓)
- Stator core loss $\propto V_{BR}^2 \rightarrow 0$
- RCL ($3I_2^2 R_2$)
Rated
- Rotor core loss ($B_m^2 + b_m^2 f^2$) $\propto B_m^2 V_{BR}^2 \rightarrow 0$
- Mech loss ≈ 0

$$W_{BR} = \text{Stator Cu loss} + \cdot RCL \\ = \text{motor Cu loss}$$

At Blocked Rotor $N=0$, $S=1$

$$R_L' = \left(\frac{1-S}{S} \right) R_2' = 0 \text{ (s.c.)}$$




$$I_m \propto V_m$$

|||

$$R_{e1} = R_1 + R_2'$$

$$X_{e1} = X_1 + X_2'$$



$$Z_{BR} = R_{e1} + jX_{e1}$$

$$Z_{BR} = \sqrt{R_{e1}^2 + X_{e1}^2}$$

$\downarrow$ $\downarrow$ $\downarrow$
 k/η k/η cal

$$X_{ci} = X_1 + X_2'$$

$$X_1 \approx X_2' \approx \frac{X_{ci}}{2}$$

$$Z_{BR} = \frac{V_{BR}}{I_{BR}} \quad \text{①}$$

Cov

A

$$W_{BR} \approx 3 I_{BR}^2 \cdot R_{ci}$$

$\downarrow$ $\downarrow$ $\downarrow$
 k/n k/n cap

$$R_{ci} = R_1 + R_2'$$

$$R_1 \approx R_2' \approx \frac{R_{ci}}{2}$$

3-d, 4 pole, 1440 rpm

$$E_2 = 120V$$

$$R_2 = 2\Omega$$

$$X_2 = 1\Omega$$

$$\frac{I_{sc}}{I_{FL}} = ?$$

$$I_1 = I_0 + I_a'$$

$$I_1 \propto I_a' \propto I_a$$

$$I_1 \propto \frac{SE_2}{\sqrt{R_2^2 + SX_2^2}}$$

$$I_{sc} = \frac{E_2}{\sqrt{R_2^2 + X_2^2}}$$

$$I_{sc} \propto \frac{120}{\sqrt{(2)^2 + (1)^2}}$$

$$I_{sc} \propto 11.8A \quad \text{--- (1)}$$

$$I_{FL} \propto \frac{SE_2}{\sqrt{R_2^2 + SX_2^2}}$$

$$S = 0.04$$

$$I_{FL} \propto \frac{0.04 \times 120}{\sqrt{(2)^2 + (0.04 \times 1)^2}}$$

$$I_{FL} \propto \text{R3.V.A} \quad \text{--- (2)}$$

$$\frac{I_{SC}}{I_{FL}} = \frac{170}{23} = 5$$

$$I_{SC} = (5 \text{ से } 8) \text{ times of } I_{FL}$$

Results :- During starting 3- ϕ induction motor draw 5 to 8 times of full load current it means it starts with a high starting current (inrush in current) due to such heavy inrush in current during starting there is a possibility of damage of motor and also its cause large ^{line} voltage dips. So, other appliances subjected to voltage spikes. So, their performance also affect.

$\Rightarrow$ Starter is a device which is used to limit the high starting current this current can be limited by applying reduced voltage on stator or by increasing the rotor resistance

$\Rightarrow$ 3- ϕ induction motor are self starting in nature so, due to RMF. So, starters not to used start

The motor it is only used to limit the starting current.

Types of starter:-


- ① Direct online starter (DOL) $< (5 \text{ HP})$
- ② Stator resistance / reactor starter
- ③ Star-delta starter
- ④ Auto - T/F starter
- ⑤ Rotor resistance starter.

① DOL :- In case of small capacity motors less than 5 HP the starting current is not such high and such motors can withstand with such a high starting current without any starter. So, such type of motor uses a starter which is used to connect the motor directly to the supply. So it is known as DOL starter.

⇒ This starter protect the motor from over loading.


Singe phasing :- burning of 1 phase in 3- ϕ

Overvoltage , under voltage , single phasing and from
overcurrent



$$I_{sc} \propto V_1$$

$$T_{st} \propto V_1^2$$



$$I_{sc} \propto V_1$$


$$I_{st} \propto V_{1/2}$$

Stator resistance and reactor starter:-

In order to apply reduced voltage to the stator 3- resistance or reactor are added in series with stator. So, that large voltage gets dropped and a reduced voltage is applied to the stator. So, starting current reduces by factor 2 and starting

torque reduces by factor x^2

$$(I_{sc})' = x(I_{sc})$$



$$I_{sc}' \propto xV_1$$


$$T_{st}' \propto (xV_1)^2$$

$$T_{st}' = x^2 T_{st}$$

x = reduction factor

$x < 1$, $\eta \downarrow$, $\text{speed} \downarrow$

Reactor use :-



$$\downarrow \cos \theta \propto \frac{R}{\sqrt{R^2 + X^2}} \uparrow$$


$$P_2 = \frac{V I \cos \theta}{\sqrt{2} I_2}$$

It is used upto 20 H.P

$$\eta \uparrow, P_f \downarrow$$

Auto transformer starter :-

In this starter both starting current and starting torque reduces by factor x^2 and this starter used ~~upto~~ for above 20 H.P.



$$\frac{xV_1}{V_1} = k$$

$$k = k$$

$$\frac{I_1}{I_2} = K \quad \frac{V_1}{V_2} = \frac{1}{K}$$

$x = \text{No of tapplings.}$

$$(I_{scL}) = k^2 I_{scL'}$$



$$T_{st}' \propto (kV_1)^2$$

$$T_{st} = k^2 T_{st}'$$


$\eta \uparrow$, $P_f = \text{const}$, cost ly.

Star - delta starter :-

$\Rightarrow$ In this type of starter initially stator windings are connected in star by using the three pole double throw switch (TPDTS). So, starting current reduces by factor $(1/3)$ and starting torque reduces by factor $1/3$.



$$(I_{scl})_{\Delta} = \sqrt{3} I_{sc}$$



$$(I_{scl})_Y = \frac{1}{3} (I_{scl})_{\Delta}$$

$$(T_{st})_Y = \frac{1}{3} (T_{st})_{\Delta}$$

$$\frac{I_{scL Y}}{I_{scL D}} = \frac{\frac{1}{\sqrt{3}} I_{sc}}{\frac{1}{\sqrt{3}} I_{sc}} = \frac{1}{3}$$

Line voltage $\rightarrow$ phase voltage $\rightarrow$ phase current
~~first final~~ finding sequence line current

Resistor resistance starter:

This is a fundamental way to start a slip ring induction motor.

$X_b, R_2 \uparrow$

$$(1) \quad I_{sc} \propto \frac{1}{\sqrt{R_2^2 + X_2^2}}$$

$$(2) \quad T_{st} \propto R_2 \uparrow$$

$$(3) \quad \cos \theta_2 = \frac{R_2 \uparrow}{\sqrt{R_2^2 + X_2^2}}$$

Note:

$$T_{er} = \frac{1}{s} \frac{I_{er}^2 R_2}{\omega_s}$$

$$T_{er} \propto \frac{I_{er}^2}{s} \propto \frac{I_1^2}{s} \quad \text{---} \quad \text{Mark for phase current}$$

$$I_1 \propto I_2' r \propto I_2 r$$

$$T_{st}' \propto \frac{(x I_s)^2}{1} \quad (1)$$

$$T_{FL} \propto \frac{I_{FL}^2}{S_{FL}} \quad (2)$$

$$\frac{T_{st}'}{T_{FL}} = x^2 \left(\frac{I_{SC}}{I_{FL}} \right)^2 \cdot S_{FL}$$

T_{st}' = starting torque with any starter

T_{FL} = Full load torque.

I_{SC} = starting current with DOL / w/o any starter. or
at rated voltage

I_{FL} = Full load current

S_{FL} = full load slip.

$$(T_{st}')_{PU} = x^2 (I_{SC})_{PU}^2 S_{FL}$$

$$SFL = 4\%$$

$$T_{st}' = T_{FL}$$

$$\boxed{\frac{T_{st}'}{T_{FL}} = x^2 \left(\frac{I_{sc}}{I_{FL}} \right)^2 \times SFL}$$

$$\frac{1}{1} = (1) \left(\frac{I_{sc}}{I_{FL}} \right)^2 \times \frac{4}{100}$$

$$25 I_{FL}^2 = I_{sc}^2$$

$$\boxed{I_{sc} = 5 I_{FL}}$$

Page 231



Ex:-

Value :-

$$V_{IL} = 100V$$

$$\boxed{\begin{matrix} V_{IL}' = 40V \\ I_{sc}' = 2.4 I_{FL} \end{matrix}}$$

$$SFL = .05$$

$$(T_{st}')_{DOL} = ?$$

$$\begin{aligned} (T_{st}') &= (1)^2 (1.8) \\ &= 1.8 \text{ pu} \end{aligned}$$

$$(T_{st}') = x^2 (6)^2 \times .05$$

$$\boxed{T_{st}' = 1.8 x^2}$$

$$\therefore 40V \rightarrow 2.4 I_{FL}$$

$$\therefore 1 \Rightarrow \frac{2.4}{40}$$

$$\therefore 100V \rightarrow \frac{2.4 \times 100}{40} = 6$$

$$\therefore I_{st} = 6 I_{FL}$$

$$(T_{st}')_{auto}$$

$$x = 0.5 \text{ or } 1/2$$

$$\therefore \frac{1}{4} \times 1.8 = .45 \text{ pu}$$

$$40V \longrightarrow 2.4 FL$$

$$100 \longrightarrow \frac{2.4}{40} \times 100 I_{FL}$$

$$I_{sc} \longrightarrow 6 I_{FL}$$

$$\frac{(T_{st})_1 \propto \left(\frac{1}{3}\right)}{(T_{st})_2 \propto (k)^2} = \frac{1}{4}$$

$$k^2 = \frac{1}{3}$$

$$k = \frac{1}{\sqrt{3}}$$

$$= \frac{1}{1.732} \times 100 = 57.7\% \quad \} \quad \text{Ans}$$

Speed control of induction motor :-

Speed can be controlled from rotor side as well as from stator side

$$A1, \boxed{I_{load} = \text{constant}}$$

$$T_{er} = \frac{3SE\cancel{R}^2}{\cancel{W_s} \cancel{R/2}}$$

$$\boxed{W_s = \frac{4\pi f}{\cancel{P}}}$$

U-Method

From stator side :-

① By variation in supply voltage :-

$$V_1 \begin{cases} V_1 \uparrow, \text{ Not permitted. } (X) \\ V_1 \downarrow, \text{ (Auto Transformer) } \checkmark \end{cases}$$

$$T_{cr} = \frac{3SE_v^2}{w_s \cdot R_2}$$

constant constant constant

$$SE_v^2 = \text{constant}$$

$$SV_1^2 = \text{constant}$$

$$\uparrow S \propto \frac{1}{V_1^2 \downarrow}$$

N ↓, Below ruddes

$$S_m = \frac{R}{r_2} = \text{constant}$$

$$T_{st} = \frac{3E_v^2 \cdot R_2}{w_s \cdot \lambda_a^2}$$

$$\downarrow T_{st} \propto E_v^2 \propto V_1^2 \downarrow$$

$$T_{max} = \frac{3E_v^2}{\lambda_w \lambda_2}$$

$$\downarrow T_{max} \propto E_v^2 \propto V_1^2 \downarrow$$

$$N_s = \frac{1206}{P} = \text{constant}$$


$$I_{ar} = \frac{SE_a}{R_2}$$

$$I_{ar} \propto SE_a$$

$$I_{ar} \propto SV_1$$

$$I_{ar} \propto \frac{1}{V_{1d}} \text{ at } V_1$$

$$I_{ar} \propto \frac{1}{V_{1d}}$$



Result :-

motor draws more current from the supply to maintain the torque at reduced voltage. So, due to temperature rise it cannot be used for long duration and wide range.

A - 3- ϕ 440 V , 1000 RPM = N_s , slip ring - IM

is operating with 2% slip $s = .02$ and taking

stator current of 50 A - Speed of motor is reduce

to 500 rpm by variation in supply voltage calculate

to motor stator current .

$$s = \frac{1000 - 500}{1000} = 0.5$$

$$\boxed{s = 0.5}$$

$$s \propto \frac{1}{V_1^2}$$

$$\frac{s_1}{s_2} = \frac{V_2^2}{V_1^2}$$

$$V_2^2 = \frac{s_1 V_1^2}{s_2}$$

$$= (440)^2 \times \frac{0.02}{0.5}$$

$$V_2 = \frac{440}{5}$$

$$V_2 = 88 \text{ V}$$

$$I_{st} \propto \frac{1}{V_1} \quad I$$

$$I_1 \propto I_{IL} \propto I_{ar} \propto I_{ar}^1$$

$$I_{IL} \propto \frac{1}{V_{IL}}$$

$$\frac{I_{IL}}{I_{rL}} = \frac{V_{2L}}{V_{1L}}$$

$$I_{rL} = \frac{V_{1L} \times I_{IL}}{V_{2L}}$$

$$= \frac{440 \times 800}{88}$$

$$I_{rL} = 250 A$$

② By variation in supply frequency. (V/f) control method :-

$$f \uparrow, \phi \propto \frac{V}{f} \text{ --- Constant}$$

$f \uparrow$

$$f \downarrow, \phi \propto \frac{V \downarrow}{f \downarrow}, \frac{V}{f} = \text{constant}$$

Constant

but at low f and V saturation of motor /

$$T_{er} = \frac{3SE_a^2}{W_s R_2}$$

Constant

const

$$I_{ar} = \frac{SE_2}{R_2}$$

$$I_{ar} \propto SV_1 = \text{constant}$$


$$\propto \text{Slip speed} = N_s - N$$

$$= sN_s$$

$$\propto s \cdot f$$

$$\propto \frac{1}{f}$$

$$sN_s = \text{constant}$$



Result :-


① Speed obtained are below rated, for variation in voltage and frequency it requires power electronic converter which increases its cost.

③ 8 Pole changing speed control :-

This method only used for SCIL.

④ Consequent pole changing :-

In this method connection of stator windings changed with the help of ~~st~~ simple switching. So that number of stator poles are changed in the ratio 2:1



⑤ By using multiple stator winding :-

Stator contains two or more windings which is designed for different / different no. of poles and at a time only only one winding is connected.

Disadvantages :-

① Speed change in steps and smooth speed control is not possible, due to multiple stator windings size and cost $\uparrow$ increases.

④ By ~~conn~~ connecting a resistance in stator circuit.
Same as method 1

From rotor side :-

① By adding external resistance in to rotor circuit :-

Only used for slipring induction motor.

$H_b, R_2 \uparrow$

$$T_{er} = \frac{3SE_2^2}{\omega_s R_2}$$

constant $\swarrow$ constant

$\frac{S}{R_2} = \text{constant}$

$$\uparrow S \propto R_2 \uparrow$$

$N \downarrow$ Below rated

$$(1) \quad T_{st} = \frac{3E_2^2 R_2}{\omega_s X_2^2}$$

$$(2) \quad s_m = \frac{R_2}{X_2}$$


$$(3) \quad T_{max} = \frac{3E_2^2}{2\omega_s X_2} = \text{constant}$$

$$(4) \quad N_s = \frac{120f}{P} = \text{constant}$$

$$I_{er} = \frac{SE_2}{R_2}$$

$$I_{er} \propto \frac{S}{R_2}$$

$$\approx \text{constant}$$



Since current in the rotor remains but rotor resistance increases. So, power loss also increases. So it is less efficient method.

② Slip power recovery method or by injecting emf in


the rotor circuit at slip frequency:-

In this method a voltage is injected in the rotor circuit at slip frequency. It is only used for slipping in I-M.




⇒ In this method emf is injected in the rotor circuit at subtractive polarity. So, that effective rotor resistance increases. So, speed decreases.

~~###~~ Same frequency of injected emf is essential condition



$$I' = \frac{8}{5}$$

$$I' = 1.6 \text{ A } \uparrow$$




$$I' = \frac{2}{5} = .4 \text{ A } \downarrow$$

Subtractive polarity

$(R_2)_{\text{eff}} \uparrow$,

$s \uparrow$, $N \downarrow$
Below Rated.

Casked control:



$$N_{s1} = \frac{120 f_1}{P_1}$$

$$N_1 = (1 - s_1) N_{s1}$$

$$N_1 = (1 - s_1) \frac{120 f_1}{P_1} \quad \text{--- (1)}$$

$$N_{s2} = \frac{120 f_2}{P_2}$$

$$f_2 = s_1 f_1$$

$$N_{s2} = \frac{120 f_1 s_1}{P_2}$$

$$N_2 = (1 - s_2) N_{s2}$$

$$N_2 = (1 - s_2) \frac{120 f_1 s_1}{P_2} \quad \text{--- (2)}$$

$$(1) = (2)$$

$$(1-s) \frac{120f_1}{P_1} = (1-s_2) \frac{120f_1 s_1}{P_2}$$

$$\frac{1}{P_1} - \frac{s_1}{P_1} = \left(\frac{1}{P_2} - \frac{s_2}{P_2} \right) s_1$$

$$\frac{1}{P_1} - \frac{s_1}{P_1} = \frac{s_1}{P_2} - \frac{s_1 s_2}{P_2}$$

$$s_1 s_2 \longrightarrow 0$$

$$\frac{1}{P_1} - \frac{s_1}{P_1} = \frac{s_1}{P_2}$$

$$\frac{1}{P_1} = s_1 \left(\frac{1}{P_1} + \frac{1}{P_2} \right)$$

$$\boxed{s_1 = \frac{P_2}{P_1 + P_2}}$$

$$N_1 = N_2 = \left(1 - \frac{P_2}{P_1 + P_2} \right) \frac{120f_1}{P_1}$$

$$N_1 = N_2 = \left(\frac{P_1}{P_1 + P_2} \right) \frac{120f_1}{P_1}$$

$$\boxed{N_1 = N_2 = \frac{120f_1}{P_1 + P_2}}$$

cumulative.

for $P_1 \neq P_2$

$$N_1' = N_2' = \frac{120f_1}{P_1 - P_2}$$

differentially cascading,
(Two ϕ terminal interchanged)

For Result :-

- ① For ~~so~~ cascading 1 motor must be S.R.I.M.
- ② And from this method a speed can be obtained by two motors.

Braking :-


① Plugging :-

The direction of R.M.F can be reversed by interchanging any two supply terminals. So that a high braking current will flow which produces a negative torque and motor speed decreases quickly and before it reaches zero speed it is disconnected from the supply. Otherwise it will start rotation in opposite direction. In plugging highest braking torque is produced but it is highly inefficient method.

→ Plugging should not be frequently done because all the stored kinetic energy dissipates into


heat. so, rotor conductor may melt.

At starting




$I_{sc} \propto 1000 \text{ RPM}$
starter

Running



$I_{FL} \propto 50 \text{ Rated}$




$I_b \propto 1950 \text{ R.P.M.}$

② Regenerative braking :- / D.C dynamic braking

In this braking motor is disconnected from the supply and a d.c supply is given which produces a stationary flux. so, so rotor speed decreases.

⇒ To limit this high braking current a braking resistance is connected in series with rotor



$$I_B \propto (0 - 950)$$

$$I_B \propto (-950)$$

↓
generator

Regenerative braking :-


① Regenerative braking is highly efficient.


② If the motor speed becomes more than synchronous speed it converts mechanical energy into electrical energy which is given back to supply and it is called goes into generating mode and without any opposition no energy conversion. So, a negative torque is experienced by the motor, motor and motor speed control automatically.

⇒ Motor does not stop in this breaking but
control its speed under overhalling loading
condition . for

⇒ Induction generator always operate at ^{lagging} ~~leading~~ pf and
it always takes reactive power and gives
active power .

⇒ Induction generator always used in wind power
plant .






Equivalent ckt of Induction generator

Cogging :- It specially comes when in three phase squirrel caged I-M started with reduced voltage and if ~~an~~ number of rotor slots and number of stator slots were exactly same and having a common factor then alignment torque dominate the starting torque. So, rotor refuse to start this is called as cogging.



⇒ Cogging effect can be eliminated by making the number of stator and rotor slots different numbers and does not have any


common factor, by skewing the rotor slots.



$$S_s \neq$$

$$|S_{stator} - S_{rotor}| = \text{odd} = 1, 3$$






Crawling effect :-

Time harmonics:- The harmonics present in the supply given to an induction motor is known as time harmonics. These harmonics does not have any major effect on the torque slip characteristics. So, these harmonics does not create crawling effect.

$$\vec{I}_1 = \underbrace{I_{01}}_b \sin \omega t + \underbrace{I_{02}}_{2b} \sin(2\omega t) + \underbrace{I_{03}}_{3b} \sin(3\omega t) + \dots$$



Speed of ϕ Rm f to fundamental

$$N_s = \frac{120f}{P}$$

Speed of RMS to 3rd time harmonics.

$$\therefore \{ \text{at } f = 3b \} \quad N_{s3} = \frac{120(3b)}{P} = \frac{360b}{P} = 3N_s$$

$$\downarrow T_{st} \propto \frac{1}{f^3} \uparrow$$

by 27 times

$$\downarrow S_m \propto \frac{1}{f} \uparrow$$


2 times

$$\downarrow T_{max} \propto \frac{1}{f^2} \uparrow$$

by 9 times

$$\uparrow N_s \propto f \uparrow$$

3 times



So, time harmonics does not have any effect cause twisting.

Space harmonics :- Harmonics present in the flux is known as space harmonics. These harmonics are present due to machine slotting, non uniform airgap,


speed of RMF due to fundamental

$$N_s = \frac{120f}{P}$$


speed of RMF at 3rd space harmonics.

$$N_{s3} = \frac{120f}{3P} = \frac{N_s}{3}$$


$$\therefore \left\{ \begin{array}{l} \text{at frequency} = \frac{f}{3} \text{ or } \text{poles} = 3P \end{array} \right\}$$



$$N_s = \frac{120f}{3P}$$



Space 3rd harmonics means 3 poles per cycle $3N$ & $3P$




Crawling definition:-

When squirrel caged induction motor started on load does not accelerate upto full speed and runs near to $N_s/7$ speed the motor is called to be in crawling. Due to crawling there is large current drawn by the motor and it runs with vibration and noise.

⇒ Space harmonics can be eliminated by making uniform of air gap which can be obtained by skewing the rotor slots.

Analysis of space harmonics:-

Even harmonics
{2, 4, 6, 8, ...}



Avg effect of even harmonics in a cycle becoming zero. So, these harmonics also not produce crawling.

Odd Harmonics
{3, 5, 7, 9, 11, 13, ...}

$3N$
($N = \text{odd}$)

{3, 9, 15, ...}

Triplen
Harmonics

$3N - 1$
($N = \text{even}$)

{5, 11, ...}

$3N + 1$
($N = \text{even}$)


{7, 13, ...}

Let

$$\phi_R = \phi_m \sin(\omega t)$$

$$\phi_Y = \phi_m \sin(\omega t - 120^\circ)$$

$$\phi_B = \phi_m \sin(\omega t - 240^\circ)$$



(12) 3rd space harmonics :-

$$\phi_{R3} = \phi_{m3} \sin 3(\omega t)$$

$$\phi_{Y3} = \phi_{m3} \sin 3(\omega t - 120^\circ)$$


$$\phi_{B3} = \phi_{m3} \sin 3(\omega t - 240^\circ)$$

$$\phi_{Y3} = \phi_{m3} \sin 3\omega t$$

$$\phi_{B3} = \phi_{m3} \sin 3(\omega t - 240^\circ)$$

$$\phi_{B3} = \phi_{m3} \sin(3\omega t - 720^\circ)$$

$$\phi_{B3} = \phi_{m3} \sin 3\omega t$$



3rd harmonics have zero effect

These harmonics don't have any 3- ϕ nature. So, don't create RMF. So, these are also not responsible for crawling.

② 5th space harmonics :-


$$\phi_{R5} = \phi_{m5} \sin(5\omega t)$$

$$\phi_{Y5} = \phi_{m5} \sin(5(\omega t - 120^\circ))$$

$$\phi_{B5} = \phi_{m5} \sin(5\omega t - 240^\circ)$$

$$\phi_{R5} = \phi_{m5} \sin(5\omega t - 240^\circ)$$

$$\phi_{B5} = \phi_{m5} \sin(5\omega t - 120^\circ)$$



Result: ① Slip due to 5th space harmonics.

$$s_5 = \frac{N_5 - \left(-\frac{N_s}{5}\right)}{N_s}$$

$$s_5 = \frac{6}{5} = 1.2$$

— i/v sequence

$$s_5 > 1 \quad \text{— Braking torque}$$

So, motor speed decreases and crawling is due to 5th space harmonics only.


③ 7th space harmonics :-

$$\phi_{R7} = \phi_{m7} \sin(7\omega t)$$

$$\phi_{Y7} = \phi_{m7} \sin(7\omega t - 120^\circ)$$

$$\phi_{B7} = \phi_{m7} \sin(7\omega t - 240^\circ)$$

$$\phi_{B7} = \phi_{m7} \sin(7\omega t - 240^\circ)$$



— i/v sequence

$$S_f = \frac{N_s - \frac{N_s}{7}}{N_s}$$

$$= \frac{6}{7} = .82$$

Methods to eliminate crawling :-


- ① By skewing the rotor slots, by starting the motor at no load.

Special rotor construction :-

Squirrel caged induction motor having small rotor resistance. so, at starting its performance is poor. so, to improve its starting performance special rotor constructions are used. there are two types of special rotor construction.


The working of special rotor construction depends on skin effect.

AC = current
 $f = 50\text{Hz}$




A_r, R_r

DC current.
 $f = 0$




A_r, R_b


① Deep Bar rotor construction :-



② Understarting $\phi_e = f_1 = 50\text{Hz}$



Under Running condⁿ :-





$$f_{ar} = sf_1 = 2.5\text{Hz} \approx \text{DC}$$

$$R_2 \propto \frac{1}{I_s}, T_s \propto \frac{1}{R_2\downarrow}$$

$$X_2 \uparrow$$

$$T_{max} \propto \frac{1}{X_2\uparrow}$$


Concep to solve above prob of X_1 :-



air gap is made up in path of leakage flux - so, it will flow from low S path.


② Double cage rotor construction :-

- Its rotor consist of 2 cage outer cage and inner cage which are short circuited by two end rings
- Both the cages are separated by narrow airgap




a) Starting

$$y_e = b_{AC} \approx 50H_3$$



b) Running :-



$$y_e r = 5b$$



$$= 2.5H_3$$

$$= DC$$

best
Force is
more than
previous case

1- ϕ Induction motor:-

Since average torque ^{experienced} by single ϕ induction motor in a complete cycle becomes zero. So, 1- ϕ I-M are not self starting in nature. This behaviour of non self starting of 1- ϕ I-M is explained by double field revolving theory.



Double field revolving theory:-


According to this theory alternating flux contains two components, forward R.M.F and backward R.M.F, which have same magnitude and rotating at synchronous speed N_s in opposite direction to each other.

$$\boxed{\text{Pulsating flux} = \text{Forward R.M.F} + \text{Backward R.M.F}}$$

$$S_f = \text{forward slip}$$

$$S_b = \text{Backward slip}$$

Torque slip characteristics of 1- ϕ induction motor



$$S_f = \frac{N_s - N}{N_s} \quad \text{--- (i)}$$

$$S_b = \frac{N_s - (-N)}{N_s}$$

$$S_b = \frac{N_s + N}{N_s} \quad \text{--- (2)}$$

$$S_b + S_f = 2$$

$$T_{cr} = \frac{1}{SWS} (RCL)$$

$$RCL = 1 \cdot T_{cr}^2 R_2 \quad \text{act starting.}$$

$$T_b = \frac{R \cdot CL}{S_f \cdot WS} \quad \text{--- (3)}$$

$$T_b = \ominus \frac{1}{S_b WS} (RCL) \quad \text{--- (4)}$$

$\ominus$ represents opposition

$$T_{net} = T_f + T_b$$

from Q 2 (a)

$$T_{net \text{ at starting}} = T_f + T_b = 0$$

$\therefore 1-\phi$ EM is not self starting.


Under running $\therefore N \rightarrow N_s$

$$s_f \rightarrow 0, \quad s_b \rightarrow 2$$

$$T_b \rightarrow \infty$$

$$T_b = -\frac{1}{2ws} \quad (\text{RCL})$$


Since, backward torque is also present in running condition also, so, its performance is not smooth.



Result :-


- ① Torque developed by 1- ϕ induction motor drops to zero slightly before synchronous speed and becomes ~~zero~~ negative at synchronous speed. It means it acts as induction generator slightly before synchronous speed. (negative torque is also present)

Single- ϕ I-M becomes self starting by split phase concept.



$$\boxed{\bar{I}_1 = \bar{I}_R + \bar{I}_L} \quad \text{or} \quad \bar{I}_R + \bar{I}_C$$

split phase I-M





Types of 1- ϕ I-M :-

(i) split phase type

(ii) shaded pole induction motor


(1) Split phase type Motor :-

(a) Resistance phase split I-M :- or crresistance start
induction run or split phase motor




$$T_{st} = (1.50) T_{FL}$$

$$I_{st} \propto I_R / I_L \sin \delta$$



Under running :-


Switch gets open $\therefore I_2 = 0$



$$\cos \phi_f = \cos (70^\circ)$$

$$\phi_f = 0.2 \text{ lag}$$

$$\boxed{\text{poor } \phi_f}$$




⇒ These are used for low inertia load upto 250 watt
 cannot be preferred for high inertia load,
hard to start load, frequently starting and
 stoping load.


⇒ The auxillary winding having a centrifugal switch in
 series with it and operate when motor obtains
 40-80% of synchronous speed.

⇒ If centrifugal switch ~~does~~ does not open mechanically
 after starting the motor motor will draw lag
large current and stator gets over heated.

(b) Capacitor start induction run motor :-



Starting:-



$$\therefore T_{st} = I_R I_L \sin \delta$$


$$T_{st} = (3 \text{ to } 4) T_{FL}$$


Under Running:-

$$P_f = \cos 70^\circ$$

$$P_f = \cos \phi \text{ Lagg}$$

poor pf






⇒ As if the supply terminals are interchanged then the direction of motor rotation remains the same. For reversing the direction of rotation main winding terminals are interchanged or auxiliary winding terminals are interchanged.


⇒ These motors can be used for high inertia load upto 500 watt but cannot be preferred for hard to start load, frequently starting & stopping load.

Capacitor start - capacitor & run motor / capacitor

run motor :-




Starting



$T_{st} \propto |I_a| \sin \delta$


$$T_{st} = (5) T_{FL}$$

Running:-



$$P_f = 0.7 \text{ Logging}$$

2. P. f. get improved





Result :-

- ① Such a motor runs as 2- ϕ induction motor from 1- ϕ supply. So, produces a constant torque not a pulsating torque.
- ② These motors have highest cost, highest starting torque, highest operating ϕ power factor. so, can be used for high inertia load, hard to start loads frequently starting & stopping load.
- ③ Used in air ceiling fan.

a) Permanent split capacitor motor / Capacitor run motor

It is the only motor which does not have ~~any~~ any centrifugal switch and have smooth torque slip characteristics.




Shaded pole induction motor :-

→ Stator having shaded pole generally 2 or 4. Since, these are ~~comp~~ compact in size so, used in fans and table fan.

It is the fractional kilowatt motor which have minimum cost, lowest efficiency (80-85)%, having highest slip, lowest starting torque.

⇒ The starting current or blocked rotor current is of shaded pole motor is slightly more than full load current.




OA $\phi \uparrow, \frac{d\phi}{dt} = \text{+ive}, e = \text{-ive}$


AB $\phi \approx \text{const}, \frac{d\phi}{dt} \approx 0, e = 0$

BC + $\phi \downarrow$, $\frac{d\phi}{dt} = -ve$, $e = +ve$


(1)




(2)



(3)



(unshaded)




Notes :-

① $\text{Size (machine)} \propto \frac{\text{Power o/p}}{\text{speed} \propto f \propto \text{Voltage}}$


② For same power rating :-

	3- ϕ I-M	1- ϕ I-M
Size	↓	↑
pf	.8 lag	.7 lag
	Self starting	Not self starting

③ Stator fed I-M | Rotor fed I-M



N_s = speed of stator R.M.F w.r.to stator
 $S N_s$ = speed of rotor



Not w.r.to stator